(August 2007)

UNITED STATES

1. Type of Well

· Whoe

DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUBMIT IN TRIPLICATE - Other instructions on page 2.

FORM APPROVE			
OMB No.	1004-0137		

Exp	oires: .	July	31,	201
			,	

7. If Unit of CA/Agreement, Name and/or No.

Farming Con Field SUNDRY NOTICES AND REPORTS ON WELLS
Farmingion Field SUNDRY NOTICES AND REPORTS ON WELLS Burgay of Land Manager this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals

5. Lease Serial No. NW-04224 6. If Indian, Allottee or Tribe Name

Oil Well	X Gas Well Ot	ner	Well Name and No.		
	_			Quitzau 8R	
2. Name of Operator			9. API Well No.		
Burling	ton Resources Oil & G	as Company LP		-045-29603	
3a. Address		3b. Phone No. (include area code)	Field and Pool or Explora	atory Area	
PO Box 4289, Farmington, NM 87499 (505) 326		(505) 326-9700	1	Ballard PC	
4. Location of Well (Footage, Sec., T., K.	R.,M., or Survey Description)		11. Country or Parish, State		
Surface Unit G (S	WNE), 2100' FNL & 225	55' FEL, Sec. 11, T25N, R8W	San Juan	, New Mexico	
12. CHECK	THE APPROPRIATE BOX	ES) TO INDICATE NATURE OF	NOTICE, REPORT OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
X Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
(31	Change Plans	X Plug and Abandon	Temporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
13. Describe Proposed or Completed Or	peration: Clearly state all pertinen	t details, including estimated starting date	of any proposed work and approx	imate duration thereof.	

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

9/20/13 Plug #1 had dropped from 315' to 715', BLM onsite Bill Diers approved to pump an additional 13 sacks to top off plug and move uphole to perf & set surface plug. Brandon Powell w/ OCD was called and he gave verbal concurrence.

9/20/13 Second call: Pumped additional 13 sacks as approved earlier and perfed @ 380'. Pressure is building up. Bill Diers on site w/ BLM approved to move up to 300' and re-perf. Brandon Powell w/ OCD was contacted and gave verbal concurrence.

> RCVD OCT 25'13 OIL CONS. DIV. DIST. 3

The Subject well was P&A'd on 9/23/13 per the attached report.

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)			
Kenny Davis	Title	Staff Regulatory Technicis	an .
Signature	 Date_		10/23/2013
THIS SPACE FOR FEL	ERAL OF	R STATE OFFICE USE	ASSEPTED FOR RECOR
Approved by		Title	OC 2 4 2013
Conditions of approval, if any, are attached. Approval of this notice does not warrant of that the applicant holds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon.	-	Office	PARAMAGTON FIELD OFFICE.

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources

Quitzau 8R

September 23, 2013 Page 1 of 1

2100' FNL and 2255' FEL, Section 11, T-25-N, R-8-W San Juan County, NM Lease Number: NM-04224 API #30-045-29603

Cement Services Report
Notified NMOCD and BLM on 9/13/13

Plug and Abandonment Summary:

Plug #1 with 105 sxs (120.7 cf) Class G cement inside casing from 2726' to 252' to cover the Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops.

Plug #1a with 12 sxs (13.8 cf) Class G cement inside casing from 716' to 434'.

Plug #2 with 67 sxs (76.7 cf) Class G cement to cover the surface casing shoe.

Plug #3 with 16 sxs top off casing and install P&A marker.

Plugging Work Details:

- 9/18/13 Rode rig and equipment to location. RU cement equipment. Basic Coil tubing unit pulled 1.5" coil tubing from well. Basin Wireline round trip 3.5" GR to 2776'. Set 3.5" CIBP at 2726' above top perforations. SI well. SDFD.
- 9/19/13 Basic Coil tubing unit spool into hole with 1.5" tubing to top CIBP at 2726'. Circulate well clean with 25 bbls of water. Attempt to pressure test casing, leak. Spot plug #1 with estimated TOC at 252'. Spool 1.5" coil tubing to 395' circulate 3.5" casing clean with 10 bbls. POH with remaining tubing. WOC overnight. SI well. SDFD.
- Basin Wireline tag TOC at 717'. Wait on orders. Spool in hole with Basic coil tubing to 716'. Establish circulation. Pressure test casing to 1000 PSI, OK. Spot plug #1a with estimated TOC at 434'. Spool out hole to circulate 3.5" casing clean with 4.6 bbls. Spool out remaining 1.5" coil tubing. Basin Wireline perforated 3 HSC squeeze holes at 380'. Pressure test casing to 1000 PSI, bled down to 800 PSI, OK. Load 7" bradenhead with ½ bbls and holds at 800 PSI, cacl shows 20' down. Wait on orders. Basin Wireline perforated 4 HSC holes at 183'. Establish rate of 2 bpm at 600 PSI. Attempt and unable to pump down bradenhead pressured up to 1000 PSI. Wait on orders. Spot plug #2 with estimated TOC at surface. SI well. SDFD.
- 9/23/13 RU High Desert. Fill out Hot Work Permit. Cut off wellhead. Top off casing. Spot plug #3 and install P&A marker. RD cement equipment and MOL.

Johnny Cole, COPC representative, was on location. Bill Dier, BLM representative, was on location.