1							
Form 3160-5 UNITED STATES					FORM APPROVED		
(August 2007). DEPARTMENT OF THE INTERIOR					OMB No. 1004-0137		
BUREAU OF LAND MANAGEMENT NOV 06 2013					Expires: July 31, 2010 5. Lease Serial No.		
					SF-080594		
FCT Do not use this form for proposals to drill or to re-enter an					6. If Indian, Allottee or Tribe 1	lame	
Burezabandoned	well. Use Form 3160-3 (A	PD) for	such proposa	ns.			
SUBMIT IN TRIPLICATE - Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well					Canyon Largo Unit 8. Well Name and No.		
Oil Well X Gas Well Other					Canyon Largo Unit 85		
2. Name of Operator Burlington Resources Oil & Gas Company LP					9. API Well No.	39-05472	
3a. Address	No. (include area co						
PO Box 4289, Farmington, NM 87499			(505) 326-9700)	Ballard PC		
4. Location of Well <i>(Footage, Sec., T.,</i> Surface UNIT I (N	EL, Sec	. 13, T24N, R6	W	11. Country or Parish, State Rio Arriba , New Mexico			
12. CHECK T	HE APPROPRIATE BOX(ES)		CATE NATURE	OF NO	TICE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION TYPE OF ACTION							
Notice of Intent	Notice of Intent Acidize				Production (Start/Resume) Water Shut-Off		
	Alter Casing		ure Treat		Reclamation	Well Integrity	
X Subsequent Report	Casing Repair Change Plans		Construction and Abandon		Recomplete Femporarily Abandon	Other	
Final Abandonment Notice	Convert to Injection	Plug			Water Disposal	<u></u>	
following completion of the invol- Testing has been completed. Fina determined that the site is ready for	work will be performed or provide the ved operations. If the operation results of Abandonment Notices must be filed or final inspection.)	s in a multi only after a	ple completion or re all requirements, inc	completi	on in a new interval, a Form 316 clamation, have been completed	50-4 must be filed once	
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)					····		
Denise Journey	Title Regulatory Technician						
Signature Anus	11/6/2013						
<u></u>	THIS SPACE FO	R FEDE	RAL OR STAT	TE OF	FICE USE		
Approved by		<u> </u>					
				itle		Date	
Conditions of approval, if any, are atta that the applicant holds legal or equital entitle the applicant to conduct operati	ble title to those rights in the subject le		r certify	ffice			
Title 18 U.S.C. Section 1001 and Title false, fictitious or fraudulent statement				nd willfu		r agency of the United States any	
(Instruction on page 2)					NOV	07 2013	
					MANANA	IN FIELD OFFICE	
					9349	noi rella officia	
NMOCDIV						and a second	
			· .			D All	

1

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources Canyon Largo Unit 85

October 9, 2013 Page 1 of 1

1650' FSL and 990' FEL, Section 13, T-24-N, R-6-W Rio Arriba County, NM Lease Number: SF-080594 API #30-039-05472

Plug and Abandonment Report Notified NMOCD and BLM on 10/4/13

Plug and Abandonment Summary:

Plug #1 with 76 sxs (89.68 cf) Class B cement inside casing from 2064' to 1393' to cover the Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops.

- Plug #2 with 96 sxs (113.28 cf) Class B cement inside casing from 164' to surface to cover surface casing shoe.
- Plug #3 with 25 sxs Class B cement top off casing and install P&A marker.

Plugging Work Details:

- 10/4/13 Rode rig equipment to location. Spot in and RU. SDFD.
- 10/7/13 Check well pressures: tubing and casing 140 PSI, bradenhead 0 PSI. Blow down casing thru 1" x 2" swedge original casing valves frozen. Pump 20 bbls of water down tubing to kill well. Change out casing valves. Attempt to remove screw-on 8-5/8" cap, broke free. Unable to ... separate cap from hanger. Wait on WSI to bring new cap. NU companion flange. NU BOP. PU on tubing, LD hanger and 104 jnts 1-1/4 line pipe. X-over to 2-3/8" tools. PU 5.5" watermelon mill. PU and tally 66 jnts 2-3/8" tubing to 2064', SB 33 stands, LD mill. SI well. SDFD.
- 10/8/13 Bump test H2S equipment. Open up well; no pressures. PU 5.5" Select Tools CR and set at 2064'. Circulate casing clean with 40 bbls of water. Pressure test casing to 800 PSI, OK. Ran CBL from 2064' to surface. TIH open-ended. Spot plug #1 with estimated TOC at 1393'. LD all tubing. Perforate 3 HSC holes at 164'. Establish circulation. Circulate well clean. PU 5.5" Select Tool CR and set at 136'. Establish same rate. Spot plug #2 with estimated TOC at surface. Circulate well clean. WOC. SI well. SDFD.
- 10/9/13 Open up well; no pressures. ND BOP. Dig out wellhead. RU High Desert. Perform Hot Work Permit. Cut off wellhead. Top off casing. Spot plug #3 and install P&A marker. RD and MOL.

Jason Vasquez, MVCI representative, was on location. Bill Diers, BLM representative, was on location.