	•					
• •						
Fire () Pro						
Form 3160-5				FORM APPROVED		
(August 2007) DEPARTMENT OF THE INTERIOR NOV 06 2013 ^{BUREAU} OF LAND MANAGEMENT Familie Sundre Notices and Reports on Wells				OMB No. 1004-0137 Expires: July 31, 2010		
				5. Lease Serial No.		
				NM-03561		
	e this form for proposals		er an	6. If Indian, Allottee or Tribe	Name	
	well. Use Form 3160-3 (4					
SUBMIT IN TRIPLICATE - Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well Oil Well Image: Constraint of Operator 2. Name of Operator Image: Constraint of Operator						
				8. Well Name and No. Grenier B 2		
				9. API Well No.		
Burlington Resources Oil & Gas Compa						
3a. Address 3b. PO Box 4289, Farmington, NM 87499 3b.		1 .	Phone No. (include area code) 10. I (505) 326-9700		10. Field and Pool or Exploratory Area Aztec PC	
4. Location of Well (<i>Footage, Sec., T.R.M., or Survey Description</i>)				11. Country or Parish, State		
	WSE), 1650' FSL & 1650' F	EL, Sec. 6, T29N,	R10W	San Juan	, New Mexico	
			·	<u>]</u>		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF AC					
Notice of Intent	Acidize	Deepen		Production (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat		Reclamation	Well Integrity	
X Subsequent Report	Casing Repair	New Construction X Plug and Abandon		Recomplete Femporarily Abandon	Other	*
Final Abandonment Notice	Convert to Injection	Plug Back		Water Disposal		
13. Describe Proposed or Completed C	Deration: Clearly state all pertinent de	tails, including estimated s	tarting date of	f any proposed work and appro:	ximate duration thereof.	•
	ionally or recomplete horizontally, giv					
Attach the bond under which the	work will be performed or provide the	Bond No. on file with BLN	M/BIA. Requi	ired subsequent reports must be	e filed within 30 days	
following completion of the invol	ved operations. If the operation result	s in a multiple completion	or recompleti	on in a new interval, a Form 31	60-4 must be filed once	
Testing has been completed. Fina	al Abandonment Notices must be filed	only after all requirements	, including rea	clamation, have been complete	d and the operator has	
determined that the site is ready f	or final inspection.)					
	I that one day ago intermed					
2# on Intermediate and	d 10# on BH. CBL was run `	Yesterday. Request	ed permis	sion to perf the Kirtland	d / Ojo plug below Kitland (@ 1100'.
This was to see if they	can get cement behind the	e 5 1/2" casing. If no	ot, the plan	is to perf below the O	jo @ 982' and try. If this as	lo failed,
	plug & come up to perf for					
	with BLM approved. Called					0
The subject well was	28 A'd on $10/7/12$ nor the sh	ove notification and	the attack	and report	DAIRMONALA	
The subject well was P&A'd on 10/7/13 per the above notification and the a				ieu report.	RCVD NOV 8'13 DIL CONS. DIV.	
					DIST. 3 🐜 👘	
					<i>,</i>	
						-
14. I hereby certify that the foregoing	is true and correct. Name (Printed/Ty	ped)				
Kenny Davis			Title Staff Regulatory Technician			
Freh			11/6/2013			
Signature		Date			AGGET MET OFFICE	<u>D</u> AD
	THIS SPACE FO	OR FEDERAL OR S	TATE OF			
Approved by					NUV 0 7 2013	-
			Títle	R	YANNATAN CIZI A AM	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or				······································	WANNESS CAN FREIDUPF	W.r.
that the applicant holds legal or equita		ease which would	Office	-		Mar va
entitle the applicant to conduct operat Title 18 U.S.C. Section 1001 and Title		me for any person knowing		lly to make to any department of	or agency of the United States any	$\overline{\gamma}$
false, fictitious or fraudulent statemen			siy and white		si agency of the Onneu States any	_\
(Instruction on page 2)		REAL OF	A			jb/
		6 18 8 6 W W				QI ~ /
						~ .

7

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources Grenier B 2

1650' FSL and 1650' FEL, Section 6, T-29-N, R-10-W San Juan County, NM Lease Number: NM-03561 API #30-045-08696

October 7, 2013

Page 1 of 1

Plug and Abandonment Report Notified NMOCD and BLM on 9/30/13

Plug and Abandonment Summary:

Plug #1 with 16 sxs (18.88 cf) Class B cement inside casing from 2151' to 1571' to cover the Pictured Cliffs and Fruitland tops.

Plug #2 with 93 sxs (109.74 cf) Class B cement 92 sxs in annulus, 1 sxs below CR and 0 sxs above to cover the Kirtland and Ojo Alamo tops.

Plug #2a with 8 sxs (9.44 cf) Class B cement inside casing from 1057' to 767' to cover the Kirtland top.

Plug #2b with 8 sxs (9.44 cf) Class B cement inside casing from 993' to 703' to cover the Ojo Alamo top.

Plug #3 with 123 sxs (145.14 cf) Class B cement from 159' to surface, 5 sxs in 2-7/8" casing, 12 sxs in 5.5" casing intermediate, 106 sxs in annulus to cover surface casing shoe.

Plug #4 with 36 sxs Class B cement top off casing and install P&A marker.

Plugging Work Details:

- 10/1/13 Rode rig equipment to location. Spot in and RU. SDFD.
- 10/2/13 Bump test H2S equipment. Check well pressures: casing and intermediate casing 150 PSI, bradenhead 40 PSI. RU valves and relief lines. Blow well down. RIH with 2-7/8" GR to 2170'. RIH with 2-7/8" CIBP and set at 2151'. ND wellhead. RU A-Plus companion flange. NU BOP and function test. TIH with A-Plus 1-1/4" workstring and set CIBP at 2151'. Establish circulation. Pressure test casing to 800 PSI, OK. RU Bluejet Wireline. Ran CBL from 2151' to surface, estimated TOC at 340'. Note: During pressure test closed bradenhead for 20 mins; pressured up to 5 PSI. While blowing down had 5 PPM H2S. Wait on orders. Establish circulation. Spot plug #1 with estimated TOC at 1571'. SI well. SDFD.
- 10/3/13 Bump test H2S equipment. Check well pressures: tubing and casing 0 PSI, bradenhead 10 PSI. Take gas samples from 5.5" casing and bradenhead. RU relief lines, blow well down. Bradenhead 10 PPM of H2S. Wait on orders. Note: BLM and NMOCD approved to perforate at 1100'. Perforate 6 bi-wire holes at 1097'. Establish rate of 22.5 bpm at 700 PSI. RIH and set 2-7/8" CR at 1057'. Spot plug #2. WOC requested by COPC. Monitor pressure on bradenhead. SI well. SDFD.
- 10/4/13 Bump test H2S equipment. Check well pressures: no tubing, casing on vacuum and bradenhead 0 PSI. Monitor for H2S at 12 PPM. Blow well down. Spot plug #2a with estimated TOC at 767'. Reverse circulate. Perforate 6 bi-wire holes at 982'. Attempt to establish rate to 800 PSI, OK. Establish circulation. Spot plug #2b with estimated TOC at 703'. Perforate 6 bi-wire holes at 159'. Establish circulation. Spot plug #3 with estimated TOC at surface. SI well. SDFD.
- 10/7/13 Bump test H2S equipment. Open up well; no pressures. THI and tag TOC at 29'. ND BOP. Dig out wellhead. RU High Desert. Cut off wellhead. Found cement down 20' in casing and 33' in annulus. Spot plug #4 and install P&A marker. RD and MOL.

Jim Morris, MVCI representative, was on location. Leo Pacheco, BLM representative, was on location.