

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

Burlington Resources Oil & Gas Company LP

3a. Address

PO Box 4289, Farmington, NM 87499

3b. Phone No. (include area code)

(505) 326-9700

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface

Unit 1 (NESE), 1920' FSL & 415' FEL, Sec. 25, T28N, R11W

5. Lease Serial No.

SF-047017-B

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

Delo 9

9. API Well No.

30-045-21126

10. Field and Pool or Exploratory Area

Fulcher Kutz PC

11. Country or Parish, State

San Juan

New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

12/17/13 - Ran CBL, TOC @ 170', asked to combine plugs 2A & 2B as an inside only from 643' to 910'. Ray Espinoza on site with BLM agrees. Called Charlie Perin w/ OCD and got verbal approval.

12/18/13 - Pumped plug 1, WOC overnight, ran in & tagged upon hard cement @ 1345' (40' lower than planned). BLM on site is okay w/ proceeding on to plug 2. Called Brandon Powell w/ OCD and got verbal approval.

The subject well was P&A'd on 12/19/13 per the above notifications and the attached report.

RCVD JAN 15 '14

OIL CONS. DIV.

DIST. 3

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Kenny Davis

Title **Staff Regulatory Technician**

Signature

Date

1/10/2014

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

ACCEPTED FOR RECORD

Title

Office

JAN 13 2014

FARMINGTON FIELD OFFICE
BY: **SC**

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 *fax: 505-325-1211

Burlington Resources

Delo 9

December 19, 2013

Page 1 of 2

1920' FSL and 415' FEL, Section 25, T-28-N, R-11-W

San Juan County, NM

Lease Number: SF-047017-B

API #30-045-21126

Plug and Abandonment Report
Notified NMOCD and BLM on 12/11/13

Plug and Abandonment Summary:

- Plug #1** with CR at 1854' and CIBP at 1785' spot 41 sxs (48.38 cf) Class B cement inside casing from 1785' to 1255' to cover the Pictured Cliffs, Fruitland Coal tops. Tag TOC at 1349'.
- Plug #2** with 28 sxs (33.04 cf) Class B cement inside casing from 918' to 566' to cover the Kirtland and Ojo Alamo tops.
- Plug #3** with CR at 94' spot 40 sxs (47.2 cf) Class B cement in 2 stages 1) mix 24 sxs and circulate good cement out bradenhead. SI in BH with 200 PSI sting out and circulate casing clean with 8 bbls of water. LD tubing and setting tool. PU 3 jnts and mix 16 sxs and fill casing circulate good cement 110' to surface to cover the surface casing shoe. Tag TOC at 7'.
- Plug #4** with 24 sxs Class B cement top off surface and weld on P&A marker.

Plugging Work Details:

- 12/11/13 Rode rig and equipment to location. Spot in and RU. SI well. SDFD.
- 12/12/13 Bump test H2S equipment. Check well pressures: tubing and casing 20 PSI and bradenhead 0 PSI. Blow well down. ND stripping head. X-over to 1.5 tools. ND wellhead. Screw on A-plus 8-5/8" companion flange. NU A-plus BOP. RU High Tech tools, single BOP with 1.5 pipe rams. Pressure test blind rams to 250 PSI and 1250 PSI. Test blind rams, OK. PU on tubing. LD 1.5 sub. Check 2 way ck, no pressure. LD 55 jnts 1.5 EUE tubing 1-SN, 1 jnt with notch collar 56 jnts 1.5 tubing x-over to 2-3/8" tools. ND Hi-tech BOP and Acc. NU stripping head onto A-Plus BOP. SI well. SDFD.
- 12/13/13 Bump test H2S equipment. Check well pressures: casing 20 PSI and bradenhead 0 PSI. Blow well down. Tally and PU 1-4.5 A-Plus watermelon mill with 58 jnts A-plus 2-3/8 workstring to 1817'. LD 2 jnts, SB 28 stands total 1755'. TIH with 4.5" Select Tool CR. Set early at 564'. Order 6- 3-1/8" DC's and BHA. PU 3-7/8" 5 blade mill. 6 3-1/8" DC's x-over TIH with 6 stands. Tag with 8' stick up, LD 1 jnt. SI well. Spot in flow tank and power swivel. Spot in air package. SI well. SDFD.
- 12/16/13 Open up well; no pressures. PU and RU swivel. PU 1jnt with power swivel. Establish circulation. Found 4" tee washed out. Establish circulation. Start drilling on CR at 564' and drilled out. PU 1 jnt and chase down CR to 630'. RD swivel. TIH with tubing and chase CR down to 1854'. TOH with tubing and LD BHA. RD flow back tank and re-spot waste pit. RIH with 4.5" CIBP and set at 1785'. Note: BLM approved procedure change. Circulate well clean. Pressure test casing to 800 PSI, OK. SI well. SDFD.
- 12/17/13 Open up well; no pressures. Ran CBL from 1785' to surface. Note: BLM approved procedure change. Spot plug #1 with estimated TOC at 1255'. Note: B. Powell, NMOCD, S. Mason BLM and COPC approved plug #2. Attempt to mix cement, unable to get good cement. Note: BLM request tag plug #1. SI well. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 *fax: 505-325-1211

Burlington Resources

Delo 9

December 19, 2013

Page 2 of 2

Plugging Work Details (continued):

12/18/13 Bump test H2S equipment. Open up well; no pressures. TIH and tag TOC at 1349'. Note: B. Powell, NMOCD, BLM and COPC approved procedure change. Circulate well clean. Spot plug #2 with estimated TOC at 566'. LD all tubing. Perforate 4 HSC squeeze holes at 110'. Establish circulation. Circulate well clean. PU 4.5" Select Tool CR and set at 94'. Re-est. circulation. Spot plug #3 with estimated TOC at surface. LD all tubing. SI well. SDFD.

12/19/13 Open up well; no pressures. Tag TOC at 7'. ND BOP. Dig out wellhead. RU High Desert. Monitor and issue Hot Work Permit. Cut off wellhead. Found cement at surface. Spot plug #4 and weld on P&A marker. RD and MOL.

Jason Vasquez, COPC representative, was on location.

Ray Espinoza, BLM representative, was on location.