Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0137

BUREAU OF LAND MANAGEMENT				Expires: J	uly 31, 2010
		•		5. Lease Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLSE'N AFTER				SF- 078215	
				6. If Indian, Allottee or Tribe Na	ame
Do not use this form for proposa abandoned well. Use Form 3160-3				<i>j</i>	
SUBMIT IN TRIPLICATE - Other instructions of page 2) 8 2014			<u>l</u>	7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well					
Oil Well X Gas Well Other Form 177 on Field Office Bureau of Lared Monager)^?r	8. Well Name and No.	
2. Name of Operator	Bureau	of Land Work	TENER TO	9. API Well No.	Com 100S
Burlington Resources Oil & Gas Company LP			_	30-045-32513	
3a. Address 3b. Phone No. (include area code)			de)	10. Field and Pool or Exploratory Area	
PO Box 4289, Farmington, NM 87499		(505) 326-9700		Basin FC	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)				11. Country or Parish, State	
Surface Unit M (SWSW), 790' FSL & 795' FV		VI., Sec. 7, T32N, R10W		San Juan ,	New Mexico
		,		,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
12. CHECK THE APPROPRIATE BOX((ES) TO IND	CATE NATURE	OF NO	TICE, REPORT OR OTHE	R DATA
TYPE OF SUBMISSION	TYPE OF AC			TION	
Notice of Intent Acidize	Deep	en	P	roduction (Start/Resume)	Water Shut-Off
Alter Casing	Fract	ure Treat	F	Reclamation	Well Integrity
X Subsequent Report Casing Repair	New	Construction	F	Recomplete	Other
Change Plans	X Plug	and Abandon	Fi	Cemporarily Abandon	
Final Abandonment Notice Convert to Injection	Plug		=	Vater Disposal	
13. Describe Proposed or Completed Operation: Clearly state all pertinent				<u> </u>	te duration thereof
If the proposal is to deepen directionally or recomplete horizontally,					
Attach the bond under which the work will be performed or provide	the Bond No. o	n file with BLM/BIA	. Require	ed subsequent reports must be file	d within 30 days
following completion of the involved operations. If the operation re-	-	-	_		
Testing has been completed. Final Abandonment Notices must be fi determined that the site is ready for final inspection.)	iled only after al	I requirements, inclu	ding recia	amation, have been completed and	the operator has
determined that the site is ready for final hispection.)					
12/13/13 - PC plug originally to be @ 3495'. Ta	aged @ 350	20' perfed liner	bottto	m @ 3535' Spoke w/ Br	andon Powell w/ OCD
& received verbal approval to move up to FC pl				_	
			, p - 1 p -		
12/16/13 - TOC on CBL is 158', planned to do a	a surf plug i	nside but no ce	ment t	here. Asked to perf @ 1	50' & circ outside throug
annulus. Called Steve Mason w/ BLM & receive	ed verbal ap	proval. Called	Brando	on Powell w/ OCD he co	ncurred but asked for
inside to be spotted @ 208'.					•
				,	•
				All co	D *
	•	•		GIF CO	NS. DIV DIST. 3
				.1Δ1.	N 1 0 2014
The subject well was P&A'd on 12/17/13 per the	e above not	ifications & atta	ched r	eport.	· 1 U ZU14
					•
14. I hereby certify that the foregoing is true and correct. Name (Printed	/Typed)				

Staff Regulatory Technician Title 1/7/2014 Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE JAN 0.9 2014 Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify FARMINGTON FIELD OFFICE BY:_____ that the applicant holds legal or equitable title to those rights in the subject lease which would Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

entitle the applicant to conduct operations thereon.

Kenny Davis

Approved by

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources
Page Com 100S

December 17, 2013 Page 1 of 1

790' FSL and 795' FWL, Section 7, T-32-N, R-10-W San Juan County, NM Lease Number: SF-078215 API #30-045-32513

Plug and Abandonment Report Notified NMOCD and BLM on 12/10/13

Plug and Abandonment Summary:

- Plug #2 with CR at 3248' spot 79 sxs (93.22 cf) Class B cement inside casing from 3248' to 2838' to cover the Pictured Cliffs, Fruitland and liner top.
- Plug #3 with 33 sxs (38.94 cf) Class B cement inside casing from 1753' to 1578' to cover the Kirtland and Ojo Alamo tops.
- Plug #4 with 30 sxs (35.4 cf) Class B cement inside casing from 631' to 476' to cover the Nacimiento top.
- Plug #5 with 85 sxs (100.3 cf) Class B cement from 255' to surface with approx. 44 sxs inside 7" casing, 22 sxs outside &" with approx. 19 sxs good cement returned to pit out casing and bradenhead valves. Tag TOC at 10'.
- Plug #6 with 30 sxs Class B cement top off surface and weld on P&A marker.

Plugging Work Details:

- 12/11/13 Rode rig and equipment to location. Spot in and RU. Check well pressures: casing 90 PSI and tubing 50 PSI. RU relief lines. Blow well down. SI well. SDFD.
- 12/12/13 Bump test H2S equipment. Check well pressures: casing and tubing 60 PSI, bradenhead 0 PSI. ND wellhead. NU BOP. Function test BOP and unable to get blind rams to open. Pressure test BOP at 1150 PSI and 400 PSI, OK. Pressure test equipment and LD 2-3/8" tubing hanger. TOH with 2-3/8" prod string as follows: 111 jnts, 1-4' x 2-3/8" sub, 1 jnt, 1-2-3/8" F-nipple, 1 mule shoe, 2-3/8" 4.7# J-55 EUE tubing total 3499.49'. TIH tag fill at 3520'. SI well. SDFD.
- 12/13/13 Bump test H2S equipment. Check well pressures: casing and tubing 65 PSI and bradenhead 0 PSI. Open up well and blow down. Note: B. Powell, NMOCD approved procedure change. TIH with 7" scrapper and tag liner top at 3253'. TIH with 7" DHS CR and set at 3248'. Pull 10k over string weight. Establish circulation. Circulate well clean. Pressure test casing to 800 PSI. Ran CBL from 3248' to surface estimated TOC at 155'. TIH and displace fluid out of BOP and wellhead. SI well. SDFD.
- 12/16/13 Bump test H2S equipment. Open up well; no pressures. TIH to 3248' and establish circulation. Spot plug #2 with estimated TOC at 2838'. PUH. Establish circulation. Spot plugs #3 and #4. Perforate 4 HSC holes at 150'. Establish circulation. Circulate well clean. Establish rate of 3.5 bpm at 200 PSI. Spot plug #5 with estimated TOC at surface. SI well. SDFD.
- 12/17/13 Open up well; no pressures. Tag TOC at 10'. ND BOP. Fill out Hot Work permit. RU High Desert. Dig out wellhead. Cut off wellhead. Found cement at surface. Spot plug #6 and weld on P&A marker. RD and MOL.

Josh Jacobs, COPC representative, was on location. Joe Ruybalid, BLM representative, was on location.