## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin Cabinet Secretary-Designate

Brett F. Woods, Ph.D. Deputy Cabinet Secretary Jami Bailey, Division Director
Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

			<i></i>										
Operator S	Signature Dat	e: M	arch 4, 2014										
Application  Application  Well infor	P&A Location		Drilling/Casing ( Change		anç	ge [	Rec	on	np	let	e/ <b>i</b>	ЭΗ	IC
API WELL#	Well Name	Well #	Operator Name	Туре	Stat	County	Surf_Owner	UL	Sec	Twp	N/S	Rng	W/E
30-039- 05996-00-00	JICARILLA APACHE F	009	ELM RIDGE EXPLORATION COMPANY LLC	G	Ā	Rio Arriba	J	Р	16	25	Ŋ	5	W
***************************************													

Conditions of Approval:

Notify NMOCD 24hrs prior to beginning operations

Run CBL and present to agencies prior to perforating

NMOCD Approved by Signature

3/17/14

Form 3160-5 \* (Navember 1994)

# UNITED STATES DEPARTMENT OF THE INTERIOR

RECEWED

FORM APPROVED OMB No. 1004-0135 Expires July 34, 1996

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS MAR 06 2014

Jicarilla Contract 149

5. Lease Serial No.

Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals gron Field Off

6. If Indian, Allottee or Tribe Name

e			
agreement, Name and/or No.			
8. Well Name and No.  Jicarilla Apache F #9  9. API Well No.			
30-039-05996  10. Field and Pool, or Exploratory Area			
Gallup-Dakota sh, State unty, NM			
Water Shut-Off Well Integrity Other			
Gá sh,			

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days Following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Elm Ridge Exploration Co., LLC requests permission to plug and abandon this well according to the attached procedure.

RCVD MAR 11'14 OIL CONS. DIV. DIST. 3

· <b>/</b>		•	
14. Thereby certify that the foregoing is true and corn	rect		
Name (Printed/Typed) Amy Mackey	Title	Administrative Mana	ger
Signature	Date	March 4, 2014	
	THIS SPACE FOR FEDE	PERAL OR STATE USE	The state of the s
Approved by Original Signed: Step	hen Mason	Title	MAR 0.7 2014
Conditions of approval, if any, are attached. Approval o certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations t	those rights in the subject lease	Office	F-W-W () / 2011
Title 18 U.S.C. Section 1001, makes it a crime for any fraudulent statements or representations as to any matter.		to make to any department or agency of the United	States any false, fictitious or

#### Plugging Program for Jicarilla Apache F #9:

- 1) TOOH with 1-1/2" tubing strings from both Gallup and Dakota 2-7/8" wellbores.
- 2) Establish rate into both 2-7/8" casing strings with water.
- 3) In Dakota wellbore only, perforate squeeze holes at 5350' and 4200'.
- 4) Tie onto 2-7/8" Gallup casing string. Mix and pump 121 sx cement. Drop wiper plug, and displace to 2000' with 11.6 bbls water, to cover inside Gallup 2-7/8" casing string from 50' below top Gallup perf to 2000' (120' above Ojo Alamo top).
- See Avenue band
- 5) Tie onto 2-7/8" Dakota casing string. Mix and pump 63.1 sx cement. Drop wiper plug, and displace to 2000' with 11.6 bbls water to cover inside Dakota 2-7/8" casing string from 50' below top of Dakota to 2000' (120' above Ojo Alamo top), and outside Dakota and Gallup strings from 5350' to 4200'.
- 6) In both Gallup and Dakota casing strings, perforate squeeze holes at 980'. Tie onto both Gallup and Dakota casing strings. Mix and pump 443 sx, or sufficient volume to bring cement from 50' below top of Nacimiento to surface inside and outside both Gallup and Dakota casing strings.
- 7) Cut off both casing strings 4' below surface, set dry hole marker, and remediate location per regulatory agencies' conditions of approval.

### Elm Ridge Exploration Co., LLC

#### **Pertinent Data Sheet**

Well Name: Jicarilla Apache F #9
Footage: 1120' FSL and 1120' FEL
Location: Section 16, T25N, R5W
County: Rio Arriba County, NM

**API#:** 30

30-039-05996

Field: West Lindrith GP-DK

Elevation: 6760' KB

**TD**: 7450' KB

**GP PBTD:** 7210' KB **DK COTD:** 7340' KB

**Completed:** 6/11/62

#### **Casing Record:**

Hole Size	Csg Size	Wt.	Grade	Depth Set	Cement
13-3/4"	9-5/8"	25.4#	SJ-SW	215'	175 sx (Circ. cement to surface.)
7-7/8"	2-7/8"	6.4#	SS	7250'	Stg 1: 330 sx (DK: 200 sx; GP 130 sx)
7-7/8"	2-7/8"	6.4#	SS	7439'	Stg 2: 325 sx (DV tool @ 4051') <sup>1</sup>

<sup>1</sup>st Stage TOC: 5480' (TS). 2<sup>nd</sup> Stage TOC: 2000' (TS)

Tubing Record: GP: 1 jt 1-1/2" tbg, SN, and remaining tbg to 6209'.

DK: 1 jt 1-1/2" tbg, SN, and remaining tbg to 7226'

#### **Formation Tops:**

San Jose	Surface
Nacimiento	930'
Ojo Alamo	2120'
Kirtland-Fruitland	2534'
Pictured Cliffs	2914'
Lewis	2987'
Chacra	3772'
Mesaverde	4580'
Mancos	5300'
Gallup	6157'
Greenhorn	7047'
Dakota	7276'

Perforation Intervals: Gallup string: 6312-6384'

Dakota string: 6312-6384'


Wellbore Diagram Jicarilla Apache F 9 Sec. 16, T25N, R5W Rio Arriba Co., NM API #30-039-05996

#### **Before**

9-5/8" 25.4# set @ 215' Circulated cmt to surface Nacimiento 930' TOC: 2000' (TS) Oio Alamo 2120' Kirtland-Fruitland 2534' Pictured Cliffs 2914' Chacra 3772' DV Tool @ 4051' Mesaverde 4580' Mancos 5300' TOC: 5480' (TS) **Gallup 6157'** 1.9" EUE set at 6209' Gallup Perfs: 6312-6384' Greenhorn 7047' PBTD: 7210' 2-7/8" 6.4# set @ 7250' **Dakota 7276'** 1.9" EUE set at 7226' Greenhorn-Dakota Perfs: 7140-7338' COTD: 7340' 2-7/8" 6.4# set @ 7439' TD: 7450'

JicAp F 9.xls 3/4/2014 Wellbore Diagram Jicarilla Apache F 9 Sec. 16, T25N, R5W Rio Arriba Co., NM API #30-039-05996

#### After



# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: 9 Jicarilla Apache F

#### CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:

The procedure as outlined in step #5 would not work. You will be required as follows:

- a) Bring the top of the Dakota/Gallup top to 6057' or higher.
- b) Perforate the casing @ 5427' and place the Mancos plug from 5427' 5327' inside and outside the  $2\,7/8$ " casing.
- c) Perforate the casing @ 4606' and place the Mesavered plug from 4606'- 4506' inside and outside the 2.7/8" casing.
- d) Place the Chacra/Pictured Cliffs/Fruitland/Kirtland/Ojo Alamo plug from 3827' 2287'.

Note: The Gallup casing plug outlined in step #4, the casing will need to tested. If the casing doesn't test, pumping down the casing would not work and plugs would have to be set through tubing.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.