

· ···· · · · ·	
Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office Energy, Minerals and Natural Resources	June 19, 2008
1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-045-21029
District.III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV	STATE FEE 🗴
1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	ELLIOTT A LS
PROPOSALS.)	
1. Type of Well: Oil Well Gas Well 🕱 Other	8. Well Number
2. Name of Operator	9. OGRID Number
XTO Energy Inc.	5380
3. Address of Operator	10. Pool name or Wildcat
382 CR 3100 Aztec, NM 87410	AZTEC PICTURED CLIFFS
4. Well Location	
Unit Letter <u>M</u> : <u>900'</u> feet from the <u>SOUTH</u> line and	800' feet from the WEST line
Unit Letter <u>M</u> : <u>900'</u> feet from the <u>SOUTH</u> line and Section <u>19</u> Township <u>31N</u> Range <u>11W</u>	
Section 19 Township 31N Range 11W	NMPM County SAN JUAN
11. Elevation (Show whether DR, RKB, RT, GR	, etc.)
5982' GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
	-
NOTICE OF INTENTION TO:	JBSEQUENT REPORT OF:
TEMPORARILY ABANDON 🗌 CHANGE PLANS 🔲 COMMENCE DR	ILLING OPNS. 🔄 🛛 P AND A 🔄
PULL OR ALTER CASING  MULTIPLE COMPL  CASING/CEMEN	т јов
	-
OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At	tach wellbore diagram of proposed completion
or recompletion.	
XTO Energy Inc. intends to plug and abandon this well per the atta	
closed loop system. Please also see the attached current and prop	
Run COL And provides to NMOCO ; MOVE Fruitland plug to 2078-1978 ADD Kintland Oj. Adam plug - 1038-	the REVIEW ROUD MAR 11'14
- 11 1 abre to 2078- 1978	
Mour Fruithand pung to 2010 1110	Notify NMOCD 24 hrs
100 Kintland Oji AMAM pluy - 1038	- 7/L prior to beginning
	operations
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowl	edge and belief.
SIGNATURE Kuisten D. Bahcack	2/7/14
	ATORY ANALYST DATE DATE J77/14
Type or print name <u>KRISTEN D. BABCOCK</u> E-mail address:	kextoenergy.com PHONE _505-333-3206
Type of print name <u>competent with metodology</u> Contain address.	
For State Use Only	in the start
APPROVED BY Transform Rell TITLE Deputy O	III & Ges InspectBATE <u>3 24/14</u> District #3
Conditions of Approval (if any):	District #3





LWA \_\_\_\_\_ MTG \_\_\_\_\_ Approved \_\_\_\_\_

## PLUG AND ABANDONMENT PROCEDURE

. . .

١

March 6, 2014

## Elliott A LS 2

Aztec Picture Cliffs 990' FSL and 800' FWL, Section 19, T31N, R11W San Juan County, New Mexico / API 30-045-21029 Lat: \_\_\_\_\_/ Lat: \_\_\_\_\_

- Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.
  - Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
  - Rods: Yes\_\_\_\_, No\_\_\_, Unknown\_\_\_\_. Tubing: Yes\_\_\_\_, No\_X\_\_, Unknown\_\_\_\_, Size \_\_\_, Length \_\_\_\_ Packer: Yes\_\_\_\_, No\_X\_\_, Unknown\_\_\_\_, Type \_\_\_\_\_.
  - Plug #1 (Picture Cliffs Perforations and top, 2462' 2412'): PU and TIH with 2.785" cement retainer, set at 2462'. Pressure test tubing to 1000 PSI. Pressure test casing to 800 PSI. If casing does not test, then spot or tag subsequent plug as appropriate. Mix and pump 3 sxs Class B cement above CR to isolate Picture Cliffs perforations and top. PUH.
  - 4. Plug #2 (Fruitland top, 1925' 1825'): Mix and pump 5 sxs Class B cement and spot a balanced plug inside casing to cover the Fruitland top. TOH.
  - 5. **Plug #3 (8-5/8" Surface Casing shoe, 180' to Surface):** Perforate 3 HSC holes at 180'. Mix and pump approximately 67 sxs cement down the 5.5" casing until good cement returns out casing and bradenhead valves. Shut in well and WOC.
  - 6. ND BOP and cut off casing below surface casing flange. Install P&A marker with cement to comply with regulations. RD, move off location, cut off anchors and restore location.