ري مو			r.	E Provinging	11-21-2		
	, <b>1</b>		Ú V				
	Form 3160- 5 (August 2007)	UNITED S DEPARTMENT OF BUREAU OF LAND	THE INTERIOR MANAGEMENT	May 27 2		FORM APPROVED OMB No. 1004- 0137 Expires: July 31,2010	
	SUNDRY NOTICES AND REPORTS ON WELLS ( Land Well Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				12 3MDA: 701-98-0013 Tract 1 6. If Indian, Allottee, or Tribe Name		
						A Agreement Name and/or No.	
	SUBMIT IN TRIPLICATE - Other Instructions on page 2.       1     Type of Well       Oil Well     Gas Well   Other				8. Well Name a	-	
	2. Name of Operator Black Hills Gas Resources, Inc.				<b>Jicarilla 29-02-30 #34</b>		
	3a. Address	<u>rces, mc.</u>	3b. Phone No. (include are	ea code)	<b>30-039-2</b>		
	3200 N 1st St, Bloomfi		(505) 634-5104	,	10. Field and Po	ool, or Exploratory Area	
2	4. Location of Well (Foolage, Sec., T., R., M., or Survey Description) 1605' FSL & 755' FEL NE/SE Section 30 T29N R2W (UL: I)			East Blanco Pictured Cliffs 11. County or Parish, State			
भूर					Rio Arriba County, New Mexico		
~	12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, O						
	TYPE OF SUBMISSION TYPE OF ACTION						
					·······		
	Notice of Intent		Deepen	Production ( S	Start/ Resume)	Water Shut-off	
		Altering Casing	Fracture Treat	Reclamation		Well Integrity	
	Subsequent Report	Casing Repair	New Construction	Recomplete		Other	
	. Bl	Change Plans	Plug and abandon	Temporarily A	Abandon	•	
	Final Abandonment Notice	Convert to Injection	Plug back	Water Dispos	al		
	Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.) Black Hills Gas Resources intends to plug and abandon Jicarilla 29-02-30 #34 per attached procedure.						
	OIL CONS. DIV DIST. 3						
	AVARNEREDA 29M. 18	Notify NMOCD 24 1 prior to beginnin L OR ACCEPTANCE OPTHIS	hrs MAY	<b>29</b> 2014			
	action ides n Oficator fro Authorization	d of relative the lessee af M Ojtaining any other N required for operatio D indian lands	ND		0	ATTACHED FOR ONS OF APPROVAL	
	14. I hereby certify that the foregoing is true and correct. Name (Printed/ Typed)						
	Daniel Manus Title Regulatory Techician						
	Signature Milling Date May 19, 2014 THIS SPACE FOR FEDERAL OF STATE OFFICE USE I						
	Approved by						
	Conditions of approval, if any are attach that the applicant holds legal or equitabl entitle the applicant to conduct operation	e title to those rights in the subject lease	rant or certify	FFO	0		
	Title 18 U.S.C. Section 1001 AND Title fictitious or fraudulent statements or rep	43 U.S.C. Section 1212, make it a crime	e for any person knowingly a irisdiction.		department or age	ncy of the United States any false,	
	(Instructions on page 2)		:				

.;



6

## PLUG AND ABANDONMENT PROCEDURE

May 16, 2014

## Jicarilla 29-02-30 #34


East Blanco Pictured Cliffs/Fruitland Sand 1605' FSL, 755' FEL, Section 30, T29N, R2W, Rio Arriba County, NM API 30-039-29530 / Long: \_\_\_\_\_ / Lat: \_\_\_\_\_

- 1. This project will use an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
- Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
- 3. Rods: Yes\_\_\_\_, No\_X\_, Unknown\_\_\_\_. Tubing: Yes\_X\_, No\_\_\_, Unknown\_\_\_\_, Size <u>2-7/8</u>, Length <u>3436</u>. Packer: Yes\_\_\_\_, No\_X\_, Unknown\_\_\_, Type \_\_\_\_\_.


If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.

NOTE: TOH AND LD 2-7/8" tubing. Black Hills will provide 2-3/8" tubing to plug well with.

- 4. Plug #1 (Pictured Cliffs interval, Fruitland Sand interval, Kirtland and Ojo Alamo tops, 3380' 2998'): Round trip 5.5" gauge ring or csg scraper to 3380', or as deep as possible. TIH and set 5.5" wireline CIBP or tbg-set CR at 3380'. Tag CIBP or CR with tubing. Mix 53 sxs Class B cement and spot plug inside the casing above the CIBP or CR to isolate the PC interval, fill the Fruitland Sand perforations and cover the Fruitland, Kirtland and Ojo Alamo tops. PUH and WOC. TIH and tag cement 50' above top of Ojo Alamo. If necessary top off cement and go to Plug #2.
- 5. Plug #2 (Nacimiento top, 2015' 1915'): Mix 17 sxs Class B cement and spot a balanced plug inside the casing to cover the Nacimiento top. PUH.
- 6. **Plug #3 (8-5/8" Surface casing shoe, 323' Surface)**: Mix and pump 37 sxs Class B cement inside 5.5" casing from 323' to surface; TOH and LD tubing. PU plastic tubing and spot 8 sxs Class B cement in annulus from 30' to surface. TOH and LD plastic tubing.
- ND BOP and cut off wellhead below surface casing flange. Top off as necessary and install P&A marker with cement to comply with regulations. RD, MOL and cut off anchors. Restore location per BLM stipulations.



3643' TD 3611' PBTD



3611' PBTD

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Jicarilla 29-02-30 #34

## CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

3. The following modifications to your plugging program are to be made:

a) Bring the top of plug #2 to 1820' to cover the Nacimiento top

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

1

Office Hours: 7:45 a.m. to 4:30 p.m.