Submit & Copies To Appropriate District Office State of New Mexico Figure 1. Minerals and Network Decomposite Figure 2. Minerals and Network Decomposite Figure 2. Minerals and Network Decomposite Figure 2. Minerals and Network Decomposite Figure 3. Minerals and Network Decomposite Figure 4. Minerals and Network Decomposite Figure 3. Minerals and Network Decomposite Figure 4. Minerals and Network Decomposi			Form C-10	
District I	Energy, Minerals and Natural Resources		June 19, 200)8
1625 N. French Dr., Hobbs, NM 87240 District II			WELL API NO. 30-039-30148	
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type of Lease	1
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505		STATE FEE		
District IV 1220 S. St. Francis Dr., Santa Fe, NM		6. State Oil & Gas Lease No.	\dashv	
87505			or state on a sus heast two.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name: Carracas SWD	
1. Type of Well: Oil Well Gas Well Other Salt Water Disposal			8. Well Number	7
Oil Well Gas Well Other Salt Water Disposal 2. Name of Operator			# 2 9. OGRID Number	
Energen Resources Corporation			162928	
3. Address of Operator			10. Pool name or Wildcat	┪
2198 Bloomfield Highway, Farmington, NM 87401			Entrada-Chinle	╝
4. Well Location				
Unit Letter I : 1489 feet from the South line and 134 feet from the East line				
Section 09	Township 32N	Range 04W	NMPM County Rio Arrib	a
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
	622	22' GL		_
12. Check A	appropriate Box to Indicate	Nature of Notice, l	Report, or Other Data	
NOTICE OF INTENTION TO:			SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			☐ ALTERING CASING	\Box
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI		_
<u>_</u> ·				
PULL OR ALTER CASING X	MULTIPLE COMPL	CASING/CEMENT J	OB 🗀	
DOWNHOLE COMMINGLE				
OTHER:		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
Energen Resources intends surface as per the attach	ned procedure.	NMOCD 24 hrs	tring from the 5 1/2" liner top to	
This will be a closed loo	į, o	to beginning perations	OIL CONS. DIV DIST. 3	
The NMOCD will be notified 24hrs before commencing operations and MI			Ts	
			JUN 3 0 2014	
G 1D	Pi - Pala	nas Datas		
Spud Date:	Rig Relea	ase Date:		
I hereby certify that the information	above is true and complete to the	e best of my knowledg	ge and belief.	
SIGI II II CILE			t Engineer DATE 6/27/14	
Cplacke@energen.com Type or print name Collin Placke E-mail address:PHONE 505.325.6800				
For State Use Only		Πi	& Gas Inspector. strict #3 DATE 7/7/14	
APPROVED BY Dunel Conditions of Approval (if any):		TLE	DATE // / · · ·	_
Conditions of Approval (II ally).	•	7		

Recommended Procedure Carracas SWD #2 API No. 30-039-30148

NOTE: See pertinent data for physical well data.

- 1. MIRU. Pump kill fluid, set plug in 3 ½" tbng, and test tbng to 2500psi. ND WH, NU BOP.
- 2. Release on/off tool from packer and TOOH w/ tbng while scanning. Replace bad jnts.
- 3. TIH w/ 5 ½" WRBP to 8500'. PU 2 7/8" N-80 WS and 5 ½" packer, TIH to 8450' and test WRBP to 1000psi.
- 4. PUH w/ packer and test 5 ½" csng from TOL to WRBP to 600psi. TOOH and LD 5 ½" packer.
- 5. MIRU wireline. Run EMIT log from 3480' to surface to determine ID of csng patches at 2879'-2899' and 370'-390'.
- 6. PU mill and dress up tie back sleeve at 5954'. LD mill.
- 7. PU 5 ½" TIW seal assembly, 5 ½" x 7" XO, and TIH on 7" 26# L-80 csng to tie back sleeve.
- 8. Set down on seal assembly and pressure test backside to 600psi to ensure seal. PU on seal assembly and establish circulation to surface.
- 9. Circulate 7" tie back csng w/ cmnt to surface.
- 10. Set down on seal assembly and hang off 7" csng at surface. WOC.
- 11. TIH and clean out to WRBP at 8500'. Pressure test csng to 600psi for 30 mins. Release WRBP and TOOH.
- 12. PU 3 ½" injection string and TIH to packer. Latch on packer and pressure test backside to 600psi. Latch off packer and circulate packer fluid in annulus.
- 13. Latch on packer and hang off 3 ½" tbng.
- 14. RDMO WSU.