Form 3160-5 (August-2007)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVE

FORM APPROVED OMB NO. 1004-0137 Expires July 31, 2010

Lease Serial No.

SUNDRY NOTICES  Do not use this form for abandoned well. Use Fori	Jicarilla Contract 67 6. If Indian, Allottee or Tribe Name Ficarilla Apache				
SUBMIT IN TRIPLICAT	TE - Other instruction	ons on page 200 La	and Manage	7! If Unit or CA/Agree	ment, Name and/or No
Type of Well Oil Well X Gas Well Other      Name of Operator Energen Resources Corporation				8. Well Name and No. Jicarilla 67  9. API Well No.	#11
3a. Address	3b. Phone No. (include area code)		30-039-20730		
2010 Afton Place, Farmington, NM 87401       505-325-6800         4. Location of Well (Footage, Sec., T., R., M., or Survey Description)         1810' FSL 1180' FWL Sec. 19 T25N R05W N.M.P.M. (L)NW/SW				10. Field and Pool, or Exploratory Area S. Blanco Pictured Cliffs/ Otero Chacra 11. County or Parish, State Rio Arriba NM	
12. CHECK APPROPRIATI	E BOX(ES) TO IN	DICATE NATURE OF N	OTICE, REPO		
TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent  Subsequent Report  Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction X Plug and Abandon Plug Back	Reclamation Recomple	on W te C	/ater Shut-Off ell Integrity ther
13. Describe Proposed or Completed Operation (clearly If the proposal is to deepen directionally or recomp Attach the Bond under which the work will be per following completion of the involved operations. I testing has been completed. Final Abandonment I determined that the final site is ready for final insper.	olete horizontally, give s rformed or provide the I If the operation results i Notices shall be filed or	subsurface locations and meas Bond No. on file with BLM/ n a multiple completion or re	sured and true ver BIA. Required s ecompletion in a r	rtical depths of all perting ubsequent reports shall be new interval, a Form 316	ent markers and zones be filed within 30 days 0-4 shall be filed once

Energen Resources intends to plug and abandon the Jicarilla 67 #11 according to the attached procedure.

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

OLCONS. DIV DIST. 3

SEE ATTACHED FOR CONDITIONS OF APPROVAL

Notify NMOCD 24 hrs prior to beginning operations

Regulatory Analyst 06/26/14
STATE OFFICE USE
Petroleum Engineer Pate 7 7 2014
ffice FF6
it

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

### PLUG AND ABANDONMENT PROCEDURE

May 9, 2014

## Jicarilla 67-11 South Blanco Pictured Cliffs / Otero Chacra Extension

	1810' FSL and 1180' FWL, Section 19, T25N, R5W, Rio Arriba County, New Mexico API 30-039-20730 / Lat: / Long:
Note:	All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.
	This project will use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
1.	Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Blow PC casing down; kill with water as necessary. Open up bradenhead valve. Establish rate down 2-7/8" PC then CH casing, record pump rate and pressure. Monitor bradenhead for flow. If now flow or blow, then pump additional water and monitor pressure, rate and volumes pumped to confirm perforations taking water and there is not a casing leak.
2.	Rods:       Yes
Pictur	ed Cliffs P&A:
3.	RU on PC 2-7/8" casing.
4.	Plug #1 PC (Pictured Cliffs interval, Fruitland, Kirtland and Ojo Alamo tops, 2568' – 2051'): Round trip 2.875" gauge ring to 2568' or as deep as possible. RIH and set 2.875" wireline CIBP at 2568'. TIH with tubing and tag CIBP at 2568'. Load casing with water and circulate well clean. Pressure test casing to 500#. If the casing does not test, then spot or tag subsequent plugs as appropriate. Mix 16 sxs Class B cement and spot a balanced plug inside the casing above the CIBP to isolate the PC interval and cover through the Ojo Alamo top. TOH with tubing.
5.	Plug #2 PC (Nacimiento top and 9.625" casing shoe, 1205' - 0'): TIH with open ended tubing. Mix approximately 34 sxs Class B cement from 1205' to surface, circulate good cement out the casing valve. Shut in well and WOC.
6.	RU on Chacra 2-7/8" casing
7.	Plug #1 CH (Chacra perforations, fish, Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops, 3424'- 2011'): PU open ended tubing and TIH. Establish injection rate into CH perforations. Note: previous record indicates a fish may be in the hole at 3450'. Mix and pump 51 sxs Class B cement (30% excess) and bullhead down 2-7/8" casing from surface. PUH with tubing. SI CH casing valve and WOC. TIH and tag cement at least 50' above Ojo Alamo top. If

necessary top off 2-7/8" CH Plug #1 with cement.

#### See COA

- 8. Plug #2 CH (Nacimiento top, 1205' 1105'): Perforate 3 squeeze holes at 1205'. Attempt to establish rate into squeeze holes if the casing pressure tested. Set 2.875" wireline cement retainer at 1155'. Sting into CR and establish rate into squeeze holes. Mix and pump 61 sxs Class B cement, squeeze 56 sxs outside casing and leave 5 sxs inside casing to cover the Nacimiento top. TOH and LD tubing.
- 9. Plug #3 CH (Surface casing, 172' Surface): Perforate 3 squeeze holes at 172'. Establish circulation out bradenhead and casing valve. Mix 60 sxs Class B cement and pump down PC casing and circulate good cement out casing valve and bradenhead valve. SI well and WOC.
- 10. ND BOP and cut off wellhead below surface casing flange. Install P&A marker with cement to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. Cut off anchors and clean up location. Restore location per BLM stipulations.

#### Jicarilla 67-11 Current

Otero Chacra Ext. / So. Blanco Pictured Cliffs 1810' FSL & 1180' FWL, Section 19, T-25-N, R-5-W, Rio Arriba County, NM

\_\_\_\_\_/ Long: \_\_\_\_/ API 30-039-20730 Today's Date: 5/9/14 Spud: 11/16/73 9.625" 32.3#, H-40 Casing set @ 122' Cement with 142 cf, circulated to surface Comp: 6/7/74 13.75" Hole Elevation: 6610' GL Nacimiento @ 1155' TOC @ 1600' (T.S.) Ojo Alamo @ 2061' Kirtland @ 2199' Fruitland @ 2455' Pictured Cliffs Perforations: Pictured Cliffs @ 2618' 2618' - 2630' 8-3/4" Hole 2.875" 6.4#, J-55 Casing @ 2701' Cement with 355 cf Fish @ 3450' (swab mandrel & 25' sandline) Chacra Perforations: Chacra @ 3476' 3474' - 3590' 6.75" and 2.875" 6.4#,J -55 Casing @ 3659' 7-7/8" Hole Cement with 412 cf 3659' TD 3648' CH PBTD 2690' PC PBTD

### Jicarilla 67-11 Proposed P&A

Otero Chacra Ext. / So. Blanco Pictured Cliffs

1810' FSL & 1180' FWL, Section 19, T-25-N, R-5-W, Rio Arriba County, NM

/ Long: / API 30-039-20730 Today's Date: 5/9/14 Spud: 11/16/73 9.625" 32.3#, H-40 Casing set @ 122' Cement with 142 cf, circulated to surface Comp: 6/7/74 13.75" Hole Elevation: 6610' GL Chacra Plug #3: 172' - 0' Perforate @ 172' Class B cement, 60 sxs See COA Chacra Plug #2: 1205' - 1105' Class B cement, 61 sxs 56 outside and 5 inside Set CR @ 1155' Nacimiento @ 1155' See COA Perforate @ 1205' PC Plug #2: 1205' - 0' Class B cement, 34 sxs TOC @ 1600' (T.S.) Ojo Alamo @ 2061' Kirtland @ 2199' Chacra Plug #1: 3424' - 2011' Class B cement, 51 sxs (30% excess) Fruitland @ 2455' See COA PC Plug #1: 2568' - 2051 Class B cement, 16 sxs Set CIBP @ 2568' Pictured Cliffs @ 2618' Pictured Cliffs Perforations: 2618' - 2630' 8-3/4" Hole 2.875" 6.4#, J-55 Casing @ 2701' Cement with 355 cf Fish @ 3450' (swab mandrel & 25' sandline) Chacra Perforations: Chacra @ 3476' 3474' - 3590' 6.75" and 2.875" 6.4#,J -55 Casing @ 3659' 7-7/8" Hole Cement with 412 cf 3659' TD

3648' CH PBTD 2690' PC PBTD

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: Jicarilla 67 #11

#### **CONDITIONS OF APPROVAL**

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. Bring the top of plug #1 (PC) to 2009 ft. to cover the Ojo Alamo top.
- 4. Adjust the placement of plug #2 (PC) to (690-0) ft. to cover the Nacimiento top and surface shoe.
- 5. Adjust placement to plug #2 (CH) to (690-790) ft. inside/outside to cover the Nacimiento top.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.