Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

DEI ARTMENT OF THE INTERIOR		ı
BUREAU OF LAND MANAGEMENT		1
SUNDRY NOTICES AND REPORTS ON V	WELLS	•

FORM APPROVED OMB NO. 1004-0137 Expires July 31, 2010

5. Lease Serial No.

Jicarilla Contract 67

Do not use this form for proposals to drill or to re-enter an JUN 3 () 2014 abandoned well. Use Form 3160-3 (APD) for such proposals

6. If Indian, Allottee or Tribe Name

abandoned wen. Ose Form	1 3 100-3 (AFD) 101	Such proposals.		Jicarilla .	Apache	
SUBMIT IN TRIPLICAT	E - Other instruction	ons on page 2 Liu Oi Li				Name and/or No
1. Type of Well Oil Well X Gas Well Other 2. Name of Operator				8. Well Name a		#18
Energen Resources Corporation 3a. Address 2010 Afton Place, Farmington, NM 87 4. Location of Well (Footage, Sec., T., R., M., or Survey D 1850' FSL 820' FEL Sec. 19 T25N F	escription)	3b. Phone No. (include are 505–325–6800 (I) NE/SE	ea code)	9. API Well No. 30–039–213 10. Field and I S. Blanco Otero Chac 11. County or	Pool, or Explo Pictured Parish, State	Cliffs/
12. CHECK APPROPRIATE	BOX(ES) TO INI	DICATE NATURE OF N	OTICE, REPO	Rio Arriba RT, OR OTHE		NM
TYPE OF SUBMISSION		TY	PE OF ACTION			
X Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction X Plug and Abandon Plug Back	Reclamation Recomple	te Iy Abandon	Water Si Well Inte	
13. Describe Proposed or Completed Operation (clearly If the proposal is to deepen directionally or recomple Attach the Bond under which the work will be perfifollowing completion of the involved operations. If testing has been completed. Final Abandonment No determined that the final site is ready for final inspec	ete horizontally, give so formed or provide the I the operation results in otices shall be filed on	ubsurface locations and mea: Bond No. on file with BLM/ n a multiple completion or re	sured and true ver BIA. Required secompletion in a r	rtical depths of al ubsequent reports new interval, a Fo	ll pertinent ma s shall be filed orm 3160-4 sh	arkers and zones. d within 30 days nall be filed once

Energen Resources intends to plug and abandon the Jicarilla 67 #18 according to the attached procedure.

OIL CONS. DIV DIST. 3 JUL 14 2014

Notify NMOCD 24 hrs prior to beginning operations

ELM'S APPROVAL OR ACCEPTANCE OF THIS ACTION BOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

SEE ATTACHED FOR CONDITIONS OF APPROVAL

Regulatory		
Regulatory		
	Analyst	
06/26/14		
STATE OFFICE	USE	
icle Petroleum	Engineer	Date 7 7 2014
	3	
į	STATE OFFICE itle Petroleum	STATE OFFICE USE itle Petroleum Engineer ffice

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

PLUG AND ABANDONMENT PROCEDURE

April 21, 2014

Jicarilla 67-18

	South Blanco Pictured Cliffs / Otero Chacra Extension 1850' FSL and 820' FEL, Section 19, T25N, R5W, Rio Arriba County, New Mexico API 30-039-21307 / Lat: / Long:/
Note:	All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.
	This project will use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
1.	Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
2.	Rods: Yes, NoX, Unknown Tubing: Yes, NoX, Unknown, Size, Length Packer: Yes, NoX, Unknown, Type If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.

Pictured Cliffs P&A:


- 4. Plug #1 CH (Chacra perforations and top, 3446' 3346'): Round trip 2.875" casing scraper or gauge ring to 3446'. RIH and set 2.875" wireline CIBP at 3446'. TIH with tubing and tag CIBP at 3446'. Load casing with water and circulate well clean. Pressure test casing to 500#. If the casing does not test, then spot or tag subsequent plugs as appropriate. Mix 10 sxs Class B cement and spot a balanced plug inside the casing above the CIBP to isolate the Chacra interval. PUH with tubing.
- 5. Plug #2 CH (Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops, 2670' 2000'): TIH with open ended tubing. Spot 20 sxs Class B cement inside casing to cover through the Ojo Alamo tops. PUH with tubing. WOC if necessary.
- Plug #3 CH (Nacimiento top and Surface casing, 715' Surface): TIH with open ended tubing.
 Mix approximately 20 sxs Class B cement from 715' to surface, circulate good cement out the casing valve. Shut in well and WOC.
- 7. Plug #1 PC (Pictured Cliffs interval, Fruitland, Kirtland and Ojo Alamo tops, 2584' 2000'):
 Round trip 2.875" casing scraper or gauge ring to 2584'. RIH and set 2.875" wireline CIBP at 2584'. TIH with tubing and tag CIBP at 2584'. Load casing with water and circulate well clean. Pressure test casing to 500#. If the casing does not test, then spot or tag subsequent plugs as appropriate. Mix 18 sxs Class B cement and spot a balanced plug inside the casing above the CIBP to isolate the PC interval and cover through the Ojo Alamo top. TOH with tubing.

- 8. Plug #2 PC (Nacimiento top, 715' 615'): Perforate 3 squeeze holes at 715'. Attempt to establish rate into squeeze holes if the casing pressure tested. Set 2.875" cement retainer at 715'. Establish rate into squeeze holes. Mix and pump 61 sxs Class B cement, squeeze 56 sxs outside the casing and leave 5 sxs inside casing to cover the Nacimiento top. TOH and LD tubing.
 - 9. Plug #3 PC (Surface casing, 187' Surface): Perforate 3 squeeze at 187'. Establish circulation out bradenhead and casing valve. Mix 80 sxs Class B cement and pump down PC casing and circulate good cement out casing valve and bradenhead valve. SI well and WOC.
 - 10. ND BOP and cut off wellhead below surface casing flange. Install P&A marker with cement to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. Cut off anchors and clean up location. Restore location per BLM stipulations.

Jicarilla 67-18 Current

Otero Chacra Ext. / So. Blanco Pictured Cliffs

1850' FSL & 820' FEL, Section 19, T-25-N, R-5-W , Rio Arriba County, NM



Jicarilla 67-18 Proposed P&A

Otero Chacra Ext. / So. Blanco Pictured Cliffs

1850' FSL & 820' FEL, Section 19, T-25-N, R-5-W, Rio Arriba County, NM

_/ Long: _ / API 30-039-21307 Today's Date: 4/21/14 Spud: 5/17/77 9.625" 32.3#, H-40 Casing set @ 137' Cement with 142 cf, circulated to surface Comp: 6/30/77 13.75" Hole Elevation: 6597' GL Perforate @ 187' Plug #3 PC: 187' - 0' Class B cement, 80 sxs Nacimiento @ 665' *est Set CR @ 665' Plug #3 Chacra: 715' - 0' Class B cement, 20 sxs Perforate @ 715' Plug #2 PC: 715' - 615' Class B cement, 61 sxs TOC @ 1850' (TS) 56 outside and 5 inside Ojo Alamo @ 2050' Kirtland @ 2225' *est Fruitland @ 2375' *est Pictured Cliffs Perforations: 2634' - 2652', Squeezed PC Perfs with 75 sxs and re-perf'd (1977) Plug #1 PC: 2584' - 2000' Pictured Cliffs @ 2620' Set CIBP @ 2584' Class B cement, 18 sxs 2.875" 6.4#, J-55 Casing @ 2753' Cement with 324 cf Plug #2 Chacra: 2670' - 2000' Class B cement, 20 sxs Set CIBP @ 3446' Plug #1 Chacra: 3446' - 3346' Class B cement, 10 sxs Chacra Perforations: Chacra @ 3474' 3496' - 3513' 2.875" 6.4#,J -55 Casing @ 3632'

> 6.75" / 8.75" Hole

3632' TD 3622' CH PBTD 2743' PC PBTD

Cement with 300 cf

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment	to	notice	of
Intention to	Ab	andoń	•

Re: Permanent Abandonment

Well: Jicarilla 67 #18

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.