Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

1420		ر ا د. خسانسا
والمهيمة المدستانية ال	77 (P) 477 .	

FORM APPROVED OMB NO. 1004-0137 Expires July 31, 2010

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for abandoned well. Use Fo	r proposals to drill orm 3160-3 (APD) for	or to re-enter an	rate de	6. If Indian, Allot	tee or Tribe Name
SUBMIT IN TRIPLICA	TE - Other instruction		***	OTOTT TE	Agreement, Name and/or No
Type of Well Oil Well				8. Well Name and Jicarilla 98	
ENERGEN-RESOURCES-CORPORATION					
3a. Address	,	3b. Phone No. (include are	a code)	9API-Well-No 30-039-06347	7
		<u>505-325-6800</u>		10. Field and Poo	ol, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey	Description)			Gavilan Pict	ured Cliffs
990' FSL, 990' FWL, Sec. 19, T:26N	, 03W. (M)				
				11. County or Pa	rish, State
				Rio Arriba	NM
12. CHECK APPROPRIAT	TE BOX(ES) TO INI	DICATE NATURE OF N	OTICE, REPO	RT, OR OTHER	DATA
TYPE OF SUBMISSION		TYP	E OF ACTION		
X Notice of Intent	Acidize	Deepen	Production	(Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	Reclamati	<u> </u>	Well Integrity
Subsequent Report		=	\exists	_	i .
_	Casing Repair	New Construction	Recomple	te	Other
Final Abandonment Notice	Change Plans	X Plug and Abandon	Temporari	ly Abandon	
EP BP	Convert to Injection	on Plug Back	Water Dis	posal	

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleted in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

Energen Resources plans to plug and abandon the Jicarilla 98 #1 per the attached procedure.

This will be a closed loop operation. NMOCD will be notified 24 hrs prior to commencing operation.

OIL CONS. DIV DIST. 3

SEE ATTACHED FOR CONDITIONS OF APPROVAL

entitle the applicant to conduct operations thereon

AUG 07 2014

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER **AUTHORIZATION REQUIRED FOR OPERATIONS** ON FEDERAL AND INDIAN LANDS

Notify NMOCD 24 hrs prior to beginning operations

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Kyle, Mason T	itle District Engineer
a Al M	pate 7/16/2014
THIS SPACE FOR FEDERAL	OR STATE OFFICE USE
Approved by Troy Salvers	Title Petroloum Engineer Date 8 8 2014
Conditions of approval, if aby, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would	Office

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

PLUG AND ABANDONMENT PROCEDURE

June 3, 2014

Jicarilla 98 #1

Undesignated Pictured Cliffs
990' FSL, 990' FWL, Section 19, T26N, R3W, Rio Arriba County, NM
API 30-039-06347 / Long: ____ / Lat:

	API 30-039-06347 / Long: / Lat:
ote:	All cement volumes use 10% excess per 1000 foot of depth or 100% excess outside pipe and 50' excess inside pipe, whichever is greater. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.8 ppg with a 1.18 cf/sx yield.
1.	This project will use an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
2.	Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
3.	Rods: Yes, NoX, Unknown Tubing: YesX, No, Unknown, Size2-3/8", Length3900' Packer: Yes, NoX, Unknown, Type If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.
4.	Plug #1 (Pictured Cliffs interval and Fruitland top, 3890' – 3790'): Round trip 5.5" gauge ring to 3890', or as deep as possible. TIH and set 5.5" CR at 3890'. Pressure test tubing to 1000#. Attempt to pressure test casing to 800#. IF casing does not test, then spot or tag subsequent plugs as appropriate. Mix 17 sxs Class B cement and spot plug inside the casing above the CR to isolate the PC interval and cover the Fruitland top. TOH.
5.	Plug #2 (Kirtland and Ojo Alamo tops, 3628' - 3343'): Mix 38 sxs Class B cement and spot a balanced plug inside the casing to isolate the Kirtland and Ojo Alamo tops. PUH.
6.	Plug #3 (Nacimiento top, 2204' - 2104'): Mix 17 sxs Class B cement and spot a balanced plug inside the casing to isolate the Nacimiento top. TOH.
7.	Plug #4 (10-3/4" Surface casing shoe, 321' - Surface): Perforate squeeze holes at 321'. Establish circulation out casing and bradenhead. Mix and pump 150 sxs Class B cement down 5.5" casing and circulate out annulus. SIH well and WOC.
8.	ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations

Maria de Carres de Carres

Jicarilla 98 #1 Proposed P&A

Undesignated Pictured Cliffs

990' FSL & 990' FWL, Section 19, T-26-N, R-3W, Rio Arriba County, NM

Lat: N _____/ Long: W __ _____/ API #30-039-06347 Today's Date: 6/3/14 10-3/4", 32.75# Casing set @ 271' Spud: 8/31/55 12-1/4" hole (est) Cmt with 250 sxs (Circulated to Surface) Completed: 9/21/55 Elevation: 6886' GI Plug #4: 321' - 0' Perforate @ 321' Class B cement, 150 sxs TOC 720' (T.S.) Nacimiento @ 2154' *est Plug #3: 2204' - 2104' Class B cement, 17 sxs Ojo Alamo @ 3393' Plug #2: 3628' - 3343' Kirtland @ 3578' Class B cement, 38 sxs Plug #1: 3890' - 3790' Class B cement, 17 sxs Fruitland @ 3874' 7-7/8" hole (est) Set CR @ 3890' 5-1/2",14# Casing set @ 3890' Cement with 700 sxs Pictured Cliffs @ 3930' Pictured Cliffs Open Hole: 3890' - 3930'

TD 3930'

Jicarilla 98 #1 Current

Undesignated Pictured Cliffs

990' FSL & 990' FWL, Section 19, T-26-N, R-3W, Rio Arriba County, NM

Lat: N ______ / Long: W _____ / API #30-039-06347 Today's Date: 6/3/14 10-3/4", 32.75# Casing set @ 271' Cmt with 250 sxs (Circulated to Surface) Spud: 8/31/55 12-1/4" hole (est) Completed: 9/21/55 Elevation: 6886' GI TOC @ 720' (T.S.) Nacimiento @ 2154' *est 2-3/8" tubing at 3900' Ojo Alamo @ 3393' Kirtland @ 3578' Fruitland @ 3874' 7-7/8" hole (est) Pictured Cliffs @ 3930' 5-1/2",14# Casing set @ 3890' Cement with 700 sxs Pictured Cliffs Open Hole: 3890' - 3930' TD 3930'

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment	tó	notice	Ōſ
Intention to	Αh	andon	

Re: Permanent Abandonment

Well: Jicarilla 98 #1

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Bring the top of plug #1 to 3609 ft. to cover the Pictured Cliffs and Fruitland formation tops. Adjust cement volume accordingly. Note: Plugs 1 & 2 can be combined (3890-3343) ft.

Operator must run a CBL from 3890 ft., or as deep as possible, to verify cement top. Outside plugs will be required, based on CBL result. Submit electronic copy of the log for verification to the following BLM address: tsalyers@blm.gov

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.