(August 2007) DEPART	UNITED STATES MENT OF THE INTER OF LAND MANAGEM			FORM APPROVED OMB NO. 1004-0137 Expires July 31, 2010	
11 1				5., Lease Serial No.	
	ES AND REPORTS		SEP 22 2014	Jicarilla 67 6. If Indian, Allottee or Tribe Name	
Do not use this form abandoned well. Use I	Form 3160-3 (APD) fo	or to re-enter an r such proposals.s	forman F		
				Jicarilla Apache	
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit or CA/Agreement, Name and/or No		
1. Type of Well			RCUD DCT 7'14		
Oil Well X Gas Well Other			8. Well Name and No.		
2. Name of Operator			Jicarilla 67 5E		
ENERGEN RESOURCES CORPORATION				9. API Well No.	
3a. Address	3b. Phone No. (includ	le area code)	03-039-23969		
2010 Afton Place, Farmington, NM	505-325-68	00	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Sur			S. Blanco Pictured Cliffs		
1850' FSL, 1190' FEL, Sec. 29, T			DIST 3		
				11. County or Parish, State	
12. CHECK APPROPRI				Rio Arriba NM	
	ATE BOX(ES) TO IN		DF NOTICE, REPOR	RI, OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION			
X Notice of Intent	Acidize	Deepen	Production	(Start/Resume) Water Shut-Off	
	Alter Casing	Fracture Treat			
Subsequent Report					
	Casing Repair	New Construction			
Final Abandonment Notice	Change Plans	Y Plug and Abando			
	Convert to Injecti	ion Plug Back	Water Disp	osal	
13. Describe Proposed or Completed Operation (cl If the proposal is to deepen directionally or rec Attach the Bond under which the work will be following completion of the involved operation testing has been completed. Final Abandonm determined that the final site is ready for final it	omplete horizontally, give s e performed or provide the is. If the operation results i ent Notices shall be filed of	subsurface locations and Bond No. on file with Bl in a multiple completion	measured and true ver LM/BIA. Required su or recompletion in a n	tical depths of all pertinent markers and zones. bsequent reports shall be filed within 30 days ew interval, a Form 3160-4 shall be filed once	
Energen Resources plans to plug and abandon the Jicarilla 67 #5E per the attached procedure.					
This will be a closed loop ope	ration. NMOCD will	be notified 24	hrs prior to c	commencing operation.	
BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS					
			· · · · · · · · · · · · · · · · · · ·		
 I hereby certify that the foregoing is true and con Name (Printed/Typed) 	ect				
Kyle Mason Title District Engineer					
Signature Jule 30- Date 9/17/2014					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by Troy Salvers . Conditions of approval, if any, are attached Approval of this the applicant holds legal or equitable title to those rights in the entitle the applicant to conduct operations thereon.		tify that Office FFC	roleum En	a. 10 2 2014	
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 12 fictitious or fraudulent statements or representations as to an				ent or agency of the United States any false,	

NMO	CD	KC


Jicarilla 67 #5E

1

Today's Date: 8/20/14

Current Basin Dakota


1850' FSL, 1190' FEL, Section 29, T-25-N, R-5-W Rio Arriba County, NM, API #30-039-23969



Jicarilla 67 #5E

Proposed P&A Basin Dakota

1850' FSL, 1190' FEL, Section 29, T-25-N, R-5-W



TD 7200' PBTD 7151'

PLUG AND ABANDONMENT PROCEDURE

August 20, 2014

Jicarilla 67 #5E

Basin Dakota 1850' FSL and 1190' FSL, Section 29, T25N, R11W Rio Arriba County, New Mexico / API 30-039-23969 Lat: N _____/ Lat: W _____

- Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.
 - 1. This project will use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
 - Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
 - Rods: Yes____, No_X_, Unknown____. Tubing: Yes X_, No ____, Unknown____, Size <u>2-3/8</u>, Length <u>7032</u>, Packer: Yes X_, No ____, Unknown____, Type <u>Model R-3 D.G packer 6641</u>.
 If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.
 - 4. NOTE: BLM requires a CBL log to be run on all wells where the cement did not circulate to surface or CBL log was not previously run. This procedure is prepared with the understanding that it may be modified based on the TOC from the CBL.
 - Plug #1 (Dakota perforations and top, 6819' 6719'): Round trip gauge ring or casing scraper to 6819', or as deep as possible. RIH and set 4.5" cement retainer at 6819'. Pressure test tubing to 1000 PSI. Load casing with water and circulate well clean. Pressure test casing to 1000#. If the casings do not test, then spot or tag subsequent plugs as appropriate. Circulate well clean. Mix 12 sxs Class B cement inside casing from 6819' to isolate the Dakota interval. PUH.

See COA

6. Plug #2 (Gallup top, 5942' -5842'): Mix and pump 12 sxs Class B cement and spot a balanced plug inside casing to cover the Gallup top. PUH.

See COA

- 7. Plug #3 (Mancos top, 5065' 4965'): Mix and pump 12 sxs Class B cement and spot a balanced plug inside casing to cover the Mancos top. PUH.
- 8. **Plug #4 (Mesaverde top, 4260' 4160'):** Mix and pump 12 sxs Class B cement and spot a balanced plug inside casing to cover the Mesaverde top. PUH.

- 9. Plug #5 (Chacra top, 3530' 3430'): Mix and pump 12 sxs Class B cement and spot a balanced plug inside casing to cover the Chacra top. PUH
- Plug #6 (Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops,2678' 2062'): Mix and pump 51 sxs Class B cement and spot a balanced plug inside casing to cover through the Ojo Alamo top. TOH.

See COA

1

- 11. Plug #7 (Nacimiento top, 672' 572'): Perforate squeeze holes at 572'. Attempt to establish rate if the casing pressure tested. TIH and set CR at 622'. Mix and pump 51 sxs Class B cement, squeeze 39 sxs outside 4.5" casing and leave 12 sxs inside casing to cover Nacimiento. TOH.
- 12. Plug #8 (9-5/8" casing shoe and surface, 276' Surface): Perforate 3 squeeze at 276'. Establish circulation out bradenhead and casing valve. Mix 110 sxs Class B cement and pump down PC casing and circulate good cement out casing valve and bradenhead valve. SI well and WOC.
- 13. ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Jicarilla 67 #5E

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

3. The following modifications to your plugging program are to be made:

- a) Bring the top of plug #2 to 5779 ft. to cover the Gallup top. Adjust cement volume accordingly.
- b) Set plug #3 (5126-5026) ft. to cover the Mancos top.
- c) Set plug #7 (771-671) ft. inside/outside to cover the Nacimiento top.

Operator will run a CBL from 6819 ft., or as deep as possible, to verify cement top. <u>Outside plugs</u> <u>may be revised, based on CBL result</u>. Submit electronic copy of the log for verification to the following addresses: <u>tsalyers@blm.gov</u> <u>Brandon.Powell@state.nm.us</u>

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.