
1625 N. Fre <u>District II</u> – 811 S. First		State of New M	<b>lexico</b>		Form C
<u>District II</u> – 811 S. First	575) 393-6161 nch Dr., Hobbs, NM 88240	Energy, Minerals and Na		WELL API N	Revised August 1
	(575) 748-1283 St., Artesia, NM 88210	OIL CONSERVATIO	N DIVISION		30-019-20141
1000 Rio Rt	- (505) 334-6178 razos Rd., Aztec, NM 87410	1220 South St. Fra		5. Indicate T	
District IV -	- (505) 476-3460 Francis Dr., Santa Fe, NM	Santa Fe, NM	87505	6. State Oil &	& Gas Lease No.
(DO NOT U	ISE THIS FORM FOR PROPOSA	CES AND REPORTS ON WELL ALS TO DRILL OR TO DEEPEN OR P ATION FOR PERMIT" (FORM C-101)	LUG BACK TO A		ne or Unit Agreement Na o Ranch
PROPOSAL	.\$.)	Gas Well 🔽 Other		8. Well Num	iber 033F
	of Operator	Services, LP		9. OGRID N	umber 295752
3. Addre	ss of Operator 15021 Katy	Freeway, Suite 400 Houston, T	X 77094	10. Pool nam	ne or Wildcat ervo Hill; Pennsylvanian
4. Well I	ocation				
	Jnit Letter F :	2252 feet from the Nor			t from the West
S. Administra	Section 33	Township 11N   11. Elevation (Show whether D	Range 23E	NMPM	County Guadalur
	· · · · · · · · · · · · · · · · · · ·	4755' GR	11, 1412, 111, 011, 01	,	
DOWNHO	DLE COMMINGLE FI			NT JOB [	_
	DLE COMMINGLE	П			_
OTHER:	escribe proposed or compless starting any proposed wor	eted operations. (Clearly state alk). SEE RULE 19.15.7.14 NM	OTHER:	and give pertinent	
OTHER: 13. D of pr	escribe proposed or comple starting any proposed wor oposed completion or reco	k). SEE RULE 19.15.7.14 NM/mpletion. 83-F Proposed P&A Procedure	OTHER: Il pertinent details, a	and give pertinent Completions: Atta	
OTHER: 13. D of pr Alta Mes 1. 2.	escribe proposed or complete starting any proposed wor oposed completion or recomposed completion or recomposed services. LP Latigo Ranch 3 MI&RU wireline truck, etc. to Run gamma ray, ccl & junk b	k). SEE RULE 19.15.7.14 NM/mpletion.  33-F Proposed P&A Procedure dump bail cement and set CIBP's in pasket to check PBTD at +/-17,320'.	OTHER: Il pertinent details, a AC. For Multiple C	and give pertinent Completions: Atta duction casing.	ach wellbore diagram of
OTHER:  13. D of pr  Alta Mes 1. 2. 3. 4.	escribe proposed or complete starting any proposed wor roposed completion or recomposed completion or recomposed services. LP Latigo Ranch 3 MI&RU wireline truck, etc. to Run gamma ray, ccl & junk to PU cement bailer and make PU & GIH with CIBP and set	k). SEE RULE 19.15.7.14 NM/mpletion.  33-F Proposed P&A Procedure dump bail cement and set CIBP's in basket to check PBTD at +/-17,320'. multiple runs to fill from PBTD to 17, at 17,100' and dump 10' cement on	OTHER:  Il pertinent details, a AC. For Multiple C  the 5.5" 20.0 ppf proc  110' to cover all existitop.	and give pertinent Completions: Atta duction casing. ng perforations.	
OTHER:  13. D of pr  Alta Mes 1. 2. 3. 4. 5. 6.	escribe proposed or complete starting any proposed work opposed completion or recomplete seasons. LP Latigo Ranch 3 MI&RU wireline truck, etc. to Run gamma ray, ccl & junk be PU cement bailer and make PU & GIH with CIBP and set	k). SEE RULE 19.15.7.14 NM/mpletion.  33-F Proposed P&A Procedure dump bail cement and set CIBP's in basket to check PBTD at +/-17,320'. multiple runs to fill from PBTD to 17, at 17,100' and dump 10' cement on at 7,950' and dump 10' cement on to at 1,500' and dump 10' cement on to	OTHER:  Il pertinent details, a AC. For Multiple C  the 5.5" 20.0 ppf proc  110' to cover all existitop.  op, adjacent to interme	and give pertinent Completions: Atta duction casing. ng perforations. ediate shoe.	ach wellbore diagram of
OTHER:  13. D of pr  Alta Mes 1. 2. 3. 4. 5. 6. 7. 8.	escribe proposed or completion or reconstanting any proposed work oposed completion or reconstantial services. LP Latigo Ranch of MI&RU wireline truck, etc. to Run gamma ray, ccl & junk to PU cement bailer and make PU & GIH with CIBP and set RD & demob all wireline equ	k). SEE RULE 19.15.7.14 NM/mpletion.  33-F Proposed P&A Procedure dump bail cement and set CIBP's in basket to check PBTD at +/-17,320'. multiple runs to fill from PBTD to 17, at 17,100' and dump 10' cement on at 7,950' and dump 10' cement on to at 1,500' and dump 10' cement on to at 35' and dump 30' cement on top. ipment.	OTHER: Il pertinent details, a AC. For Multiple Control of the 5.5" 20.0 ppf process In the 5.5" 20.0 ppf process It to p. It to	and give pertinent Completions: Atta duction casing. ng perforations. ediate shoe.	ach wellbore diagram of
OTHER:  13. D of pr  Alta Mes 1. 2. 3. 4. 5. 6. 7.	escribe proposed or complete starting any proposed work oposed completion or recomplete sa Services, LP Latigo Ranch and Mi&RU wireline truck, etc. to Run gamma ray, ccl & junk to PU cement bailer and make PU & GIH with CIBP and set RD & demob all wireline equ Weld ½" steel plate with dry Restore location to natural te	k). SEE RULE 19.15.7.14 NM/mpletion.  33-F Proposed P&A Procedure dump bail cement and set CIBP's in basket to check PBTD at +/-17,320'. multiple runs to fill from PBTD to 17, at 17,100' and dump 10' cement on at 7,950' and dump 10' cement on to at 1,500' and dump 10' cement on to at 35' and dump 30' cement on top. ipment. hole marker pipe per New Mexico's retrain.	OTHER: Il pertinent details, a AC. For Multiple Control of the 5.5" 20.0 ppf process In the 5.5" 20.0 ppf process It to p. It to	and give pertinent Completions: Atta duction casing. ng perforations. ediate shoe.	ach wellbore diagram of
OTHER:  13. D of pr  Alta Mes 1. 2. 3. 4. 5. 6. 7. 8. 9. 10.	escribe proposed or completion or recompletion of recompletion of recompletion or recompletion	k). SEE RULE 19.15.7.14 NM/mpletion.  33-F Proposed P&A Procedure dump bail cement and set CIBP's in basket to check PBTD at +/-17,320'. multiple runs to fill from PBTD to 17, at 17,100' and dump 10' cement on at 7,950' and dump 10' cement on to at 1,500' and dump 10' cement on to at 35' and dump 30' cement on top. ipment. hole marker pipe per New Mexico's retrain.  VBS****	OTHER: Il pertinent details, a AC. For Multiple Control of the 5.5" 20.0 ppf process In the 5.5" 20.0 ppf process It top. It to cover all existing top, adjacent to intermed pp, adjacent to surface requirements.	and give pertinent Completions: Atta duction casing. ng perforations. ediate shoe.	ach wellbore diagram of
OTHER:  13. D of pr  Alta Mes 1. 2. 3. 4. 5. 6. 7. 8. 9. 10.	escribe proposed or completion or recompletion of recompletion of recompletion of recompletion or recompletion	k). SEE RULE 19.15.7.14 NM/mpletion.  33-F Proposed P&A Procedure dump bail cement and set CIBP's in basket to check PBTD at +/-17,320'. multiple runs to fill from PBTD to 17, at 17,100' and dump 10' cement on at 7,950' and dump 10' cement on to at 1,500' and dump 10' cement on to at 35' and dump 30' cement on top. ipment. hole marker pipe per New Mexico's retrain.	OTHER: Il pertinent details, a AC. For Multiple Control of the 5.5" 20.0 ppf process In the 5.5" 20.0 ppf process It top. It to cover all existing top, adjacent to intermed pp, adjacent to surface requirements.	and give pertinent Completions: Atta duction casing. ng perforations. ediate shoe.	ach wellbore diagram of

#### Proposed P&A Wellbore Schematic

# Alta Mesa Services, LP. Latigo Ranch 33-F Cuervo Field Guadalupe County, NM KB = 4,787

Hole Sizes and Depths

Casing Sizes, etc.



## Lithology

Wellsite elevation is 4755' (KB = 4785')

Significant Formation Tops	Drill Depth	Subsea Depth
Santa Rosa	965	3820
San Andres	1630	3155
Glorietta	2015	2770
Yeso	2380	2405
Abo	3560	1225
Hueco	4427	358
Pennsylvanian	5986	-1201
Mississippian	17310	-12525
Basement	Not Penetrated	Not Penetrated

### State of New Mexico Energy, Minerals and Natural Resources Department

Governor

David Martin
Cabinet Secretary

Brett F. Woods, Ph.D. Deputy Cabinet Secretary Jami Bailey, Division Director Oil Conservation Division



## Conditions of Approval Attachment Page

#### Well information:

API WELL#	Well Name	Well #	Operator Name	Туре	Stat	County	Surf_Owner	UL	Sec	Twp	N/S	Rng	W/E
30-019-20141-00-	LATIGO	033F	ALTA MESA SERVICES,	G	Т	Guadalupe	P	F	33	11	N	23	Е
00	RANCH		LP			·							

Applic	ation Type:	☐ Drilling/Casing Change ☐ Location Change
	Recor	mplete/DHC (For hydraulic fracturing operations review EPA linjection control Guidance #84)
	Other	·
Condit	ions of Approv	al:

Notify NMOCD 24hrs prior to beginning operations, casing & cement

Add an inside/outside plug for the Santa Rosa formation from 915-1015 Add an inside/outside plug for the San Andres formation from 1580-1680 Add an inside/outside plug for the Glorietta formation from 1965-2065

Add an inside/outside plug for the Giorietta formation from 1905-200

Add an inside/outside plug for the Yeso formation from 2330-2430 Add an inside/outside plug for the Abo formation from 3510-3610

Add an inside/outside plug for the Hueco formation from 4377-4477

Add an inside/outside plug for the Pensylvanian formation from 5936-6036

Add an inside/outside plug for the 8950-9050

Add an inside/outside plug for the 11950-12050

Add an inside plug from 14950-15050

Convert plug at 7950 to an inside/outside plug from 7900-8000 Convert plug at 1500 to an inside/outside plug from 1450-1500 Convert plug at 35 to an inside/outside plug from 0-50

All inside plugs require 50% excess cement All outside plugs require 100% excess cement