Form 3160-5 (August 2007)	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010		
Do not use	DRY NOTICES AND REPORTS this form for proposals to dri		5. Lease Serial No. SF-080668 6. If Indian, Allottee or Tribe Name			
abandoned	well. Use Form 3160-3 (APD)	for such proposa	ils. 🥠			
	BMIT IN TRIPLICATE - Other instruction		2 20	7. If Unit of CA/Agreement, Na		
1. Type of Well Oil Well	Gas Weil Other	T ADM	3 ZU	8. Well Name and No.	uan 27-4 Unit	
		TE CARDINE!	Chall		n 27-4 Unit 94P	
2. Name of Operator						
3a. Address	ton Resources Oil & Gas Com		30-039-30847 10. Field and Pool or Exploratory Area			
3a. Address3b. Phone No. (include area code)10. Field and PooPO Box 4289, Farmington, NM 87499(505) 326-970010. Field and Poo					Blanco MV / Basin DK	
-	Sec. 3, T 27N, R4 Sec. 3, T 27N, R4					
	THE APPROPRIATE BOX(ES) TO I			TICE, REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION TYPE OF ACTION						
X Notice of Intent	Acidize	Deepen	Пр	roduction (Start/Resume)	Water Shut-Off	
)		racture Treat		eclamation	Well Integrity	
Subsequent Report	Casing Repair	Jew Construction	R	ecomplete	· Other	
h	Change Plans	lug and Abandon	Т	emporarily Abandon	Plug Back the	
Final Abandonment Notice	Convert to Injection X P peration: Clearly state all pertinent details, inc	lug Back		Vater Disposal	Dakota Formation	
determined that the site is ready for final inspection.) Burlington Resources Oil & Gas Company LP requests permission to trip out of hole with TBG and plug back the dakota formation. The procedure, current & proposed well bore schematics are attached. A closed loop system will be utilized for this plug back.						
	OIL CONS. DIV DIST.	\$				
	DEC 04 2014	OCD 24 hrs eginning	ACTIO OPER AUTH	S APPROVAL OR ACCEPT ON DOES NOT RELIEVE ATOR FROM OBTAINING IORIZATION REQUIRED EDERAL AND INDIAN LA	THE LESSEE AND G ANY OTHER FOR OPERATIONS	
14. I hereby certify that the foregoing is	true and correct. Name (Printed/Typed)				<u></u>	
Kenny Davis	· · · · · · · · · · · · · · · · · · ·	Title Staff Regulatory Technician				
			11/13/2014			
Signature Date						
	THIS SPACE FOR FE	EDERAL OR STA		FICE USE		
	hed. Approval of this notice does not warran	t or certify	itle PF	<u> </u>	Date 12 2 2014	
that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any						
	43 U.S.C. Section 1212, make it a crime for a or representations as to any matter within its		l willfully	to make to any department or ag	ency of the United States any	
(Instruction on page 2) NINCO A						

. 0 .

.

ConocoPhillips SAN JUAN 27-4 UNIT 94P Expense - Plugback

Lat: 36° 35' 46.344" N

Long: 107°14' 35.154" W

PROCEDURE

1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig. Notify BLM and NMOCD prior to beginning operations.

2. MIRU workover rig. Check casing, tubing, and bradenhead pressures and record them in Wellview. If there is pressure on the BH, contact Wells Engineer.

3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCI as necessary. Ensure well is dead or on vacuum.

4. ND wellhead and NU BOPE. Pressure and function test BOP to 250 psi low and 1000 psi over SICP high to a maximum of 2000 psi held and charted for 10 minutes as per COP Well Control Manual. PU and remove tubing hanger. Record pressure test in Wellview.

5. RU Tuboscope Unit to inspect tubing. TOOH with tubing (per pertinent data sheet). LD and replace any bad joints and record findings in Wellview. Make note of corrosion, scale, or paraffin and save a sample to give to the Wells Engineer for further analysis.

6. RU wireline with packoff and wireline BOP and run GR to the top of the Dakota perfs @ 8144'. TOOH with wireline. If fill is encountered, TIH with bit and mill and clean out to 8144' using air package.

7. Set CIBP @ 8094' on wireline. TOC @ 3100' per CBL on 8/31/2011.

2366'

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Class B mixed at 15.6 ppg with a 1.18 cf/sk yield. \checkmark

8. Plug 1 (Dakota and Graneros Formation Tops, 7994'-8094', 12 Sacks Class B Cement)

Mix 12 sx Class B cement and place a plug inside the casing to cover the Dakota and Graneros formation tops. POOH.

9. TIH with tubing using Tubing Drift Procedure (detail below).

		Tubing and BHA Description			
Tubing Wt/Grade:	4.7#, J-55	1 2-3/8" Expendable Check			
Tubing Drift ID:	1.901"	1 2-3/8" (1.78" ID) F-Nipple			
		1 2-3/8" Tubing Joint			
Land Tubing At:	6142'	. 1 2-3/8" Pup Joint (2' or.4')			
KB:	15'	+/- 192 2-3/8" Tubing Joints			
		As Needed 2-3/8" Pup Joints			
		1 2-3/8" Tubing Joint			

10. Ensure barriers are holding. ND BOPE, NU Wellhead. Pressure test tubing slowly with an air package as follows: pump 3 bbls pad, drop steel ball, pressure tubing up to 500 psi, and bypass air. Monitor pressure for 15 mins., then complete the operation by pumping off the expendable check. Note in Wellview the pressure in which the check pumped off. Purge air as necessary. Notify the MSO that the well is ready to be turned over to Production Operations. RDMO.

Tubing Drift Check

PROCEDURE

1. Set flow control in tubing. With air, on location, use expendable check. With no air on location, use wire line plug.


2. RU drift tool to a minimum 70' line. Drift tool will have an OD of at least the API drift specification of 1.901" for the 2 3/8",4.7# tubing, and will be at least 15" long. The tool will not weigh more than 10# and will have an ID bore the length of the tool, so fluids may be pumped through the tool if it becomes stuck.

3. Drop the tool into the tubing string and retrieve it after every 2 joints of tubing ran in hole. If any resistance to the tool movement is noticed, going in or out, that joint will be replaced.

NOTE: All equipment must be kept clean and free of debris. The drift tool will be measured with calipers before each job, to ensure the OD is the correct size for the tubing being checked. The maximum allowable wear of the tool is 0.003".


OIL CONS. DIV DIST. 3

DEC 042014



OIL CONS. DIV DIST. 3

DEC 0 4 2014



Ł