

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0137
Expires July 31, 2010DEC 03 2014
SUNDY NOTICES AND REPORTS ON WELLSDo not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

XTO ENERGY INC.

3a. Address

382 CR 3100 AZTEC, NM 87410

3b. Phone No. (include area code)

505-333-3100

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1345' FNL & 1115' FWL SWNW SEC. 29 (E) - T29N-R13W N.M.P.M.

5. Lease Serial No.

NMSF-079065

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

FRPC 29 #2

9. API Well No.

30-045-31242

10. Field and Pool, or Exploratory Area

BASIN FRUITLAND COAL

11. County or Parish, State

SAN JUAN

NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☒ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

XTO Energy Inc. intends to plug and abandon this well per the attached procedure and will be using a Closed Loop System. Please see attached current and proposed wellbore diagrams and surface reclamation plan. Please note that per the Surface Reclamation Plan item 8.1) Due to the Dunes Recreation Area Location a Below Grade Marker will be installed under the direction of the BLM FFO.

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

RECEIVED

JAN 23 2015

NMOCD
DISTRICT III

Notify NMOCD 24 hrs
prior to beginning
operations

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

KRISTEN D. BABCOCK

Title REGULATORY ANALYST

Signature

Kristen D. Babcock

Date 12/3/2014

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Troy Salvors

Title

PE

Date

1/20/2015

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FFO

NMOCD
KC

FRPC 29 #2
Sec 29, T 29 N, R 13 W
San Juan County, New Mexico
10/23/2014

Plug and Abandon Procedure

AFE Number: 1409495
Spud Date: 5/3/2003
Surface Casing: 7", 17#, H-40 csg @ 126'. Cmt'd w/50 sx. Circ 4 bbls cmt to surf.
Production Casing: 4-1/2", 10.5#, J-55 csg @ 1,349'. Cmt'd w/160 sx. Circ 14 bbls cmt to surf.
Capacity: .0159 bbls/ft or .6699 gal/ft
Production Tubing: 2-3/8" string
Rod String: 3/4" string
Pump: 1-1/2" insert pump
Perforations: Fruitland Coal: 1,028' – 1,145'
PBTD: 1,331'
Recent Production: INA since 8/28/2014. 12 mcfpd, 0 bwpd (downhole failure).

Notify NMOCD & BLM 24 hours prior to beginning plugging operations

1. Check for COA's and approved NOI before beginning operations.
2. Test rig anchors.
3. Set flowback tank.
4. MIRU completion rig. Review JSA.
5. Kill well.
6. TOH & LD rods and pump.
7. ND WH. NU & FT BOP.
8. TOH tubing.
9. TIH 3-7/8" bit & 3-7/8" string mill to 1,028'. TOH.
10. TIH 4-1/2" CR and set @ $\pm 1,020'$. PT tubing. Sting out of CR and circulate hole clean.

11. PT casing and CR to 550 psig. If casing does not test, contact engineer.
12. MIRU cement truck. Review JSA.
13. **Perforation Isolation Plug (1,020' – 970')**: Pump 12 sx Class "B" cement (15.6 ppg, 1.18 cuft/sx yield) down tubing and spot a balanced plug from 1,020' – 970' (volume calculated with 50' excess).
See COA
14. **Surface Plug (176' – Surface)**: Pump 26 sx Class "B" cement (15.6 ppg, 1.18 cuft/sx yield) down tubing and spot a balanced plug from 176' – Surface (volume calculated with 50' excess).
15. TOH & LD tubing.
16. RDMO cement truck.
17. WOC 4 hours.
18. Cut off WH. Fill in casing as needed with cement. Install above ground P&A marker.
19. Cut off anchors and reclaim location.

Checklist

Regulatory:

1. NOI to P&A on form C-103 & 3160-5
2. Submit a post-work sundry on form C-103 & 3160-5 which details the P&A work and location work within 30 days of completing all required restoration work.

Equipment:

1. 1 flowback tank
2. If tbg does not PT, 2,000' 2-3/8" workstring
3. 4-1/2" cement retainer
4. 3-7/8" string mill
5. 38 sx Class "B" cement
6. 1 above ground marker

Services:

1. Completion rig
2. Cement truck