Form 3160-5 (August 2007)

entitle the applicant to conduct operations thereon.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELL	SUNDRY	NOTICES	AND	REPORTS	ON	WELLS
------------------------------------	--------	---------	-----	----------------	----	-------

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED OMB NO. 1004-0137 Expires July 31, 2010

5. Lease Serial No.

NMNM-2204	6
-----------	---

6. If Indian, Allottee or Tribe Name

	ri.	, 100 chr ===	NAVAJO SURFACE
SUBMIT IN TRIPLICATE - Oth	ner instructions on p	age 2.	7. If Unit or CA/Agreement, Name and/or No
1. Type of Well Oil Well X Gas Well Other 2. Name of Operator XTO ENERGY INC. 3a. Address 382 CR 3100 AZTEC, NM 87410 4. Location of Well (Footage, Sec., T., R., M., or Survey Description 2482' FSL & 1413' FWL NESW Sec. 7 (K) -T	3b. Pho 5 on)	OFC 22 2014 C. M. A.	10. Field and Pool, or Exploratory Area BASIN FRUITLAND COAL 11. County or Parish, State
12. CHECK APPROPRIATE BOX(ES) TO INDICATE	NATURE OF NOTICE REP	SAN JUAN NM ORT OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTION	
■ Subsequent Report ■ Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Fracture Treat Reclamat New Construction Recomp	ete Other
Attach the Bond under which the work will be performed of following completion of the involved operations. If the ope testing has been completed. Final Abandonment Notices of determined that the final site is ready for final inspection.) XTO Energy Inc. has plugged and abandor was used, all liquid waste was taken to	eration results in a multiphall be filed only after a multiphall be multiphall be filed only after a multiphall be filed only after	ole completion or recompletion in a ill requirements, including reclamat the attached summary i	new interval, a Form 3160-4 shall be filed once ion, have been completed, and the operator has
Approved as to plugging of the well bore. Liability under bond is retained until surface restoration is completed.	FEB 1 S	2 2015 2 CD	FEB 0 6 2015 FARMINGTON FIELD OFFICE BY: To Salvers
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) KRISTEN D. BABCOCK Signature	Tit	tle REGULATORY ANALY	ST
1 Justin D. Datocock		OR STATE OFFICE USE	
Approved by	T. OKI LULIVAL	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not the applicant holds legal or equitable title to those rights in the subject lease		Office	

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

XTO Energy Inc.

Gallegos Federal 26-12-7 #1

December 12, 2014

Page 1 of 1

2482' FSL and 1413' FWL, Section 07, T-26-N, R-12-W San Juan County, NM Lease Number: NMNM-22046

API #30-045-28899

Notified NMOCD and BLM on 12/10/2014

Plug and Abandonment Summary:

Plug #1 with 32 sxs (37.76 cf) Class B cement in side casing from 1095'-760' to cover the Fruitland Coal top√

Plug #2 with 29 sxs (34.22 cf) Class B cement from 218' – surface circulate good cement out casing to cover the casing shoe and surface. ✓

Plug #3 with 24 sxs Class B cement top off casings and install P&A Marker at 36° 30′ 8″ N / 108° 9′ 24″ W.

Plugging Work Details

12/10/14 Rode rig and equipment to location and spot. SDFD.

RU and spot in. Check well pressures: tubing and casing 15 PSI, BH 0 PSI. Blow down well. Pressure test tubing to 800 PSI, held ok. X-Over to rod tools. LD rods. X-Over to 2-3/8" tools. Pump 15 bbls of fresh water down tubing to kill well. ND WH. Screw on A-Plus 8-5/8" companion flange. POOH and tally 18 stands. PU string mill. TIH to 1130'. LD string mill. TIH and set CR at 1095'. Attempt to pressure test tubing, no test. Sting out of CR. Pump and circulate casing clean with 20 bbls of water. Pressure test to 800 PSI, held ok for 15 minutes. Attempt to pressure test BH, water sprayed out of ground. Dig out WH and 7" casing. Found a leak at bottom of 7" collar. Attempt to pressure test, no test. POOH with 15 joints, found multiples holes on joint #16. Pressure test tubing to 1000 PSI, held ok. TIH with 7 stands. Pressure test tubing to 1000 PSI, held ok. POOH with 16 stands. LD standing valve and setting tool. PU notch collar and TIH with 17 stands. SI Well. Note: Dustin Porch, BLM, approved to cut off WH. SDFD.

12/12/14 Check well pressures: 0 pressures on well. Open up well. Change out to A-Plus MYT elevators. Pump 5 bbls of water into casing. Spot Plug #1. Pump 2 bbls of water into casing. Spot Plug #2. LD 7 joints. Change out elevators. RD rig. Dig out WH. HSM with High Desert. Cut off WH. Spot Plug #3 and install P&A Marker at 36° 30′ 8″ N / 108° 9′ 24″ W. Note: Found cement in 4-1/2″ casing 19′ down and in 4-1/2″ X 7″ casing 38′ down. RD equipment and MOL.

Dustin Porch, BLM representative, was on location.