Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
District I – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		30-043-21198	
<u>District III</u> – (505) 334-6178	istrict III - (505) 334-6178 1220 South Scherage Drift III		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	00 Rio Brazos Rd., Aztec, NM 87410		STATE FEE  6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		ST NM V-1697, ST NM LG-3924	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well: Oil Well Gas Well Other OIL CONS. DIV DIST. 3			7. Lease Name or Unit Agreement Name Lybrook P32-2307 8. Well Number 01H
2. Name of Operator Encana Oil & Gas (USA) Inc.		9. OGRID Number 282327	
3. Address of Operator NOV 0 5 2014		10. Pool name or Wildcat	
370 17th Street, Suite 1700 Denvel	r. CO 80202		Alamito-Gallup
4. Well Location			
Unit Letter P: 664 feet from the SOUTH line and 31 feet from the EAST line			
Section 32 Township 23N Range 7W NMPM County SANDOVAL  11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
6874' GR			
。			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
12. Check repropriate Box to indicate retained involves, report of Other Bata			
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASIN COMMENCE DRILLING OPNS.   P AND A CASING/CEMENT JOB   CLOSED-LOOP SYSTEM   COMMENCE DRILLING OPNS.   P AND A CASING/CEMENT JOB   CASING/CEMENT JOB			K ☐ ALTERING CASING ☐ LLING OPNS.☐ P AND A ☐
OTHER:		OTHER: Completi	ions 🛛
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
Please see attached sheet detailing completion operations occurring between 10/07/14 – 11/02/14.			
	·		
Ŕ			
<i>;</i>			
			11 1. C
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE CLOST DALLER TITLE Operations Technician DATE 11/3/14			
Type or print name Cristi Bauer	E-mail address: Cristi.Bauer@e	encana.com PH	IONE: 720-876-5867
For State Use Only			
0//	· //		SINSPECTOR
APPROVED BY:	TITLE	DISTRICT	#3 DATE 11/7/14
Conditions of Approval (if any):	P		•

# Lybrook P32-2307 01H API: 30-043-21198

#### 10/7/14

- Set plug @ 9,573'.
- Perforated stage #1: 9346'-9526', 36 holes.

### 10/8/14

- Frac stage #1: 30Q N2 foam 25# XL gel, 1958 bbls Fresh H2O, 267,660 #s of 20/40, 25,748 #s of 16/30, Total N2=332,100 Mscf.
- Pull up and perf stage #2 as follows, 9044'-9222', 36 holes.
- Pump 50 Bio-balls to seal off stage #1.
- Frac stage #2: 30Q N2 foam 25/20# XL gel, 1832 bbls Fresh H2O, 276,500 #s of 20/40, 22,932 #s of 16/30, Total N2 =285,600 Mscf.
- Set CFP @ 8930' to seal off stage #2.
- Pull up and perf stage #3 as follows, 8700'-8880', 36 holes.
- Frac stage #3: 30Q N2 foam 20# XL gel, 1591 bbls Fresh H2O, 276,620 #s of 20/40, 25,800 #s of 16/30, Total N2 =251,400 Mscf.
- Pull up and perf stage #4 as follows, 8345'-8525', 36 holes.
- Pump 50 Bio Balls to seal off stage #3.
- Frac stage #4: 30Q N2 foam 18# XL gel, 1800 bbls Fresh H2O, 272,000 #s of 20/40, 25,820 #s of 16/30, Total N2 =284,300 Mscf.
- Set CFP @ 8214' to seal off stage #4.
- Pull up and perf stage #5 as follows, 7987'-8167', 36 holes.
- Frac stage #5: 30Q N2 foam 18# XL gel, 1741 bbls Fresh H2O, 271,016 #s of 20/40, 24,580 #s of 16/30, Total N2 =263,100 Mscf.
- Pull up and perf stage #6 as follows, 7638'-7818', 36 holes.
- Pump 50 Bio Balls to seal off stage #5.

## 10/9/14

- Frac stage #6: 30Q N2 foam 18# XL gel, 1847 bbls Fresh H2O, 272,780 #s of 20/40, 24,560 #s of 16/30, Total N2 =305,600 Mscf.
- Set CFP @ 7510' to seal off stage #6.
- Pull up and perf stage #7 as follows, 7282'-7462', 36 holes.
- Frac stage #7: 30Q N2 foam 18# XL gel, 1711 bbls Fresh H2O, 269,360 #s of 20/40, 26,137 #s of 16/30, Total N2=261,500 Mscf.
- Pull up and perf stage #8 as follows, 6926'-7106', 36 holes.
- Pump 50 Bio Balls to seal off stage #7.
- Frac stage #8: 30Q N2 foam 18# XL gel, 1746 bbls Fresh H2O, 271,860 #s of 20/40, 24,880 #s of 16/30, Total N2 = 267,300 Mscf.
- Pull up and perf stage #9 as follows, 6576'-6756', 36 holes.
- Drop 50 bio balls to seal off stage #8
- Frac stage #9: 30Q N2 foam 18# XL gel, 1745 bbls Fresh H2O, 271,016 #s of 20/40, 24,580 #s of 16/30, Total N2 =263,100 Mscf.
- Pull up and perf stage #10 as follows, 6231'-6411', 36 holes.
- Pump 50 Bio Balls to seal off stage #9.

#### 10/10/14

- Frac stage #10 30Q N2 foam 18# XL gel, 1685 bbls Fresh H2O, 268,048 #s of 20/40, 25,030 #s of 16/30, Total N2 =272,000 Mscf.
- Set CFP @ 6110' to seal off stage #10.
- Pull up and perf stage #11 as follows, 5885'-6065', 36 holes.
- Frac stage #11: 30Q N2 foam 18# XL gel, 2216 bbls Fresh H2O, 238,127 #s of 20/40, Total N2=408,000 Mscf.
- Pull up and perf stage #12 as follows, 5537'-5717', 36 holes.
- Pump 50 Bio Balls to seal off stage #11.
- Frac stage #12: 30Q N2 foam 18# XL gel, 1663 bbls Fresh H2O, 269,940 #s of 20/40, 29,922 #s of 16/30, Total N2=253,000 Mscf.
- Set CFP @ 5418' to seal off stage #12.
- Pull up and perf stage #13 as follows, 5193'-5373', 36 holes.
- Frac stage #13: 30Q N2 foam 18# XL gel, 1800 bbls Fresh H2O, 274,360 #s of 20/40, 28,394 #s of 16/30, Total N2 =272,000 Mscf.
- Set kill plug @ 4850'.

# 10/28/14

- Mill out kill plug @ 4850'
- Set composite bridge plug @ 5031'

## 10/30/14

Mill out composite bridge plug @ 5031', cfp @ 5418'.

#### 10/31/14

Mill out cfp @ 6110'.

## 11/1/14

Mill out cfp @ 7510'.

## 11/2/14

Mill out cfp @ 8214', 8930'.

Tubing details will be provided on a subsequent sundry.