Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

_	_					-		-
 E	ΧĮ	эіге	s:	Ju	ıly	3	1,	2

ase bellal Ivo.	
	NM-0546

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
shandanad wall. Usa Form 2460 2 (ABD) for such proposals

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe N	Jame .	
SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well				7. If Unit of CA/Agreement, N	ame and/or No.	
···				8 Well Damelatië No.	C WN Federal 13	
2. Name of Operator	ConocoPhillips Compa	anv .	1,	O API Well-No	45-34104	
3a. Address	3b. Phone No. (include are	a code)	10. Field and Pool or Exploratory Area			
PO Box 4289, Farmingto	n, NM 87499	(505) 326-9	700	Basin	Fruitland Coal	
4. Location of Well (Footage, Sec., T.,R., Surface Unit P (SE	EL, Sec. 14, T30N, I	R13W	11. Country or Parish, State San Juan	, New Mexico		
12. CHECK TI	HE APPROPRIATE BOX(ES)	TO INDICATE NATU	RE OF NO	TICE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION		TYF	PE OF AC	TION		
X Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	R	roduction (Start/Resume) eclamation	Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair	New Construction	=	ecomplete	Other	
Final Abandonment Notice	Change Plans Convert to Injection	X Plug and Abandon Plug Back	=	emporarily Abandon Vater Disposal		
ACTION DOES NOT I OPERATOR FROM O AUTHORIZATION RE ON FEDERAL AND IN	Abandonment Notices must be filed of final inspection.) Is permission to P&A the state of the Maddo of the M	subject well per the bx C WN Federal Co	e attachedom 1E (30 VED) 2015	mation, have been completed at d procedure, current a 04526617), a produci Notify NA prior to	and proposed wellbore ng well. A Closed MOCD 24 hrs beginning rations	
14. I hereby certify that the foregoing is t	rue and correct. Name (Printed/Typ		ff Degulat	ory Technician		
Dollie L. Busse	Title Sta	Title Staff Regulatory Technician				
Signature Mulie	Date 2	Juli	5			
	THIS SPACE FO	OR FEDERAL OR S	TATE OF	ICE USE		
Approved by						
Conditions of approval, if any, are attached that the applicant holds legal or equitable entitle the applicant to conduct operation.	title to those rights in the subject least thereon.	ase which would	Title Prooffice P	Fo	Date 2/13/2015	
Title 18 U.S.C. Section 1001 and Title 43	3 U.S.C. Section 1212, make it a crin	ne for any person knowingly	and willfully	to make to any department or as	gency of the United States any	

(Instruction on page 2)

ConocoPhillips MADDOX C WN FEDERAL 13 Expense - P&A

Lat 36° 48' 32.681" N

Long 108° 10' 9.156" W

PROCEDURE

This project requires the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig. Notify BLM and NMOCD prior to beginning work.
- 2. MIRU workover rig. Check casing, tubing, and bradenhead pressures and record them in Wellview. If there is pressure on the BH, contact the Wells Engineer.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure. Kill well as necessary. Ensure well is dead or on a vacuum.
- 4. TOOH w/ rod string and LD (per pertinent data sheet).

Size:

3/4"

Set Depth:

1.866

ft

- 5. ND wellhead and NU BOPE. Pressure and function test BOP to 250 psi low and 1000 psi over SICP high to a maximum of 2000 psi held and charted for 10 minutes as per COP Well Control Manual. PU and remove tubing hanger
- 6. TOOH with tubing (per pertinent data sheet).

Tubing size:

2-3/8"

4.7# J-55 EUE

Set Depth:

1885

ftKB

KB:

11

ft

7. PU 3-3/4" bit and watermelon mill and round trip as deep as possible to PBTD @ 2010'.

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Class B mixed at 15.6 ppg with a 1.18 cf/sk yield.

8. Plug 1 (Lewis and Pictured Cliffs Formation Tops, 1838-2010', 17 Sacks Class B Cement)

TIH. Mix 17 sx Class B cement and spot a balanced plug inside the casing to cover the Lewis and Pictured Cliffs Tops. PUH. WOC and tag.

- 9. PU 4-1/2" CR on tubing, and set @ 1746'. Pressure test tubing to 1000 psi. Sting out of CR. Load hole, and pressure test casing to 800 psi. If casing does not test, then spot or tag subsequent plugs as appropriate. POOH w/ tubing.
- 10. RU wireline and run CBL with 500 psi on casing from CR to surface to identify TOC. Adjust plugs as necessary for new TOC.


11. Plug 2 (Fruitland Coal Formation Top, 1150-1746', 50 Sacks Class B Cement)

Mix 50 sx Class B cement and spot a balanced plug inside the casing to cover the Fruitland Top. PUH.

12. Plug 3 (Kirtland and Ojo Alamo Formation Tops and Surface Plug, 0-458', 39 Sacks Class B Cement)


Connect the pump line to the bradenhead valve and attempt to pressure test the BH annulus to 300 psi. Note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix 39 sx Class B cement and spot balanced plug inside casing from 458' to surface, circulating good cement out casing valve. TOOH and LD tubing. SI well and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface, filling the casing and the BH annulus to surface. Shut well in and WOC.

13. Nipple down BOP and cut off casing below the casing flange. Install P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.



ConocoPhillips

Proposed_Schematic



Page 1/1

Report Printed: 10/20/2014

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:	Re: Permanent Abandonment Well: Maddox C WN Federal #13
Abandonment of Wells on Federal and Inc	
(505) 564-7750.	ast 24 hours before the plugging operations commence
Operator will run a CBL to verify cement top the following addresses: tsalyers@blm.gov	 Submit the electronic copy of the log for verification to v <u>Brandon.Powell@state.nm.us</u>

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.