Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No.

SF-080844

	DRY NOTICES AND REPO	6. If Indian, Allottee or Tribe Name			
Do not use	e this form for proposals t	to drill or to re-enter apEC	:FIVEN		
abandoned	well. Use Form 3160-3 (A	PD) for such proposals.			
SUBMIT IN TRIPLICATE - Other instructions on page 2.			7, If Unit of CA/Agreement, Name and/or No.		
1. Type of Well		MAR	1 / 2015		
Oil Well	Gas Well Other		8. Well Name and No.		
			Rhoc	les B #100 /	
2. Name of Operator Burling	ton Resources Oil & Gas	D	n চাহ্নার আমিজে nd Management 30-04	15-29217 🗸	
3a. Address		3b. Phone No. (include area code)	10. Field and Pool or Exploratory Area		
PO Box 4289, Farmington, NM 87499		(505) 326-9700	Fruit	land Coal 🗸	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. Country or Parish, State		
Surface Unit G (SWNI	E), 1770' FNL & 1850' FEL	, Sec. 20, T28N, R11W	San Juan ∕ ,	New Mexico	
12. CHECK T	HE APPROPRIATE BOX(ES)	TO INDICATE NATURE OF NO	OTICE, REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
0	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
X Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
(C)	Change Plans	X Plug and Abandon	Temporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
13. Describe Proposed or Completed Op	peration: Clearly state all pertinent de	tails, including estimated starting date of	f any proposed work and approxin	nate duration thereof.	
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.					
Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days					
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has					
determined that the site is ready for final inspection.)					
	Γγ				

Burlington Resources Oil & Gas, LP plugged and abandoned the subject well on 3/5/15 per the attached summary.

Approved as to plugging of the well bore. Liability under bond is retained until surface restoration is completed. OIL CONS. DIV DIST. 3

MAR 3 0 2015

16600000 FOR RECORD

MAR 2 6 2013

FARMINGTON FIELD OFFICE

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Patsy Clugston	Staff Regulatory Technician				
Signature Patsy Chigh	3/16/2015 Date				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved by					
	Title	Date			
Conditions of approval, if any, are attached. Approval of this notice does not warrant of that the applicant holds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon.	· · ·	Office			
Title 18 II S.C. Section 1001 and Title 43 II S.C. Section 1212, make it a crime for any	person knowingly and willfully to make to any den	artment or agency of the United States any			

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources
Rhodes B #100

March 5, 2015 Page 1 of 1

1770' FNL and 1850' FEL, Section 20, T-28-N, R-11-W San Juan County, NM Lease Number: SF-080844 API #30-045-29217

Plug and Abandonment Report Notified NMOCD and BLM on 3/3/15

Plug and Abandonment Summary:

Plug #1 with CR at 1282' spot 15 sxs (17.7 cf) Class B cement inside casing from 1282' to 1085' to cover the Fruitland top. ✓

Plug #2 with 24 sxs (28.32 cf) Class B cement inside casing from 616' to 300' to cover the Kirtland and Ojo Alamo tops.

Plug #3 with 30 sxs (35.4 cf) Class B cement inside casing from 270' to surface to cover the surface casing shoe. Tag TOC at 6'.

Plug #4 with 36 sxs Class B cement top off casings and weld on P&A marker with coordinates 36° 39.004' N / 108° 01.470' W.✓

Plugging Work Details:

- 3/3/15 Rode rig and equipment. Spot in and RU. SI well. SDFD.
- 3/4/15 Bump test H2S equipment. Check well pressures: tubing and bradenhead 0 PSI, casing 80 PSI. ND wellhead. RU A-Plus companion flange. Strip on kill spool and BOP. TOH and tally LD 52 jnts 1-1/4" tubing total tally 1691'. Pull 2-7/8" tubing hanger install 2-7/8" stripping rubber. TOH and tally LD 52 jnts 2-7/8" FJ total 1704'. PU 4-1/2" string mill. TIH to 1297'. PU 4-1/2" DHS CR and set at 1282'. Pressure test tubing to 1000 PSI, OK. Establish circulation. Pressure test casing to 800 PSI, OK. Spot plugs #1, #2 and #3. SI well. SDFD.
- 3/5/15 Bump test H2S equipment. Open up well; no pressures. Function test BOP. Tag TOC at 6'. ND BOP and kill spool. Dig out wellhead. RU High Desert. Cut off wellhead. Found cement at surface in 4-1/2" casing and down 23' in annulus. Spot plug #4 top off casings and weld on P&A marker with coordinates 36° 39.004' N / 108° 01.470' W. RD and MOL.

Jim Morris, MVCl representative, was on location.

Darrell Priddy, BLM representative, was on location.

✓