Form 3160-5 (August 2007)

UNITED STATES . DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

		REC	EIVED		
	FORM APPROVED	leo .	"ED		
	OMB No. 1004-0137	7 24	20		
	Expires: July 3/F 2010	,	<015		
Vo.	Uro- IIIno				

	ONED 110. 1004-0157
	Expires: July 3/1-2010
5. Lease Serial No.	Urea, "Ilnos

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

SF-0784331 Land Managernent If Indian, Allottee or Tribe Name

abanaonea	Went Oce Tollin Clos C	Al b) for such proposuls.			
S	UBMIT IN TRIPLICATE - Other in	nstructions on page 2.	7. If Unit of CA/Agreement, N	lame and/or No.	
1. Type of Well					
Oil Well	X Gas Well Other	8. Well Name and No.			
		NEWSOM 7			
2. Name of Operator			9. API Well No.		
	ConocoPhillips Comp	30-045-05833			
3a. Address		3b. Phone No. (include area code)	10. Field and Pool or Explorat	10. Field and Pool or Exploratory Area	
PO Box 4289, Farmingt	ton, NM 87499	(505) 326-9700	BALLARD	BALLARD PICTURED CLIFFS	
4. Location of Well (Footage, Sec., T.,	R.,M., or Survey Description)	11. Country or Parish, State			
UNIT I (i	NESE), 1650' FSL & 990'	San Juan	, New Mexico		
12. CHECK	THE APPROPRIATE BOX(E	S) TO INDICATE NATURE OF	NOTICE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
X Subsequent Report	Casing Repair	New Construction	Recomplete	Other	
BP	Change Plans	X Plug and Abandon	Temporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
13. Describe Proposed or Completed O	peration: Clearly state all pertinent d	etails, including estimated starting date	of any proposed work and approxin	nate duration thereof.	
		ve subsurface locations and measured a			
Attach the bond under which the	work will be performed or provide the	e Bond No. on file with BLM/BIA. Re-	quired subsequent reports must be fi	led within 30 days	

See sundry date 3/31/15 for changes that were made to the initially approved NOI for the P&A of the Newsom 7.

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has

See the attached procedure used to abandon this well. The Newsom 7 was plugged and abandoned on April 2, 2015.

OIL CONS. DIV DIST. 3

MAY 0 1 2015

ACCEPTED FOR RECORD

APR 29 2015

FARMINGTON FIELD OFFICE BY: To Salves

14. Thereby certify that the foregoing is true and correct. Name (Printed/Typed) Patsy Clugston	Staff F	Regulatory Technician	
Signature Halsis Clush	4/23/2015 Date		
U HHIS SPACE FOR FE	DERAL OR STATE OFFICE US	E	
Approved by			
	Title	Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant that the applicant holds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon.	· · · · · · · · · · · · · · · · · · ·		

determined that the site is ready for final inspection.)

Approved as to plugging

of the well bore. Liability

under bond is retained until surface restoration is completed.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Conoco Phillips Newsom #7 April 2, 2015 Page 1 of 1

1650' FSL and 990' FEL, Section 17, T-26-N, R-8-W San Juan County, NM Lease Number: SF-078433 API #30-045-05833

Plug and Abandonment Report Notified NMOCD and BLM on 3/27/15

Plug and Abandonment Summary:

- Plug #1 with CR at 2072' spot 55 sxs (64.9 cf) Class B cement inside casing from 2072' to 1587' to cover the Pictured Cliffs and Fruitland tops. Tag TOC at 1624'. ✓
- Plug #2 (combined #3) with 47 sxs (55.46 cf) Class B cement inside casing from 1504' to 1089' to cover the Kirtland and Ojo Alamo tops. Tag TOC at 1118'.
- Plug #4 with squeeze holes at 148' and CR at 100' spot 80 sxs (94.4 cf) Class B cement inside casing from 148' to surface with 5 sxs below CR, 12 sxs above CR and 63 sxs in annulus to cover the surface casing shoe. Tag TOC at 8'.
- Plug #5 with 28 sxs Class B cement top off casings and weld on P&A marker with coordinates 36° 29.075' N / 107° 41.973' W.✓

Plugging Work Details:

- 3/30/15 Rode rig and equipment to location. Spot in and RU. Bump test H2S equipment. Open up well; no pressures. RU A-Plus relief lines. RU companion flange. NU kill spool and BOP. Pull tubing hanger. TOH and tally LD 102 jnts, 1" NU tally total 2132'. SI well. SDFD.
- 3/31/15 Bump test H2S equipment. Open up well; no pressures and no tubing. Function test BOP. Round trip 5-1/2" string mill to 2080'. PU 5-1/2" DHS CR and set at 2072'. Pressure test tubing to 1000 PSI, OK. Establish circulation. Attempt to pressure test casing establish a rate of 3 bpm at 600 PSI, no test. RU A-Plus wireline. Ran CBL from 2072' to surface found cement at 1210'. Establish circulation. Spot plug #1 with calculated TOC at 1587'. SI well. SDFD.
- High Hamiltonian Hamiltonian Bump test H2S equipment. Open up well; no pressures. Function test BOP. TIH and tag TOC at 1624'. Attempt to pressure test casing establish a rate of 2 bpm at 600 PSI, no test. Note: Darrin H. BLM and NMOCD approved balance plug. Spot plug #2 combined with #3 with calculated TOC at 1089'. SI well. WOC due to sample. TIH and tag TOC at 1118'. Attempt to pressure test casing establish circulation with 5 bbls. Attempt to due dye test pump 20 bbls no dye, got half circulation after 10 bbls. RU A-Plus wireline. Perforate 4 HSC squeeze holes at 148'. PU 5-1/2" DHS CR and set at 100'. Establish circulation. Spot plug #4 with TOC at surface. SI well. SDFD.
- 4/2/15 Bump test H2S equipment. Open up well; no pressures. Tag TOC at 8'. ND BOP and kill spool. Dig out wellhead. RU High Desert. Cut off wellhead. Found cement at surface in 5-1/2" casing and down 9' in annulus. Spot plug #5 top off casings and weld on P&A marker with coordinates 36° 29.075' N / 107° 41.973' W. RD and MOL. ✓

Jim Morris, MVCI representative, was on location.

Darrin Halliburton, BLM representative, was on location.