Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

RECEIVE	Đ
---------	---

FORM APPROVED OMB No. 1004-0137

Expires:	July	31,	2010

ŗ	•	٠,٠		4	5
ŧ	•:		IJ	4	[]

SF-077106

			6. If Indian, Allottee or Tribe Name	
Do not use	this form for proposals	to drill or to re-enter an	on Field Office	
abandoned	well. Use Form 3160-3 (A	PD) for such proposals	end Nanagement	
SU	IBMIT IN TRIPLICATE - Other ins	tructions on page 2.	7. If Unit of CA/Agreement, N	Name and/or No.
1. Type of Well		L.	LACKEY B LS	
Oil Well X Gas Well Other		8. Well Name and No.	8. Well Name and No.	
		LAC	LACKEY B LS #6	
2. Name of Operator			9. API Well No.	
ConocoPhillips Company		30-	30-045-07357	
3a. Address 3b. Phon		3b. Phone No. (include area code)	Field and Pool or Explorat	tory Area
PO Box 4289, Farmington, NM 87499 (505) 326-9700		AZTEC P	ICTURED CLIFFS	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)		11. Country or Parish, State		
Surface UL D (N)	NNW), 900' FNL & 560' FV	VL, SEC. 21, T28N, R9W	San Juan	, New Mexico
12. CHECK	THE APPROPRIATE BOX(ES)	TO INDICATE NATURE OF	NOTICE, REPORT OR OTH	IER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	Reclamation	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
— (h)	Change Plans	X Plug and Abandon	Temporarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	
13. Describe Proposed or Completed Op	peration: Clearly state all pertinent det	ails, including estimated starting dat	te of any proposed work and approxing	mate duration thereof.
	onally or recomplete horizontally, give		•	
Attach the bond under which the w	ork will be performed or provide the l	Bond No. on file with BLM/BIA. R	equired subsequent reports must be f	filed within 30 days

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

ConocoPhillips requests permission to P&A the subject well per the attached procedure, current and proposed wellbore schematics. The Pre-Disturbance onsite was held on 4/27/15 with Bob Switzer/BLM. A Closed Loop system will be utilized for this P&A.

OIL CONS. DIV DIST. 3

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS
Notify NMOCD 24 hrs

MAY 08 2015

prior to beginning operations

SEE ATTACHED FOR CONDITIONS OF APPROVAL



14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) PATSY CLUGSTON	STAFF REGULATORY TECHNICIAN Title			
Signature Patsy Chical	Date	4/28/2015		
THIS SPACE FOR FED	ERAL OR S	TATE OFFICE USE		
Approved by Trov Salvers		Title PE	Date 5 5 2015	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or that the applicant holds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon.	•	Office FF6		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any	person knowingly	y and willfully to make to any depa	rtment or agency of the United States any	

false, fictitious or fraudulent statements or representations as to any matter within the false, fictitious or fraudulent statements or representations as to any matter within the false, fictitious or fraudulent statements or representations as to any matter within the false, first the false of the fals

(Instruction on page 2)

ConocoPhillips LACKEY B LS 6 Expense - P&A

Lat 36° 39' 7.488" N

Long 107° 48' 2.196" W

PROCEDURE

Note: Hole in casing at 923'.

This project requires the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COP safety and environmental regulations. Test rig anchors prior to moving in rig. Before RU, run WL to check for and remove any downhole equipment. If an obstruction is found, set a locking-3-slip-stop in the tubing.
- 2. MIRU workover rig. Check casing, tubing, and bradenhead pressures and record them in WellView. If there is pressure on the BH, contact the Wells Engineer.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure. Kill well as necessary. Ensure well is dead or on a vacuum.
- 4. ND wellhead and NU BOPE. Pressure and function test BOP to 250 psi low and 1,000 psi over SICP high to a maximum of 2,000 psi held and charted for 10 minutes per COP Well Control Manual. PU and remove tubing hanger. Tag for fill that may have accumulated above CIBP at 2,223'.
- 5. TOOH with tubing (per pertinent data sheet).

Tubing size: 2-3/8", 4.7#, J-55

Set Depth: 2.217

KB: 10'

6. PU 4-3/4" bit and watermelon mill and round trip as deep as possible above CIBP at 2,223'. If necessary, clean out fill to top of CIBP.

CBL ran on 12-16-2014 showed TOC at 1,688'.

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Class B mixed at 15.6 ppg with a 1.18 cf/sk yield.

7. Plug 1 (Pictured Cliffs Formation and perforations, 2123-2223', 17 sacks Class B cement)

Mix 17 sacks Class B cement and spot a balanced plug inside the casing to cover the Pictured Cliffs Formation and perforations. PUH.

See COA 8. Plug 2 (Fruitland Formation, 1669-1769', 17 sacks Class B cement)

Mix 17 sacks Class B cement and spot a balanced plug inside the casing to cover the Fruitland Formation. POOH.

SeccoA


9. Plug 3 (Ojo Alamo and Kirtland Formations, 1178-1386', 120 sacks Class B cement)


RIH and perforate 3 squeeze holes at 1,386'. Establish injection rate into squeeze holes. RIH with a 5-1/2" CR and set at 1,336'. Mix 120 sacks Class B cement. Squeeze 90 sacks outside the casing, leaving 30 sacks inside the casing to cover the Ojo Alamo and Kirtland Formations. POOH. Use caution squeezing outside casing - TOC will be near hole in casing at 923'.

10. Plug 4 (Surface Plug, 0-181', 93 sacks Class B cement)

RU WL and perforate 4 big hole charge (if available) squeeze holes at 181'. TOOH and RD wireline. **Observe well for 30 minutes per BLM regulations.** RU pump, close blind rams and establish circulation out bradenhead with water. Circulate BH clean. TIH with 5-1/2" CR and set at 131'. Mix 73 sacks Class B cement and squeeze until good cement returns to surface out BH valve. Shut BH valve and squeeze to max 200 psi. Sting out of CR and reverse circulate cement out of tubing. TOOH and LD stinger. TIH with open ended tubing to 130'. Mix 20 sacks Class B cement and pump inside plug. TOOH and LD Tubing. SI well and WOC.

11. Nipple down BOP and cut off casing below the casing flange. Install P&A marker with cement to comply with regulations. RDMO. Cut off anchors, and restore location.





UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: Lackey B LS #6

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Set plug #2 (2014-1914) ft. to cover the Fruitland top. BLM picks top of Fruitland at 1964 ft.
 - b) Bring the top of plug #3 to 1139 ft. inside/outside to cover the Kirtland and Ojo Alamo tops. Adjust cement volume accordingly.

Note: CBL ran 12-16-2014 is on file and will be used for plugging proposes.

Note: H2S has not been reported in this section; however, low concentrations of H2S (6ppm GSV) have been reported in the SW/NE of section 17, 28N, 9W.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.