Form 3160-5 (August 2007)

Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	FORM	M AI	PPRO	VED
	OMB	No.	1004	0137
1	Evnire	es. In	lv 31	2010

NOS ZOIS

5 Lease Serial No.

NAVAJO 14-20-603-769

6. If Indian, Allottee or Tribe Name

Water Disposal

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160-3 (APD) for such proposals. **NAVAJO TRIBE** SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Oil Well X Gas Well Other 8. Well Name and No. GE-ELE-GU-LITHE-E 500S 2. Name of Operator 9. API Well No. Burlington Resources Oil & Gas Company LP 30-045-34763 3b. Phone No. (include area code) 3a. Address 10. Field and Pool or Exploratory Area PO Box 4289, Farmington, NM 87499 (505) 326-9700 **BASIN FRUITLAND COAL** 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State Unit C (NENW), 915' FNL & 1775' FWL, Sec. 7, T26N, R8W San Juan **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Production (Start/Resume) Water Shut-Off Deepen Alter Casing Fracture Treat Reclamation Well Integrity X Subsequent Report Casing Repair New Construction Recomplete Other X Plug and Abandon Change Plans Temporarily Abandon

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Plug Back

The subject well was P&A'd on 6/1/15 per the attached report.

Approved as to plugging

of the well bore. Liability under bond is retained until surface restoration is completed.

Convert to Injection

OIL CONS. DIV DIST. 3

JUN 1 1 2015

ACCEPTED FOR RECORD

JUN 08 2015

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Arleen White Staff Regulatory Technician Title irleen White THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify Office that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources

GE-ELE-GU-LITHE-E 500S

June 1, 2015 Page 1 of 1

915' FNL and 1775' FWL, Section 7, T-26-N, R-8-W San Juan County, NM Lease Number: Navajo 14-20-603-769 API #30-045-34763

Plug and Abandonment Report Notified NMOCD and BLM on 5/27/15

Plug and Abandonment Summary:

- Plug #1 with CR at 1668' spot 60 sxs (70.8 cf) Class B cement inside casing from 1668' to 877' to cover the Fruitland, Kirtland and Ojo Alamo tops.√
- Plug #2 with 32 sxs (37.76 cf) Class B cement inside casing from 281' to surface to cover the surface casing shoe. Tag TOC at 7'.√
- Plug #3 with 26 sxs Class B cement top off casings and weld on P&A marker with coordinates 36° 30.422' N / 107° 43.569' W.√

Plugging Work Details:

- 5/28/15 Rode rig and equipment to location. Spot in and RU. RU H2S equipment. Check well pressures. Tubing 0 PSI, casing 50 PSI and bradenhead 40 PSI. RU relief lines. Blow well down. TOH and LD 2'-8' 6' pony, 66 3/4" rods, 2-8' ponys, 6 sinker bars, 8' guided and rod pump. SI well. SDFD.
- 5/29/15 Bump test H2S equipment. Check well pressures: tubing and bradenhead 0 PSI, casing 60 PSI. RU relief lines. Blow well down to 0 PSI. ND wellhead. RU Well Check pressure equipment. Pressure test blind 2-3/8" pipe rams to 250 PSI and 1250 PSI, OK. Pull tubing hanger. TOH and tally 1 jnt. 8', 2' subs, 26 stds, 6 jnts, FN, MA, 2-3/8" tubing, 60 jnts total tally 1886'. Round trip 4-1/2" string mill to 1688'. PU 4-1/2" DHS CR and set at 1668'. Pressure test tubing to 1000 PSI, OK. Establish circulation. Pressure test casing to 800 PSI. RU A-Plus wireline. Ran CBL from 1668' to surface, TOC at 68'. Establish circulation. Spot plugs #1 and #2. SI well. SDFD.
- 6/1/15 Bump test H2S equipment. Open up well; no pressures. Tag TOC at 7'. ND BOP. Dig out wellhead. RU High Desert. Cut off wellhead. Found cement at surface in 4-1/2" casing and down 40' in annulus. Spot plug #3 to top off casings and weld on P&A marker with coordinates 36° 30.422' N / 107° 43.569' W. RD and MOL.

Jim Morris, MVCI representative, was on location. Leo Pacheco, BLM representative, was on location.√