(Instruction on page 2)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Form 3160-5 (August 2007)	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT		FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010 5. Lease Serial No. I-149-IND-8473		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an			6. If Indian, Allottee or Tribe Nan		
			Zena Niela Off		
abandoned	well. Use Form 3160-3 (A	APD) for such proposals.		Man Oss	
SUBMIT IN TRIPLICATE - Other instructions on page 2.			7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well	VIC. W.II Dod			NITO UNIT	
Oil Well X Gas Well Other			8. Well Name and No. HUERFANITO UNIT 93S		
2. Name of Operator			9. API Well No.		
Burlington Resources Oil & Gas Company LP			30-045-34780		
		3b. Phone No. (include area code)	10. Field and Pool or Exploratory		
PO Box 4289, Farmington, NM 87499 (505) 326-9700			AND COAL		
4. Location of Well (Footage, Sec., T., Unit K (NE		WL, SEC. 25, T27N, R09W	11. Country or Parish, State San Juan ,	New Mexico	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA					
TYPE OF SUBMISSION		TYPE OF AC	TION		
x Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
_	Alter Casing		Reclamation	Well Integrity	
Subsequent Report	Casing Repair		Recomplete	Other	
60	Change Plans		Temporarily Abandon		
Final Abandonment Notice	Convert to Injection		Water Disposal		
		etails, including estimated starting date of ve subsurface locations and measured and			

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days

Burlington Resources requests permission to P&A the subject well per the attahed procedure, current and proposed wellbore schematics. A Closed Loop System will be used.

OIL CONS. DIV DIST. 3

SEE ATTACHED FOR CONDITIONS OF APPROVAL JUL 0 8 2015

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

14. I hereby certify that the foregoing is true and correct. Name (Printed Typed) Denise Journey	Title	Staff Regulatory Technician		
Signature Misk Journey	Date	7/1/2015 Date		
THIS SPACE FOR FED	ERAL OR	STATE OFFICE USE		
Approved by				
Troy Salvers		Title PE	Date 7/2/2015	
Conditions of approval, if any, are attached. Approval of this notice does not warrant		Office		
that the applicant holds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon.	Office FFO			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for ar false, fictitious or fraudulent statements or representations as to any matter within its i		ingly and willfully to make to any depart	rtment or agency of the United States any	

NMOCD

ConocoPhillips HUERFANITO UNIT 93S Expense - P&A

Lat 36° 32' 34.48" N

Long 107°44' 35.974" W

PROCEDURE

NOTE: Plug depths based off CBL ran in 2010.

This project requires the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU workover rig. Check casing, tubing, and bradenhead pressures and record them in Wellview. If there is pressure on the BH, contact the Wells Engineer.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure. Kill well as necessary. Ensure well is dead or on a vacuum.
- 4. TOOH w/ rod string and LD (per pertinent data sheet).

Size: 3/4"

Set Depth:

2,193

- 5. ND wellhead and NU BOPE. Pressure and function test BOP to 250 psi low and 1,000 psi over SICP high to a maximum of 2,000 psi held and charted for 10 minutes as per COP Well Control Manual. PU and remove tubing hanger
- 6. TOOH with tubing (per pertinent data sheet).

Tubing size: 2-3/8" 4.7# J-55 EUE

Set Depth: 2,214'

KB: 16'

- 7. PU 3-7/8" bit and watermelon mill and round trip as deep above top perforation at 1,942'.
- 8. PU 4-1/2" CR on tubing, and set a 1,892'. Pressure test tubing to 1,000 psi. Sting out of CR. Load hole, and pressure test casing to 800 psi. If casing does not test, then spot or tag subsequent plugs as appropriate. POOH w/ tubing.

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Class B mixed at 15.6 ppg with a 1.18 cf/sk yield.

9. Plug 1 (Fruitland Perforations and Fruitland Top, 1,774'-1,892', 13 Sacks Class B Cement)

Mix 13 sx Class B cement and spot a balanced plug inside the casing to cover the Fruitland formation top and Fruitland perforations. PUH.

See COM


10. Plug 2 (Ojo Alamo and Kirtland formation tops, 1,191'-1,440', 23 Sacks Class B Cement)


Mix 23 sx Class B cement and spot a balanced plug inside the casing to cover the Ojo Alamo and Kirtland formation tops. POOH.

9. Plug 3 (Surface Shoe, 0'-281', 26 Sacks Class B Cement)

Connect the pump line to the bradenhead valve and attempt to pressure test the BH annulus to 300 psi. Note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix 26 sx Class B cement and spot balanced plug inside casing from 281' to surface, circulating good cement out casing valve. TOOH and LD tubing. SI well and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface, filling the casing and the BH annulus to surface. Shut well in and WOC.

12. Nipple down BOP and cut off casing below the casing flange. Top off cement in 7" x 4-1/2" annulus from 0'-68'. Install P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.





UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Huerfanito Unit #93S

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Bring the top of plug #2 to 1178 ft. to cover the Kirtland and Ojo Alamo tops. Adjust cement volume accordingly.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.