Office Office	State of New Mexico				Form (
District I – (575) 393-6161	Energy, Minerals and Natural Resources				Revised July 1	8, 2013
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-045-27340	CY	
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.			5. Indicate Type STATE		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505			6. State Oil & G	FEE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505		, 1111 070		o. State Off & G	as Lease No.	
	ICES AND REPORTS ON	WELLS		7. Lease Name of	or Unit Agreement N	lame
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEP	EN OR PLUC		/ Louis I tallie	, omer groundit	arric
DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)	CATION FOR PERMIT" (FORM	1 C-101) FOR	SUCH	Northeast Blanco	Unit	
1. Type of Well: Oil Well Gas Well Other Disposal Well				8. Well Number		
				Pump Mesa SWD 1		
2. Name of Operator	I D			9. OGRID Num	ber	
Devon Energy Production Company, L.P. 3. Address of Operator				6137 10. Pool name or Wildcat		
333 West Sheridan Avenue, Oklahoma City, OK 73102-5015				Morrison Bluff Entrada		
4. Well Location				William Bian L		
ACCIONATE AND AC	. 000 foot from th	o Courth	line and	1600 foot from	the West line	
			line and		theWestline	
Section 36	Township 31N	Range		NMPM	County San Juan	N. W
	11. Elevation (Show who 6430 GL	einer DK, I	(KB, KI, GK, etc.)			
	0150 GE					
12 Charle	Annonwista Day to Inc	licata Na	tumo of Notice I	Domant on Othor	n Data	
12. Check I	Appropriate Box to Inc	ncate Na	ture of Notice, i	Report or Other	Data	
NOTICE OF IN	ITENTION TO:		SUBS	SEQUENT RE	PORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASIN	IG 🗌
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRIL	LING OPNS.	P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMENT	JOB		
DOWNHOLE COMMINGLE						
CLOSED-LOOP SYSTEM			OT! IED			
OTHER: Packer Failure 13. Describe proposed or comp	lated energians (Classly		OTHER:	aiva nartinant dat	taa inaludina aatima	tod doto
of starting any proposed w						
proposed completion or rec		i + i vivii i c.	Tor Wattiple Con	ipictions. Attach	welloofe diagram of	
Due to a packer failure, Devon p		ork:				
1. Set plug in the tubing X-Nipple located above the retrievable packer and pressure test tubing to 3,000 psig.						
2. Pull out plug in tubing X-Nipple above the retrievable packer.						
3. RIH and set plug in the I		nt packer	located below th	ne tubing/retrie	vable packer and	
pressure test to 3,000 pt 4. Pull out of hole with tub	3	kor				
5. Run Caliper Log to ident			e casing from 5	400 feet to 8 05	0 feet	
6. Select a new point to se						est
point to set the packer						
7. RIH with tubing and set						
8. Pressure test tubing and				sure to check fo	or leaks.	
9. Pressure test casing to 5			heck for leaks.			
10. Pull out plug from the R Devon is only injecting through			anent nacker is	only for pressure	testing the casin	a
Spud Date:		elease Date		only for pressure	OIL CONS. DIV D	ST 3
	Tug II	orouse Dure				10 11 6
					JUL 1 5 201	5
I hereby certify that the information	above is true and complete	e to the bes	t of my knowledge	and belief.		
					-	, ~
SIGNATURE	June TITL	ERegul	atory Advisor	DA	TE 7-13-	15
Type or print nameGaylan G. B					ONE: 405-552-4594	
For State Use Only	0	EPUTY	OIL & GAS I	NSPECTIA	, ,	
APPROVED BY:	TITLE		DISTRICT #	3 D/	ATE 7/29/19	5
Conditions of Approval (if any):	A					
670 DM D D D D D D D D D D D D D D D D D D						