Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SUNDRY	NMSF078818A						
Do not use thi abandoned we	6. If Indian, Allottee or Tribe Name						
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No. NMNM99323						
Type of Well	8. Well Name and No. POWELL COM 1						
Name of Operator     XTO ENERGY INC	9. API Well No. 30-045-29476-00-S1						
3a. Address		3b. Phone No. (include area code) Ph: 505-333-3215		10. Field and Pool, or Exploratory BASIN FRUITLAND COAL			
ENGLEWOOD, CO 80155				BAOINTROTTE	AND OOKE		
4. Location of Well (Footage, Sec., T	11. County or Parish, and State						
Sec 22 T32N R13W SENE 20 36.974351 N Lat, 108.184656	SAN JUAN COUNTY, NM						
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION						
□ Notice of Intent	☐ Acidize	☐ Deepen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off		
	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation		■ Well Integrity		
Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete		Other		
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Abandon	☐ Tempor	☐ Temporarily Abandon			

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

☐ Plug Back

XTO Energy Inc. has plugged and abandoned this location per the attached summary report. A Closed Loop System was used, all liquid waste was taken to Basin Disposal NM01-005.

☐ Convert to Injection

OIL CONS. DIV DIST. 3

■ Water Disposal

AUG 28 2015

14. I hereby certify that the foregoing is true and correct.  Electronic Submission #311126 verified by the BLM Well Information System  For XTO ENERGY INC, sent to the Farmington  Committed to AFMSS for processing by JACK SAVAGE on 08/26/2015 (15TLS0230SE)							
Name (Printed/Typed)	RHONDA SMITH	Title	REGULATORY CLERK				
Signature	(Electronic Submission)	Date	07/31/2015				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By ACCEPTED			ACK SAVAGE PETROLEUM ENGINEER	Date 08/26/2015			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	: Farmington				
	I and Title 43 U.S.C. Section 1212, make it a crime for any po or fraudulent statements or representations as to any matter w			ment or agency of the United			

\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*



## A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 \*fax: 505-325-1211

XTO Energy Inc.
Powell Com #1

July 14, 2015 Page 1 of 1

2050' FNL and 790' FEL, Section 22, T-32-N, R-13-W San Juan County, NM Lease Number: NMSF078818A API #30-045-29476

Plug and Abandonment Report
Notified NMOCD and BLM on 7/10/15

## Plug and Abandonment Summary:

- Plug #1 with CR at 495' spot 30 sxs (35.4 cf) Class B cement from 495' to 335' to cover the Fruitland Coal Perfs.
- Plug #2 with 53 sxs (62.54 cf) Class B cement from 216' to surface to cover the Fruitland top and surface 1) pump 47 sxs to circulate good cement out casing valve, 2) TOH and LD all tubing and RU pump to casing valve, 3) pump 6 sxs to re-fill 7" casing.

Plate Marker set with coordinates N 36° 58' 28" / W 108° 11' 4".

## Plugging Work Details:

- Rode rig and equipment to location. Spot in and RU. Check well pressures: SITP 0 PSI and SICP 60 PSI. RU relief lines and blow well down to pit. ND wellhead. NU BOP and function test. X-over for 2-7/8" tubing. PU on tubing string and LD hanger 6', 4' and 2' x 2-7/8" subs. TOH with 18 jnts (552.01') 2-7/8" 6.5# J-55 tubing, LD SN heavy scale on tubing. PU A-Plus 7" TIH tubing to mill at 495'. PU DHS 7" CR and set at 495'. Pressure test tubing to 800 PSI, OK. Pressure test casing to 800 PSI, OK. Spot plug #1 with calculated TOC at 335'. TOH and LD all tubing. TIH open-ended to 216'. Spot plug #2 with TOC at surface. SI well. SDFD.
- 7/14/15 Travel to location. Open up well; no pressures. Function test BOP. Found cement at surface in casing. Dig out wellhead. RU High Desert. Write Hot Work Permit. Cut off wellhead. Weld and install P&A marker with coordinates N 36° 58′ 28″ / W 108° 11′ 4″. RD and MOL.

Joe Ruybalid, BLM representative was on location.