Form 3160-5 (March 2012)

(Instructions on page 2)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

5. Lease Serial No.

6. If Indian, Allottee, or Tribe Name

124 TR #221

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

CONTRACTOR OF THE PARTY OF THE	abandoned well. Use Form 3160-3 (APD) for such proposals.							
SUBMIT IN TRIPLICATE - Other Instructions on page CEIVED						7. If Unit or CA/Agreement Name and/or No.		
Type of Well								
Oil Well X	Gas Well C	2015	8. Well Name and No.					
		OEI 20 Dec			Jicarilla Apache Tribal 124 #3			
Name of Operator	9. API Well No.							
Enervest Operating, LLC 3a. Address 3b. Phone No findade them code; men						30-039-22140		
a. Address 001 Fannin ST., Suite 800 Houston,	TX 77002-6707	713-659		anea reoge) HIETIL	10. Field and Pool, or Exploratory Area Ojito Gallup/Dakota			
Location of Well (Footage, Sec., T., R.,		715-055	5500	11. County or Parish, State				
850' FEL & 1850' FSL, Se. 13, (UL .			Rio Arriba, NM					
12. CHECK THE APPROPRI	ATE BOX(ES) TO INDIC	CATE NATURE	OF NOTICE	E, REPORT, OR	OTHER DATA			
TYPE OF SUBMISSION		118507	PE OF ACTION	N				
X Notice of Intent	Acidize	Deepen		Production (Start/ Resume)	Water Shut-Off		
		Fracture 7						
	Alter Casing			Reclamation		Well Integrity		
Subsequent Report	Casing Repair	New Cons	struction	Recomplete		Other		
pr	Change Plans	X Plug and	Abandon	Temporarily	Abandon			
Final Abandonment Notice	Convert to Injection	Plug Back		Water Dispo	sal			
A Closed-Loop Sysem will be used						per 22, 2015. See attached		
Reclamation Plan.						OIL CONS. DIV DIS		
BLM'S APPROVAL OR ACTION DOES NOT RELI OPERATOR FROM OBTAI AUTHORIZATION REQUI ON FEDERAL AND INDIA	EVE THE LESSEE AND NING ANY OTHER RED FOR OPERATIONS	opera	OCD 24 hrs eginning tions	SEE AT	TACHED F IS OF APP			
A. I heraby partify that the foregoing is true and	orrect Name (Printed Typed)							
			Title		Regulatory C	onsultent		
Sittly Doctate			Tale .		Regulatory Consultant			
Signature Afielly	Woescher	FOR	Date	T OFFICE L	September	24, 2015		
proved by	THIS SPACE	FOR FEDERA	L OR STAT	E OFFICE US	E			
Approved by Lange Lange								
	inge_		Tista	PE		Dute 10/2/15		
	of this notice does not warrant of	or certify	Title Office			Date 10/2/15		
	Ocescher		Title Date					

PLUG AND ABANDONMENT PROCEDURE

August 28, 2015

Jicarilla Apache 124 #3

Ojito Gallup / Dakota 1850' FEL and 1850' FSL, (UL J) Section 13, T25N, R4W Rio Arriba County, New Mexico / API 30-039-22140 Lat: N 36.3974609567682/ Lat: W -107.201172310597

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

- This well requires the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
- Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety
 regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on
 location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well.
 Kill well with water as necessary and at least pump tubing capacity of water down the tubing.
 ND wellhead and NU BOP. Function test BOP.

3.	Rods: Yes_	_X, No	, Unknown							
	Tubing: Yes	X_, No	, Unknown	, Size _	2-3/8	, Length66	66'			
	Packer: Yes_	, No	, Unknown	_, Type						
	If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.									

- NOTE: BLM requires a CBL log to be run on all wells where the cement did not
 circulate to surface or where a T.S. or CBL log was not previously run. This procedure
 is prepared with the understanding that it may be modified based on the TOC from the
 CBL.
- 5. Plug #1 (Dakota/Gallup perforations and top, 6735' 6635'): Round trip gauge ring or casing scraper to 6735', or as deep as possible. RIH and set 5.5" cement retainer at 6735'. Pressure test tubing to 1000 PSI. Load casing with water and circulate well clean. Pressure test casing to 1000#. If the casings do not test, then spot or tag subsequent plugs as appropriate. Circulate well clean. Mix 17 sxs Class B cement inside casing from 6813' to isolate the Dakota/Gallup interval. PUH.
- Plug #2 (Mancos top, 6034' 5934'): Mix and pump 17 sxs Class B cement and spot a balanced plug inside casing to cover the Mancos top. PUH.
- Plug #3 (Mesaverde top, 5606' 5506'): Mix and pump 17 sxs Class B cement and spot a balanced plug inside casing to cover the Mesaverde top. PUH.
- 8. Plug #4 (Chacra top,4897' 4797'): Mix and pump 17 sxs Class B cement and spot a balanced plug inside casing to cover the Chacra top. PUH.

- Plug #5 (Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops, 4007' 3416'): Mix and pump 73 sxs Class B cement and spot a balanced plug inside casing to cover the Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops. PUH.
- Plug #6 (Nacimiento top, 2186' 2086'): Mix and pump 73 sxs Class B cement and spot a balanced plug inside casing to cover the Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops. PUH.
- 11. Plug #7 (8.625" casing shoe, 359' 0'): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 45 sxs cement and spot a balanced plug from 359' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing from 359' and the annulus from the squeeze holes to surface. Shut in well and WOC.
- 12. ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations

Jicarilla Apache 124 #3

Current

Ojito Gallup / Dakota

Today's Date: 8/28/14 Spud: 9/6/79 Completed: 11/16/79 Elevation: 7088' GL 12.25" hole Nacimiento @ 2136' *est Ojo Alamo @ 3466' *est Kirtland @ 3623' *est Fruitland @ 3750' *est Pictured Cliffs @ 3957' *est Chacra @ 4847' *est Mesaverde @ 5556' *est Mancos @ 5984' *est Gallup @ 6861' Dakota @ 7763'

1850' FEL,850'FSL,(ULJ)Section 13,T-25-N,R-4-W Rio Arriba County, NM, API #30-039-22140 TOC circulated to surface 6863' - 6982' 7034' - 7944' 7.875" hole TD 8220'

8.625" 24#, Casing set @ 309' Cement with 315 sxs, circulated

2-3/8" tubing @ 6666' (2008) (with rods and pump)

Gallup Perforations: 5750' - 5736' (sqz'd 11/12/79)

DV Tool at 5858' 2nd Stage: Cement with 1350 sxs

TOC @ DV Tool

Tension Anchor @ 6569'

(Amoco fish at 6740' plugged off with iron sulfide)

Gallup Perforations:

Dakota Perforations:

5.5",17.5#, N-80 Casing set @ 8220' 1st Stage: Cement with 665 sxs

PBTD 8170'

Jicarilla Apache 124 #3 Proposed P&A

Ojito Gallup / Dakota 1850' FEL,1850' FSL,(UL J) Section 13, T-25-N,R-4-W

Rio Arriba County, NM, API #30-039-22140

Today's Date: 8/28/14

Spud: 9/6/79 Completed: 11/16/79 Elevation: 7088' GL

12.25" hole

Nacimiento @ 2136' *est

Ojo Alamo @ 3466' *est

Kirtland @ 3623' *est

Fruitland @ 3750' *est

Pictured Cliffs @ 3957' *est

Chacra @ 4847' *est

Mesaverde @ 5556' *est

Mancos @ 5984' *est

Gallup @ 6861'

Dakota @ 7763'

7.875" hole



TD 8220' **PBTD 8170'** TOC circulated to surface

8.625" 24#, Casing set @ 309' Cement with 315 sxs, circulated

> Plug #7: 359' - 0' Class B cement, 45 sxs

Plug #6: 2186' - 2086' Class B cement, 17 sxs

Plug #5: 4007' - 3416' Class B cement, 73 sxs

Plug #4: 4897' - 4797' Class B cement, 17 sxs

Plug #3: 5606' - 5506' Class B cement, 17 sxs

Gallup Perforations: 5750' - 5736' (sqz'd 11/12/79)

DV Tool at 5858'

2nd Stage: Cement with 1350 sxs

TOC @ DV Tool

Plug #2: 6034' - 5934' Class B cement, 17 sxs

Set CR @ 6735'

Plug #1: 6735' - 6635' Class B cement, 17 sxs

(Amoco fish at 6740' plugged off with iron sulfide)

Gallup Perforations: 6863' - 6982'

Dakota Perforations:

7034' - 7944'

5.5",17.5#, N-80 Casing set @ 8220' 1st Stage: Cement with 665 sxs

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon: Re: Permanent Abandonment Well: Jicarilla Apache 124 #3

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Bring the top of plug #1 to 6527 ft. to cover the Gallup top. BLM picks top of Gallup at 6577 ft. Adjust cement volume accordingly.
 - b) Set Plug #2 (6255-6155) ft. to cover the Mancos top. BLM picks top of Mancos at 6205 ft.
 - c) Bring the top of plug #3 to 5161 ft. to cover the Mesaverde top. BLM picks top of Cliff House at 5211 ft. Adjust cement volume accordingly.
 - d) Set Plug #5 (3588-3043) ft. to cover the Pictured Cliffs, Fruitland, Kirtland, and Ojo Alamo tops. BLM picks top of Pictured Cliffs at 3538 ft. and top of Ojo Alamo at 3093 ft
 - a) Set Plug #6 (1871-1771) ft. to cover the Nacimiento top. BLM picks top of Nacimiento at 1821 ft.

Operator will run a CBL to verify cement top. Submit the electronic copy of the log for verification to the following addresses: tsalyers@blm.gov Brandon.Powell@state.nm.us

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.