Form 3160-5

UNITED STATES

FORM APPROVED

(August 2007)					OMB No. 1004-0137 Expires: July 31, 2010 5. Lease Serial No.	
SEP 1 8 2015 BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS				5. Lease Serial No.		
				The second control of	SF-080117	
				6. If Indian, Allottee or Tribe Name		
Farmington Field Propot us						
ureau of Land Marabandoned						
SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well			ge 2.	7. If Unit of CA/Agreement, Name and/or No.		
Oil Well X Gas Well Other				HUERFANITO UNIT		
				8. Well Name and No. HUERFA	ANITO UNIT 47S	
2. Name of Operator Burlington Resources Oil & Gas Company LP				9. API Well No. 30-(9. API Well No. 30-045-34559	
			include area code)	10. Field and Pool or Explorat	10. Field and Pool or Exploratory Area	
PO Box 4289, Farming	(505	326-9700	BASIN FRUITLAND COAL			
4. Location of Well (Footage, Sec., T., UL I (N	R.,M., or Survey Description) ESE), 2570' FSL & 710' FE	L, SEC. 27,	T27N, R9W	11. Country or Parish, State San Juan	, New Mexico	
12. CHECK	THE APPROPRIATE BOX(ES	TO INDICAT	E NATURE OF	NOTICE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
X Notice of Intent	Acidize	Deepen	Г	Production (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Tr	eat [Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Const	ruction	Recomplete	Other	
- BD	Change Plans	X Plug and A	bandon	Temporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back		Water Disposal		
schematics. The pre-dis- system will be utilized do	turbance onsite was held or uring this P&A.		CONS. DIV		an is attached. A closed loc	
			VIO. DIV	DIST. 3		
ACTION DO OPERATOR AUTHORIZA	ROVAL OR ACCEPTANCE OF SES NOT RELIEVE THE LESS FROM OBTAINING ANY OTI ATION REQUIRED FOR OPE AL AND INDIAN LANDS		SEP 25 20 otify NMOCD prior to begin operation	ning	ED FOR APPROVAL	
14. I hereby certify that the foregoing is	s true and correct Name (Printed/Tur	ned)	<u> </u>			
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Patsy Clugston			Staff Regulatory Technician Title			
Signature Patsn Class			9/16/2015 Date			
	THIS SPACE FO	R FEDERAL	OR STATE (OFFICE USE		
Approved by	TOTAL STRUCTURE OF THE					
Troy Salvers			Title	PE	Date 9 22 2015	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or ce that the applicant holds legal or equitable title to those rights in the subject lease which we entitle the applicant to conduct operations thereon.						
Title 18 U.S.C. Section 1001 and Title false, fictitious or fraudulent statements (Instruction on page 2)			knowingly and wil		igency of the United States any	

ConocoPhillips HUERFANITO UNIT 47S Expense - P&A

Lat 36° 32' 45.73" N

Long 107° 46' 7.496" W

PROCEDURE

This project requires the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig. Before RU, run WL remove downhole equipment. If an obstruction is found, set a locking-3-slip-stop in the tubing.
- 2. MIRU workover rig. Check casing, tubing, and bradenhead pressures and record them in Wellview. If there is pressure on the BH, contact the Wells Engineer.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure. Kill well as necessary. Ensure well is dead or on a vacuum.
- 4. ND wellhead and NU BOPE. Pressure and function test BOP to 250 psi low and 1,000 psi over SICP high to a maximum of 2,000 psi held and charted for 10 minutes as per COP Well Control Manual. PU and remove tubing hanger
- 5. TOOH with tubing (per pertinent data sheet).

Tubing size: 2-3/8" 4.7# J-55 EUE

Set Depth: 2188'

KB: 11'

- 6. PU 3-7/8" bit and watermelon mill and round trip as deep as possible above top perforation at 2114'.
- 7. PU 4.5" CR on tubing, and set a 2064'. Pressure test tubing to 1,000 psi. Sting out of CR. Load hole, and pressure test casing to 800 psi. If casing does not test, then spot or tag subsequent plugs as appropriate. POOH w/ tubing.
- 8. RU wireline and run CBL with 500 psi on casing from CR to surface to identify TOC. Adjust plugs as necessary for new TOC. Email log copy to Troy Salyers (BLM) at tsalyers@blm.gov and Brandon Powell (NMOCD) at brandon.powell@state.nm.us upon completion of logging operations.

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Class B mixed at 15.6 ppg with a 1.18 cf/sk yield.

9. Plug 1 - Fruitland Formation Top, 1880' - 2064', 18 Sacks Class B Cement

Mix 18 sx Class B cement and spot a balanced plug inside the casing to cover the Fruitland formation top. PUH.


10. Plug 2 - Kirtland and Ojo Alamo Formation Top, 1304' - 1560', 24 Sacks Class B Cement


Mix 24 sx Class B cement and spot a balanced plug inside the casing to cover the Kirtland and Ojo Alamo formation tops. PUH.

11. Plug 3 - Surface Plug, 0' - 189', 19 Sacks Class B Cement

Connect the pump line to the bradenhead valve and attempt to pressure test the BH annulus to 300 psi. Note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix 19 sx Class B cement and spot balanced plug inside casing from 189' to surface, circulating good cement out casing valve. TOOH and LD tubing. SI well and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface, filling the casing and the BH annulus to surface. Shut well in and WOC.

12. Nipple down BOP and cut off casing below the casing flange. Install P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.





UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Huerfano Unit 47S

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

Operator will run a CBL to verify cement top. Submit the electronic copy of the log for verification to the following addresses: tsalyers@blm.gov Brandon.Powell@state.nm.us

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.