Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I – (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30-039-31294
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE STATE STATE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No. E012079
(DO NOT USE THIS FORM FOR PROPO	ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name 132829
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	8. Well Number NE Chaco Com #243H
2. Name of Operator	OIL CONS. DIV DIST. 3	9. OGRID Number
WPX Energy Production, LL	C 111 1 5 2015	120782
3. Address of Operator 721 South Main Avenue, Azto	JOL 19 2013	10. Pool name or Wildcat Chaco Unit NE HZ (oil)
4. Well Location		
Unit LetterL	:1449'feet from theSOUTH line and	344'feet from the
WESTline		
Section 16	Township 23N Range 6W	NMPM County: Rio Arriba
	11. Elevation (Show whether DR, RKB, RT, GR, e	etc.)
	6858'	
12 Chaok	Appropriate Box to Indicate Nature of Notice	a Papart or Other Data
12. CHECK F	Appropriate Box to indicate Nature of Notice	e, Report of Other Data
NOTICE OF IN	ITENTION TO: SU	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WO	
TEMPORARILY ABANDON		DRILLING OPNS. P AND A
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL CASING/CEME	ENT JOB L
DOWNHOLE COMMININGLE		
OTHER:	□ OTHER:	COMPLETION
13. Describe proposed or comp	leted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date
13. Describe proposed or comp	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple 0	and give pertinent dates, including estimated date
13. Describe proposed or comp of starting any proposed we proposed completion or rec	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple 0	and give pertinent dates, including estimated date
13. Describe proposed or comp of starting any proposed we proposed completion or rec 6/2/15- MIRU TIH w/ seal Assembly, w/ 5.85 nogo. and 4 1/2	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848'
13. Describe proposed or comp of starting any proposed we proposed completion or rec 6/2/15- MIRU TIH w/ seal Assembly, w/ 5.85 nogo. and 4 1/20.04 84 jts of 4 1/2" casing 3726.71 8 pup jt	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4 is for spacing (0.78, 2.04, 4.02, 4.00, 9.70, 7.52, 7.22, 6.92) 42.2	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848'
13. Describe proposed or composed was proposed completion or recomposed	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4 is for spacing (0.78, 2.04, 4.02, 4.00, 9.70, 7.52, 7.22, 6.92) 42.2	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848' 0 1 jt of 4 1/2" casing 44.00 4 1/2" csng sub and hanger 2.43
13. Describe proposed or composed was proposed completion or recomposed	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4 its for spacing (0.78, 2.04, 4.02, 4.00, 9.70, 7.52, 7.22, 6.92) 42.2 ,,000# on csng hanger rt record test for 30 minutes. Test was good. Pressure test 7" Into	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848' 0 1 jt of 4 1/2" casing 44.00 4 1/2" csng sub and hanger 2.43 ermediate casing to 1,500 psi. Chart record test for 30
13. Describe proposed or composed was proposed completion or recomposed	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4 its for spacing (0.78, 2.04, 4.02, 4.00, 9.70, 7.52, 7.22, 6.92) 42.2 ,,000# on csng hanger rt record test for 30 minutes. Test was good. Pressure test 7" Into	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848' 0 1 jt of 4 1/2" casing 44.00 4 1/2" csng sub and hanger 2.43
13. Describe proposed or compost starting any proposed we proposed completion or recomposed completion or recomposed starting any proposed we proposed completion or recomposed completion or recomposed completion or recomposed starting and	letted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4 is for spacing (0.78, 2.04, 4.02, 4.00, 9.70, 7.52, 7.22, 6.92) 42.2, 000# on csng hanger trecord test for 30 minutes. Test was good. Pressure test 7" Into 0 psi	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848' 0 1 jt of 4 1/2" casing 44.00 4 1/2" csng sub and hanger 2.43 ermediate casing to 1,500 psi. Chart record test for 30
13. Describe proposed or compost starting any proposed we proposed completion or recomposed completion of the composed	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4 its for spacing (0.78, 2.04, 4.02, 4.00, 9.70, 7.52, 7.22, 6.92) 42.2 ,,000# on csng hanger rt record test for 30 minutes. Test was good. Pressure test 7" Into	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848' 0 1 jt of 4 1/2" casing 44.00 4 1/2" csng sub and hanger 2.43 ermediate casing to 1,500 psi. Chart record test for 30 CONFIDENTIAL 1900 psi. Pressure fell to 0 psi. Picked up and released packer, tbng) Attempt to test casing. Pressured up to 1700 psi.
13. Describe proposed or compost starting any proposed we proposed completion or recomposed completion of the composed completion of the completion of the composed completion of the completion of the composed completion of the composed completion of the completi	letted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4 its for spacing (0.78, 2.04, 4.02, 4.00, 9.70, 7.52, 7.22, 6.92) 42.2, ,000# on csng hanger rt record test for 30 minutes. Test was good. Pressure test 7" Into 0 psi rt: Pressure test casing (above packer @6422') Pressured up to Test was good. Released packer and re set @6414' (Did not land eaks off to 0 psi when pump is neutral. Pressure test down thing	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848' 0 1 jt of 4 1/2" casing 44.00 4 1/2" csng sub and hanger 2.43 ermediate casing to 1,500 psi. Chart record test for 30 CONFIDENTIAL 1900 psi. Pressure fell to 0 psi. Picked up and released packer, tbng) Attempt to test casing. Pressured up to 1700 psi.
13. Describe proposed or compost starting any proposed we proposed completion or recomposed completion of the composed composed completion of the composed composed completion of the composed	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4 is for spacing (0.78, 2.04, 4.02, 4.00, 9.70, 7.52, 7.22, 6.92) 42.2, 0.00# on csng hanger record test for 30 minutes. Test was good. Pressure test 7" Intro 0 psi rt: Pressure test casing (above packer @6422') Pressured up to 1.7 Test was good. Released packer and re set @6414' (Did not land eaks off to 0 psi when pump is neutral. Pressure test down thing	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848' 0 1 jt of 4 1/2" casing 44.00 4 1/2" csng sub and hanger 2.43 ermediate casing to 1,500 psi. Chart record test for 30 CONFIDENTIAL 1900 psi. Pressure fell to 0 psi. Picked up and released packer, tbng) Attempt to test casing. Pressured up to 1700 psi.
13. Describe proposed or comp of starting any proposed we proposed completion or rec 6/2/15- MIRU TIH w/ seal Assembly, w/ 5.85 nogo. and 4 1/ 20.04 84 jts of 4 1/2" casing 3726.71 8 pup jt landed casing @6138.02 30,000# on liner, 22 Pressure test 4 1/2" casing to 1,500 psi. Chai minutes. Test was good. Shut in 7" with 1,50 6/3/15- Attempt to pressure test 6/4//15 — Contacted NMOCD & BLM to repo Re set packer @6355' Press test to 3400 psi. Pumping @1700 psi with test unit. Pressure I good. Csng leak @6394' Spuid Date:	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4 is for spacing (0.78, 2.04, 4.02, 4.00, 9.70, 7.52, 7.22, 6.92) 42.2, 0.00# on csng hanger record test for 30 minutes. Test was good. Pressure test 7" Intro 0 psi rt: Pressure test casing (above packer @6422') Pressured up to 1.7 Test was good. Released packer and re set @6414' (Did not land eaks off to 0 psi when pump is neutral. Pressure test down thing	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848' 0 1 jt of 4 1/2" casing 44.00 4 1/2" csng sub and hanger 2.43 ermediate casing to 1,500 psi. Chart record test for 30 CONFIDENTIAL 1900 psi. Pressure fell to 0 psi. Picked up and released packer, tbng) Attempt to test casing. Pressured up to 1700 psi.
13. Describe proposed or compost starting any proposed we proposed completion or recomposed completion of the composed completion of the completion of the composed completion of the composed completion of the composed completion of the	letted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4 its for spacing (0.78, 2.04, 4.02, 4.00, 9.70, 7.52, 7.22, 6.92) 42.2 ,,000# on csng hanger rt record test for 30 minutes. Test was good. Pressure test 7" Into 0 psi rt: Pressure test casing (above packer @6422') Pressured up to Test was good. Released packer and re set @6414' (Did not land eaks off to 0 psi when pump is neutral. Pressure test down thing Rig Release Date: 4/13/15	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848' 0 1 jt of 4 1/2" casing 44.00 4 1/2" csng sub and hanger 2.43 ermediate casing to 1,500 psi. Chart record test for 30 CONFIDENTIAL 1900 psi. Pressure fell to 0 psi. Picked up and released packer, tbng) Attempt to test casing. Pressured up to 1700 psi. (Below packer @6414') to 1000 psi to test packer. Test was
13. Describe proposed or compost starting any proposed we proposed completion or recomposed completion of the composed completion of the completion of the composed completion of the composed completion of the composed completion of the	leted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4 is for spacing (0.78, 2.04, 4.02, 4.00, 9.70, 7.52, 7.22, 6.92) 42.2, 0.00# on csng hanger record test for 30 minutes. Test was good. Pressure test 7" Intro 0 psi rt: Pressure test casing (above packer @6422') Pressured up to 1.7 Test was good. Released packer and re set @6414' (Did not land eaks off to 0 psi when pump is neutral. Pressure test down thing	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848' 0 1 jt of 4 1/2" casing 44.00 4 1/2" csng sub and hanger 2.43 ermediate casing to 1,500 psi. Chart record test for 30 CONFIDENTIAL 1900 psi. Pressure fell to 0 psi. Picked up and released packer, tbng) Attempt to test casing. Pressured up to 1700 psi. (Below packer @6414') to 1000 psi to test packer. Test was
13. Describe proposed or compost starting any proposed we proposed completion or recomposed completion of the composed completion of the completion of the composed completion of the composed completion of the composed completion of the	letted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4 its for spacing (0.78, 2.04, 4.02, 4.00, 9.70, 7.52, 7.22, 6.92) 42.2 ,,000# on csng hanger rt record test for 30 minutes. Test was good. Pressure test 7" Into 0 psi rt: Pressure test casing (above packer @6422') Pressured up to Test was good. Released packer and re set @6414' (Did not land eaks off to 0 psi when pump is neutral. Pressure test down thing Rig Release Date: 4/13/15	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848' 0 1 jt of 4 1/2" casing 44.00 4 1/2" csng sub and hanger 2.43 ermediate casing to 1,500 psi. Chart record test for 30 CONFIDENTIAL 1900 psi. Pressure fell to 0 psi. Picked up and released packer, tbng) Attempt to test casing. Pressured up to 1700 psi. (Below packer @6414') to 1000 psi to test packer. Test was
13. Describe proposed or compof starting any proposed we proposed completion or recomposed completion of the proposed	letted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4 its for spacing (0.78, 2.04, 4.02, 4.00, 9.70, 7.52, 7.22, 6.92) 42.2 ,,000# on csng hanger rt record test for 30 minutes. Test was good. Pressure test 7" Intro 0 psi rt: Pressure test casing (above packer @6422') Pressured up to Test was good. Released packer and re set @6414' (Did not land eaks off to 0 psi when pump is neutral. Pressure test down thing Rig Release Date: 4/13/15 above is true and complete to the best of my knowled.	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848' 0 1 jt of 4 1/2" casing 44.00 4 1/2" csng sub and hanger 2.43 ermediate casing to 1,500 psi. Chart record test for 30 CONFIDENTIAL 1900 psi. Pressure fell to 0 psi. Picked up and released packer, tbng) Attempt to test casing. Pressured up to 1700 psi. (Below packer @6414') to 1000 psi to test packer. Test was dge and belief. DATE7/14/15
13. Describe proposed or comp of starting any proposed we proposed completion or rec 6/2/15- MIRU TIH w/ seal Assembly, w/ 5.85 nogo. and 4 1/ 20.04 84 jts of 4 1/2" casing 3726.71 8 pup jt landed casing @6138.02 30,000# on liner, 22 Pressure test 4 1/2" casing to 1,500 psi. Chai minutes. Test was good. Shut in 7" with 1,50 6/3/15- Attempt to pressure test 6/4//15 - Contacted NMOCD & BLM to repo Re set packer @6355' Press test to 3400 psi. Pumping @1700 psi with test unit. Pressure I good. Csng leak @6394' Spud Date: 3/26/15 I hereby certify that the information SIGNATURE Type or print name Lacey Granillo	letted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4 its for spacing (0.78, 2.04, 4.02, 4.00, 9.70, 7.52, 7.22, 6.92) 42.2, 000# on csng hanger the record test for 30 minutes. Test was good. Pressure test 7" Interest was good. Released packer and re set @6412' (Did not land eaks off to 0 psi when pump is neutral. Pressure test down thing Rig Release Date: 4/13/15 above is true and complete to the best of my knowless.	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848' 0 1 jt of 4 1/2" casing 44.00 4 1/2" csng sub and hanger 2.43 ermediate casing to 1,500 psi. Chart record test for 30 CONFIDENTIAL 1900 psi. Pressure fell to 0 psi. Picked up and released packer, tbng) Attempt to test casing. Pressured up to 1700 psi. (Below packer @6414') to 1000 psi to test packer. Test was dge and belief. DATE7/14/15
13. Describe proposed or compof starting any proposed we proposed completion or recomposed completion of the proposed	letted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4 its for spacing (0.78, 2.04, 4.02, 4.00, 9.70, 7.52, 7.22, 6.92) 42.2 ,,000# on csng hanger rt record test for 30 minutes. Test was good. Pressure test 7" Intro 0 psi rt: Pressure test casing (above packer @6422') Pressured up to Test was good. Released packer and re set @6414' (Did not land eaks off to 0 psi when pump is neutral. Pressure test down thing Rig Release Date: 4/13/15 above is true and complete to the best of my knowled the complete the complete to the best of my knowled the complete the complete to the best of my knowled the complete to the best of my knowled the complete the complete to the best of my knowled the complete the complete the complete to the complete the co	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848' 0 1 jt of 4 1/2" casing 44.00 4 1/2" csng sub and hanger 2.43 ermediate casing to 1,500 psi. Chart record test for 30 CONFIDENTIAL 1900 psi. Pressure fell to 0 psi. Picked up and released packer, tbng) Attempt to test casing. Pressured up to 1700 psi. (Below packer @6414') to 1000 psi to test packer. Test was dge and belief. DATE7/14/15
13. Describe proposed or comp of starting any proposed we proposed completion or rec 6/2/15- MIRU TIH w/ seal Assembly, w/ 5.85 nogo. and 4 1/ 20.04 84 jts of 4 1/2" casing 3726.71 8 pup jt landed casing @6138.02 30,000# on liner, 22 Pressure test 4 1/2" casing to 1,500 psi. Chai minutes. Test was good. Shut in 7" with 1,50 6/3/15- Attempt to pressure test 6/4//15 - Contacted NMOCD & BLM to repo Re set packer @6355' Press test to 3400 psi. Pumping @1700 psi with test unit. Pressure I good. Csng leak @6394' Spud Date: 3/26/15 I hereby certify that the information SIGNATURE Type or print name Lacey Granillo	letted operations. (Clearly state all pertinent details, ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 2" 11.6# P-110 casing Seal assembly with NO-GO 1.16 52 jts of 4 its for spacing (0.78, 2.04, 4.02, 4.00, 9.70, 7.52, 7.22, 6.92) 42.2 ,,000# on csng hanger rt record test for 30 minutes. Test was good. Pressure test 7" Intro 0 psi rt: Pressure test casing (above packer @6422') Pressured up to Test was good. Released packer and re set @6414' (Did not land eaks off to 0 psi when pump is neutral. Pressure test down thing Rig Release Date: 4/13/15 above is true and complete to the best of my knowled the complete the complete to the best of my knowled the complete the complete to the best of my knowled the complete to the best of my knowled the complete the complete to the best of my knowled the complete the complete the complete to the complete the co	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of 1/2" casing 2279.48 Marker jt 3828' - 3848' 0 1 jt of 4 1/2" casing 44.00 4 1/2" csng sub and hanger 2.43 ermediate casing to 1,500 psi. Chart record test for 30 CONFIDENTIAL 1900 psi. Pressure fell to 0 psi. Picked up and released packer, tbng) Attempt to test casing. Pressured up to 1700 psi. (Below packer @6414') to 1000 psi to test packer. Test was dge and belief. DATE7/14/15

NE Chaco Com #243H - page 2

6/6/15-Finshed picking up PH6 DP, RU 2.5 Power Swivel on jt #, 205 @ 6,363' R&R Down to 6,600',Rolled Hole w/ 90 bbls of filtered Production water Run caliper log, 6800' to Liner top @6138'.

6/11/15-6/13/15- reported squeeze on subsequent sundry filed on 6/18/15

6/14/15-6/16/15- WAIT on resin to cure. Received verbal approval from NMOCD to proceed with conditions per subsequent sundry filed on 6/18/15

6/17/15-CO 11309'

6/19/15-Perf Gallup 1st stage, 11124'-11249' + RSI TOOL @11313' with 18, 0.40" holes. RD

6/20/15-6/28/15- prepare and wait for frac

6/29/15-Frac Gallup 1st stage 11124'-11249'- with 214,180# 20/40 PSA Sand

Set flo-thru frac plug @ 11074' MD. Perf 2nd stage 10808'-11024'- with 24, 0.40" holes. Frac Gallup 2nd stage with 216,160#, 20/40 PSA Sand 4100-4110 -30030psi=15 min (72 psi/min).

Set flo-thru frac plug @ 10775' MD. Perf 3rd stage 10482'-10698'- with 24, 0.40" holes. Frac Gallup 3rd stage with 214,600#, 20/40 PSA Sand 4058psi - 3035psi=15 min (68.2 psi/min).

6/30/15-Set flo-thru frac plug @ 10430' MD. Perf 4th stage 10156'-10372'- with 24, 0.40" holes. Frac Gallup 4th stage with 214,600#, 20/40 PSA Sand Repair leaking lubricator, Pressure test to 4140psi - 3250psi=15 min (59.3 psi/min).

Set flo-thru frac plug @ 10090' MD. Perf 5th stage 9860'-10045'-with 24, 0.40" holes. Frac Gallup 5th stage with 213,380#, 20/40 PSA Sand Pressure test to 4096psi - 2800psi=15 min (86.4 psi/min).

Set flo-thru frac plug @ 9820' MD. Perf 6th stage 9564'-9749'- with 24, 0.40" holes. Frac Gallup 6th stage with 213,300#, 20/40 PSA Sand Pressure test to 4178 psi - 2756 psi in 15 min (94.8 psi/min bleed off).

Set flo-thru frac plug @ 9530' MD. Perf 7th stage 9278'-9463'- with 24, 0.40" holes. Frac Gallup 7th stage with 215,460#, 20/40 PSA Sand Pressure test to 4026 psi - 3515 psi in 15 min (34 psi/min bleed off).

Set flo-thru frac plug @ 9240' MD. Perf 8th stage 8992'-9178'- with 24, 0.40" holes. Frac Gallup 8th stage with 215,240#, 20/40 PSA Sand Pressure test to 4141 psi - 2455 psi in 15 min (112 psi/min bleed off).

Set flo-thru frac plug @ 8960' MD. Perf 9th stage 8710'-8892'- with 24, 0.40" holes. Frac Gallup 9th stage with 215,240#, 20/40 PSA Sand Pressure test to 4033 psi - 2633 psi in 15 min (93.3 psi/min bleed off).

7/1/15-Set flo-thru frac plug @ 8650' MD. Perf 10th stage 8418'-8606'- with 24, 0.40" holes. Frac Gallup 10th stage with 217,120#, 20/40 PSA Sand Pressure test to 4022 psi - 2695 psi in 15 min (88.5 psi/min bleed off).

Set flo-thru frac plug @ 8360' MD. Perf 11th stage 8134'-8320'- with 24, 0.40" holes. Frac Gallup 11th stage with 213,840#, 20/40 PSA Sand Pressure test to 4196 psi - 2164 psi in 15 min (135 psi/min bleed off).

Set flo-thru frac plug @ 8070' MD. Perf 12th stage 7648'-8033'- with 24, 0.40" holes. Frac Gallup 12th stage with 215,520# 20/40 PSA Sand Pressure test to 4180 psi - 690 psi in 15 min (232 psi/min bleed off

Set flo-thru frac plug @ 7775' MD. Perf 13th stage 7562'-7747'- with 24, 0.40" holes. Frac Gallup 13th stage with 213,860#, 20/40 PSA Sand Pressure test to 4280 psi - 1543 psi in 15 min (182 psi/min bleed off).

Set flo-thru frac plug @ 7510' MD. Perf 14th stage 7276'-7461'- with 24, 0.40" holes. Frac Gallup 14th stage with 211,640#, 20/40 PSA Sand Pressure test to 4140 psi - 1686 psi in 15 min (163 psi/min bleed off).

Set flo-thru frac plug @ 7225' MD. Perf 15th stage 6996'-7176'- with 24, 0.40" holes. Frac Gallup 15th stage with 215,260#, 20/40 PSA Sand Pressure test to 4404 psi - 1220 psi in 15 min (212 psi/min bleed off).

Set flo-thru frac plug @ 6965' MD. Perf 16th stage 6704'-6890'- with 24, 0.40" holes. Frac Gallup 16th stage with 217,660#, 20/40 PSA Sand Pressure test to 4248 psi - 1050 psi in 15 min (213 psi/min bleed off).

Set flo-thru frac plug @ 6650' MD. Perf 17th stage 6422'-6604'- with 24, 0.40" holes. Frac Gallup 17th stage with 215,460#, 20/40 PSA Sand (No test required)

7/2/15-Set 4-1/2" CBP @ 5020'. RDMO Frac & WL.

7/6/15- MIRU Pressure Tested BOP- OK.

7/7/15- DO CBP @ 5020'. DO flo- thru Frac plug @ 6650', 6965', 7225', 7510', 7775', 8070', 8360', 8650', 8960', 9240', 9530', 9820', 10090', 10430', 10775' and 11074' Circ. & CO well to 11249'

7/8/15- Pulled tieback string 4 1/2" 11.6# P-110 casing, Seal assembly with NO-GO, 52 jts of 4 1/2" casing, Marker jt, 84 jts of 4 1/2" casing, 8 pup jts for spacing, 1 jt of 4 1/2" casing, 4 1/2" casi

Land tbg @ 6288'. Run production tbng with GLV on 2 7/8" N-80 tbng 37 jts of 2 7.8" 1146.85 GLV #9 @1166.25 4.10 26 jts of 2 7/8" 801.26 GLV #8 @1971.61 4.10 21 jts of 2 7/8" 649.20 GLV #7 @2624.91 4.10 18 jts of 2 7/8" 555.67 GLV #6 @3184.68 4.10 18 jts of 2 7/8" 555.23 GLV #5 @3744.01 4.10 17 jts of 2 7/8" 525.12 GLV #4 @4273.23 4.10 18 jts of 2 7/8" 556.18 GLV #3 @4833.51 4.10 17 jts of 2 7/8" 526.24 GLV #2 @5364.03 4.10 13 jts of 2 7/8" 401.90 X-nipple @5767.13 1.20 10 jts of 2 7/8" 308.59 GLV #1 @6079.82 4.10 1 jt of 2 7/8" 30.75 2 7/8" pup jt with on/off tool 6.02 7" packer @ 6124.09 7.50 2 7/8" x 2 3/8" xo 50 X nipple @6254.38 1.25 1 jt of 2 3/8" ms collar 33.49 EOT @6287.87 Set packer with 10,000# tension

NOTE: Will file flowback test info and delivery info on delivery sundry.