RECEIVED

Form 3160- 5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR 18 2015 BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137

SUNDRY NOTICES AND REPORTS ON WELLS Office

Do not use this form for proposals to drill or to re-enter an

Expires: July 31,2010 Lease Serial No. Jicarilla 464 If Indian, Allottee, or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such proposals.				Jicarilla Apache Tribe
SUBMIT IN TRIPLICATE - Other Instructions on page 2.				7. If Unit or CA. Agreement Name and/or No.
Oil Well Gas Well				8. Well Name and No.
Name of Operator				Jicarilla 464-32 #15
Black Hills Gas Resources, Inc.				9. API Well No. 30-039-29305
3a. Address P.O. Box 249 Bloomfield, NM 87413		3b. Phone No. (include area code) (505) 634-5104		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1890' FSL & 980' FEL NE/SE Section 32 T30N R3W (UL: I)			Cabresto Canyon Tertiary	
			11. County or Parish, State	
				Rio Arriba County, New Mexico
12. CHECK APPR	OPRIATE BOX(S) TO INI	DICATE NATURE OF 1	NOTICE, REPORT,	OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	Acidize	Deepen	Production (Start/ Resume) Water Shut-off
	Altering Casing	Fracture Treat	Reclamation	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
· Bl	Change Plans	✓ Plug and abandon	Temporarily	Abandon
Final Abandonment Notice	Convert to Injection	Plug back	Water Dispos	sal
 Describe Proposed or Completed Op If the proposal is to deepen direction 				ork and approximate duration thereof. oths of all pertinent markers and zones.

Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

Black Hills Gas Resources plugged and abandoned Jicarilla 464-32 #15 per the attachment.

Attachment: Plug and Abandonment Report

OIL CONS. DIV DIST. 3

ACCEPTED FOR RECORD

JAN 04 2016

Approved as to plugging of the well bore. Liability under bond is retained until surface restoration is completed. DEC 2 1 2015

14. I hereby certify that the foregoing is true and correct. Name (Printed/ Typed)	
Daniel Manus Re	egulatory Technician II
Signature Winiel Manu 3 Date	December 18,2015
THIS SPACE FOR FEDER	RAL OR STATE OFFICE USE
Approved by	Title Date
Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office
Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person k	nowingly and willfully to make any department or agency of the United States any false,

(Instructions on page 2)

Black Hills Gas Resources Jicarilla 464-32 #15

1890' FSL and 980' FEL, Section 32, T-30-N, R-3-W Rio Arriba County, NM API #30-039-29305

Plug and Abandonment Report Notified Jicarilla BLM, BLM & NMOCD on 11/13/15

Plug and Abandonment Summary:

Plug #1 with 42 sxs (49.56 cf) Class B cement from 3278' to 2908'. Tag TOC at 2920'.

Plug #2 with 28 sxs (33.04 cf) Class B cement with 2% CaCl2 from 1902' to 1655' to cover the Nacimiento top. Tag TOC at 1714'.

Plug #3 with 48 sxs (56.64 cf) Class B cement with 2% CaCl2 from 1021' to 598' to cover the San Jose perforations. Tag TOC at 654'.

Plug #4 with 46 sxs (54.28 cf) Class B cement from 326' to surface to cover the 8 5/8" casing shoe and surface. 1) Pump 40 sxs to circulate good cement out casing valve. 2) TOH. RU pump to 5-1/2" casing valve. 3) Pump 6 sxs to refill 5-1/2" casing.

Plug #5 with 17 sxs Class B cement top off casings and install P&A Marker at 36° 45' 58" N / 107° 10' 3" W.

Plugging Work Details:

- 11/13/15 MIRU A-Plus #14 & McGuire H2S safety equipment. SWI. SDFD.
- 11/17/15 SITP 50 psi, SICP 50 psi, SIBHP 0 psi. No H2S monitored. Blow down well. ND WH. NU BOP and function test. TOOH and LD 2 3/8" production tubing. TIH with 2 3/8" workstring. Tag at 3278'. Receive OK from R. Velarde, Jicarilla BLM, V. Lucero, BLM, & B. Powell, NMOCD to pump plug #1 from 3278'. Pump 40 bbls wtr, did not establish circulation. Pump 3 bbls. Spot **Plug #1** with calculated TOC at 2908'. TOH. SWI. SDFD.
- 11/18/15 SICP 0 psi, SIBHP 0 psi. Function test BOP. TIH & tag TOC at 2920'. TOOH to 1902'. Spot Plug #2 with calculated TOC at 1655'. TOH. SWI. WOC. TIH. Tag TOC at 1714'. TOH to 1021'. Load BH with less than 1/8 bbl. Pressure test BH with 300 psi, held OK. Spot Plug #3 with calculated TOC at 598'. TOH. SWI. SDFD.
- 11/19/15 SICP 0 psi, SIBHP 0 psi. Function test BOP. TIH and tag TOC at 654'. TOH to 326'. Pressure test casing to 800 psi, held OK. Spot **Plug #4** with TOC at surface. ND BOP. Cut off WH. Found cement at cut off point in 5-1/2" and 8-5/8" casings. Spot **Plug #5** and install P&A Marker at 36° 45' 58" N / 107° 10' 3" W. RDMOL.

Rod Velarde, Jicarilla BLM representative, was on location. Stephen Charley, McGuire representative, was on location.