Form 3160-5 (August 2007)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS			5. Lease Serial No. NMNM047		
Do not use the abandoned we	6. If Indian, Allottee				
SUBMIT IN TRI	7. If Unit or CA/Agr				
Type of Well ☐ Oil Well ☐ Gas Well ☑ Ott					
Name of Operator ROBERT L BAYLESS PROD	Contact:	HELEN TRUJILLO Ibayless.com	9. API Well No. 30-045-30809	9. API Well No. 30-045-30809-00-S1	
3a. Address PO BOX 168 FARMINGTON, NM 87499		3b. Phone No. (include area code Ph: 505-326-2659			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	11. County or Parish	11. County or Parish, and State	
Sec 7 T30N R12W SWSW 10 36.823144 N Lat, 108.143906			SAN JUAN COUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE NATURE OF	NOTICE, REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Temporarily Abandon	A STATE OF THE STA	
3-0	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal		
following completion of the involved testing has been completed. Final Al determined that the site is ready for f	t operations. If the operation re bandonment Notices shall be fil inal inspection.)	sults in a multiple completion or rec led only after all requirements, inclu-	A. Required subsequent reports shall be ompletion in a new interval, a Form 31 ding reclamation, have been completed E ABOVE WELL PER THE ATT	60-4 shall be filed once I, and the operator has	
	CHED FOR OF APPROVAL	ACTION DOES NOT	eginning	ONS. DIV DIST. 3	
			J	AN 27 2016	
14. I hereby certify that the foregoing is Comm Name (Printed/Typed) JOHN TH	Electronic Submission # For ROBERT L BAY nitted to AFMSS for proces	328742 verified by the BLM We LESS PRODUCER LLC, sent to ssing by CYNTHIA MARQUEZ of Title OPER	ell Information System of the Farmington on 01/22/2016 (16CXM0132SE) ATIONS ENGINEER		
- June (1 ramew 1 ypeu) JOHN 111	ONIAO	THE OF ETV	THORSE ENGINEER	TO THE REAL PROPERTY.	
Signature (Electronic S	Submission)	Date 01/18/2	2016		
	THIS SPACE FO	OR FEDERAL OR STATE	OFFICE USE	ANT AREA CHEST	
Approved By ACCEPTED			ARQUEZ W EXAMINER	Date 01/22/2016	
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	uitable title to those rights in the	e subject lease	Office Farmington		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



Robert L Bayless, Producer LLC

Plug And Abandonment Procedure

Floyd #6

1050' FSL & 1065' FWL, Section 7, T-30-N, R-12-W San Juan County, NM / API 30-045-30809

- Hold pre-job safety meeting. Comply with all NMOCD, BLM safety and environmental regulations. Test rig anchors prior to moving in rig if not rigged to base beam.
- 2. Check casing, tubing, and bradenhead pressures.
- Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure. Kill well as necessary. Ensure well is dead or on a vacuum.
- TOOH w/ rod string and LD.
 - Size: 7/8" Set Depth: 2065 ft
- 5. ND wellhead and NU BOP. Function test BOP.
- 6. TOOH with 2-3/8" tubing string and tally as follows:
 - 2-3/8" 4.7# J-55 tubing landed @2068
 - seating nipple landed @ 1995
- 7. P/U cement retainer on tubing and set at 1600'. Pressure test tubing to 1000 psi. Sting out of retainer. Load hole and pressure test casing to 800 psi. If casing does not test, then spot or tag subsequent plugs as appropriate.

- 8. TIH and sting into retainer.
- Rig up to pump cement down tubing. Pump water to establish rate down tubing.
- 10. Plug 1(Fruitland Coal Formation Tops 1666'-2060'):

Pump 20 bbls (59 cu ft, 51 sx) Class G neat cement with 1.15 cu ft/sx yield.

- · Cement volume is 125% casing volume below retainer.
- 11. Plug 2: Sting out of retainer and spot 50' plug (20 bbls, 6 cu ft, 5 sx) Class G cement on top of retainer.
- 12. Pull up to 1300' and clear tubing by displacing with 6 bbls of water.
- 13. TOOH to 50'.
- 14. Plug 3: Set 50' cement (20 bbls, 6 cu ft, 5sx) Class G cement at surface.
- 15. WOC and cut off wellhead 4' below ground level. Weld plate with well information.
- 16. Backfill the hole. RDMO

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: Floyd 6

and a subject to the second of the two by

and out the ball of the

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - Set a cement plug (641-235) ft. to cover the Ojo Alamo and Kirtland tops. BLM picks top of Kirtland at 591 ft. BLM picks top of Ojo Alamo at 285 ft.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.