Submit I Conv To Appropriate District	Ctata CNI- Ma		E
Office	fice State of New Mexico		Form C-103 Revised July 18 2013
<u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	5) 393-6161 Energy, Minerals and Natural Resources 10 Dr., Hobbs, NM 88240 OIL CONSERVATION DIVISION 75) 748-1283 OIL CONSERVATION DIVISION 05) 334-6178 1220 South St. Francis Dr. 05) 476-3460 Santa Fe, NM 87505		WELL API NO.
District II - (575) 748-1283			30-045-07805
District III – (505) 334-6178			5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV = (505) 476-3460			6 State Oil & Gas Lease No
1220 S. St. Francis Dr., Santa Fe, NM			
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		. Bease Maine of Child Higherment Maine	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Gallegos Canyon Unit Com G	
1. Type of Well: Oil Well 🗌 Gas Well 🖾 Other		8. Well Number	
2. Name of Operator		9. OGRID Number	
BP America Production Company		000778	
3. Address of Operator		10. Pool name or Wildcat	
737 North Eldridge Pkwy, 12.181A Houston, TX 77079		Basin Dakota	
4. Well Location			Dusin Dukou
Unit Letter_K_: 1460 feet from the South line and 2494 feet from the West line			
Section 26 Township 29N Range 12W NMPM County San Juan			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
5458'			
12. Charle American Device Indicate Nictory of Nictics, Depart on Other Date			
12. Check Appropriate Box to indicate Nature of Notice, Report of Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			
			130B []
CLOSED-LOOP SYSTEM			
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE PLILE 10.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
1 1			
BP America Production Company would like to P&A the subject well. OIL CONS. DIV DIST. 3			
Please see the attached P&A procedure Notify NMOCD 24 by			
prior to beginning MAR 1 4 2016			
			DL9
Spud Date: 10/10/19	Rig Release Dr	ate	21.5
Spud Date: 10/10/19	Rig Release Da	ate:	212.5
Spud Date: 10/10/19	Rig Release Da	ate:	1125
Spud Date: 10/10/19 I hereby certify that the information	Rig Release Da Rig Release Da Rig Release Da	ate:	e and belief.
Spud Date: 10/10/19	Rig Release Da	ate:	e and belief.
Spud Date: 10/10/19 I hereby certify that the information SIGNATURE	Rig Release Da a above is true and complete to the be TITLE Reg	ate:	e and belief. DATE03/09/2016
Spud Date: 10/10/19	Rig Release Da a above is true and complete to the be TITLE Regu vin E-mail address: To	ate:	e and belief. DATE03/09/2016 n PHONE: 281-366-7148
Spud Date: 10/10/19 I hereby certify that the information SIGNATURE Office Type or print name Toya Col For State Use Only	Rig Release Da above is true and complete to the be TITLE Reg vin E-mail address: To	ate:	e and belief. DATE03/09/2016 nPHONE:281-366-7148
Spud Date: 10/10/19 I hereby certify that the information SIGNATURE Office Type or print name Toya Col For State Use Only ADDROVED BY	Rig Release Da above is true and complete to the be TITLE Reg vin E-mail address: To DEPUTY	ate: est of my knowledge ulatory Analyst oya.Colvin@bp.cor	e and belief. DATE03/09/2016 nPHONE:281-366-7148 NSPECIDR DATE2.75-1142
Spud Date: 10/10/19 I hereby certify that the information SIGNATURE OF CONT Type or print name Toya Col For State Use Only APPROVED BY: MULL Conditions of Approval dif any):	Rig Release Da above is true and complete to the be TITLE Reg vin E-mail address: To DEPUTY TITLE	ate: est of my knowledge ulatory Analyst oya.Colvin@bp.com OIL&GASI DISTRICT #:	e and belief. DATE03/09/2016 nPHONE:281-366-7148 NSPECIDR DATE3.25-110
Spud Date: 10/10/19 I hereby certify that the information SIGNATURE Opposite Type or print name Toya Col For State Use Only APPROVED BY: APPROVED BY: Opmote Conditions of Approval (if any):	Rig Release Da a above is true and complete to the be TITLE Reg vin E-mail address: To EPUTY TITLE FY	ate: est of my knowledge ulatory Analyst oya.Colvin@bp.cor OIL&GASI DISTRICT # 3	e and belief. DATE <u>03/09/2016</u> n PHONE: <u>281-366-7148</u> NSPECIDR 3 DATE <u>3:25-116</u>
Spud Date: 10/10/19 I hereby certify that the information SIGNATURE Office Type or print name Toya Col For State Use Only APPROVED BY: MOMOU Conditions of Approval (if any):	Rig Release Da above is true and complete to the be TITLE Regu vin E-mail address: To DEPUTY TITLE FY	ate: est of my knowledge ulatory Analyst oya.Colvin@bp.com OIL&GASI DISTRICT #3	e and belief. DATE03/09/2016 nPHONE:281-366-7148 NSPECIJR DATE325-110

March 3, 2016

NMOCD

BP would like to permanently plug and abandon the **Gallegos Canyon Unit Com G** #179 well, as per the attached procedure and wellbore schematics.

PLUG AND ABANDONMENT PROCEDURE

Basin Dakota

1460' FSL and 2494' FWL, Section 26, T29N, R12W San Juan County, New Mexico / API 30-045-07805 Lat: / Lat:

- Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.
 - This project will use an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
 - Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
 - 3. Rods:
 Yes_____, No____, Unknown____.

 Tubing:
 Yes_X___, No____, Unknown_____, Size___2-3/8"___, Length ___6040'__.

 Packer:
 Yes_____, No_X__, Unknown____, Type _____.

If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.

- 4. Plug #1 (Dakota perforations and top, 5900' 5796'): Round trip gauge ring or casing scraper to 5900', or as deep as possible. RIH and set 4.5" cement retainer at 5900'. Pressure test tubing to 1000 PSI. Load casing with water and circulate well clean. Pressure test casing to 800#. <u>If the casings do not test, then spot or tag subsequent</u> plugs as appropriate. Circulate well clean. Mix 12 sxs Class B cement inside casing from 6003' to isolate the Dakota interval. PUH.
- Plug #2 (Gallup top, 5132' 5032'): Mix and pump 12 sxs Class B cement and spot a balanced plug inside casing to cover the Gallup top. PUH.
- Plug #3 (Mancos top, 4215' 4115'): Mix and pump 12 sxs Class B cement and spot a balanced plug inside casing to cover the Mancos top. PUH.
- Plug #4 (Mesaverde and Mancos top, 3035' 2371'): Mix and pump 55 sxs Class B cement and spot a balanced plug inside casing to cover the Mesaverde top. PUH.

- Plug #5 (Pictured Cliffs and Fruitland tops, 1490' 1051'): Mix and pump 40 sxs Class B cement and spot a balanced plug inside casing to cover the Pictured Cliffs and Fruitland tops. TOH and LD tubing.
- Plug #6 (Kirtland, Ojo Alamo and 8.625" casing shoe, 420' 0'): Perforate 3 squeeze holes at 420'. Attempt to establish a rate . If able to establish circulation then mix and pump 135 sxs Class B cement to surface. Circulate good cement to surface. SI well and WOC.
- ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations

