Form 3160-5 (August 2007)

☐ Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS

5. Lease Serial No. NMSF078019

Do not use the abandoned we	6. If Indian, Allottee	If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No. E H PIPKIN 20			
SUBMIT IN TR	7. If Unit or CA/Ag				
Type of Well Oil Well					
Name of Operator XTO ENERGY INC	9. API Well No. 30-045-25184	9. API Well No. 30-045-25184-00-S1			
3a. Address ENGLEWOOD, CO 80155		3b. Phone No. (include area code Ph: 505-333-3206	10. Field and Pool, o	10. Field and Pool, or Exploratory KUTZ PICTURED CLIFFS	
 Location of Well (Footage, Sec., Sec 12 T27N R11W NENE 0 36.594162 N Lat, 107.94693 	The state of the s	11. County or Parish, and State SAN JUAN COUNTY, NM			
12. CHECK APP	PROPRIATE BOX(ES) T	O INDICATE NATURE OF	NOTICE, REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
□ Notice of Intent Subsequent Report	☐ Acidize ☐ Alter Casing	□ Deepen □ Fracture Treat	□ Production (Start/Resume) □ Water Shu □ Reclamation □ Well Integ		

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

☐ Plug Back

☑ Plug and Abandon

XTO Energy Inc, has completed plugging and abandonment of this well per the attached summary report. A Closed Loop System was used. All liquid waste was taken to Basin Disposal NM01-005. A below grade DH marker will be set at a later date.

☐ Change Plans

☐ Convert to Injection

OIL CONS. DIV DIST. 3

□ Temporarily Abandon

■ Water Disposal

MAR 1 7 2016

14. I hereby certify that	the foregoing is true and correct. Electronic Submission #333098 verifie For XTO ENERGY INC, Committed to AFMSS for processing by JA	sent to	the Farmington	
Name (Printed/Typed)	KRISTEN LYNCH	Title	REGULATORY ANALYST	
Signature	(Electronic Submission)	Date 03/08/2016		
A SECTION OF THE REAL PROPERTY.	THIS SPACE FOR FEDERA	L OR	STATE OFFICE USE	
Approved By ACCEPTED			ACK SAVAGE PETROLEUM ENGINEER	Date 03/11/2016
certify that the applicant ho	my, are attached. Approval of this notice does not warrant or olds legal or equitable title to those rights in the subject lease olicant to conduct operations thereon.	Office	Farmington	

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

XTO Energy Inc. E H Pipkin #20 March 1, 2016 Page 1 of 1

970' FNL and 370' FEL, Section 12(A), T-27-N, R-11-W San Juan County, NM Lease Number: NMSF-078019 API #30-045-25184

Plug and Abandonment Report Notified NMOCD and BLM on 2/25/16

Plug and Abandonment Summary:

Plug #1 with CR at 1550' and spot 8 sxs (9.44 cf) Class B cement from 1550' to 1445' to cover the Pictured Cliffs top.

Plug #2 with 13 sxs (15.34 cf) Class B cement from 1304' to 1133' to cover the Fruitland top.

Plug #3 with 20 sxs (23.6 cf) Class B cement from 712' to 449' to cover the Kirtland and Ojo Alamo tops.

Plug #4 with 25 sxs (29.5 cf) Class B cement from 188' to surface to cover the surface casing shoe and surface plug.

Plugging Work Details:

- 2/26/16 Rode rig and equipment to location. LO/TO. Spot in and RU. Check well pressures: 4-1/2" SICP 10 PSI, 2-3/8" SITP and SIBH 0 PSI. RU relief lines. Blow well down. RU rod tools and unseat pump. LD rod string as follows: 1 1-1/4" x 16' polish rod, 1-2', 6', 8' x 3/4" pony rods, 65 3/4" plain rods, 1 1" x 1' pony rod, 1 3/4" guide rod, 1 rod pump 1-1/2". Remove wellhead cap, not 8-5/8" Larkin wellhead cap. SI well. SDFD.
- 2/29/16 Check well pressures: 4-1/2" SICP 10 PSI, 2-3/8" SITP and SIBH 0 PSI. Blow well down. Remove Ind. Wellhead cap. NU WSI companion flange. NU BOP and function test. PU on production string. LD 2-3/8" tubing hanger, LD and tally 2-3/8" 4.7# J-55 EUE tubing as follows: 53 tubing jnts, 1 10' pup jnt, 1 2-3/8" SN, 1 20' OPMA. PU 3-7/8" bit and string mill and TIH to 1580'. PU 4-1/2" DHS CR and set at 1550'. Pressure test tubing to 1000 PSI, OK. Circulate well clean. Pressure test casing to 800 PSI, OK. Spot plugs #1, #2, #3 and #4. SI well. SDFD.
- 3/1/16 Open up well; no pressures. ND BOP. Found cement top in 4-1/2" casing down 3'. Install tubing hanger and wellhead cap. RD and MOL. Note: no P&A marker installed, wellhead not cut off.

Ron Chavez, BLM representative, was on location.