JUL 23 2013 |

Form 3160-5

UNITED STATES

FORM APPROVED

(August 2007)	DEPARTMENT OF THE INTERIOR			OMB No. 1004-0137		
	BUREAU OF LAND MANAGEMENT Farmington Field Office		Expires: July 31,2010			
D	SUNDRY NOTICES AND REPORTS ON WELLS and Manage Do not use this form for proposals to drill or to re-enter an			Jicarilla Contract 458 6. If Indian, Allottee, or Tribe Name		
abandoned well. Use Form 3160-3 (APD) for such proposals.				Jicarilla Apache Tribe		
SUBMIT IN TRIPLICATE - Other Instructions on page 2.				7. If Unit or CA.	Agreement Name and/or No.	
1. Type of Well Oil Well Gas Well	Other			8. Well Name and		
2. Name of Operator				Jicarilla 458 #3		
Black Hills Gas Resources, Inc.				9. API Well No. 30-039-24167		
Address 3b. Phone No. (include area code) P.O. Box 249 Bloomfield, NM 87413 (505) 634-5104			10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1818 FNL & 231 FEL SE/NE Section 7 T30N R3W (UL: H)			Cabresto Cnyn Tert / E. Blanco PC		C	
				11. County or Parish, State		
· ·				Rio Arriba County, New Mexico		
12. CHECK APPR	OPRIATE BOX(S) TO INI	DICATE NATURE OF NO	OTICE, REPORT, O	OR OTHER DA	TA	
TYPE OF SUBMISSION TYPE OF ACTION						
Notice of Intent	Acidize	Deepen	Production (S	itart/ Resume)	Water Shut-off	
	Altering Casing	Fracture Treat	Reclamation		Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete		Other	
Change Plans ✓ Plug and abandon		✓ Plug and abandon	Temporarily Abandon			
Final Abandonment Notice	Convert to Injection	Plug back	Water Dispose	al		
113 Describe Proposed or Completed O	peration Clearly state all pertinent de	etails including estimated starting	date of any proposed wo	rk and approximate	duration thereof	

Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.

Black Hills Gas Resources intends to plug and abandon Jicarilla 458 #3 per attached procedure. A closed loop system will be used.

Attachment:

Proposed procedure Current well bore diagram Proposed well bore diagram Finial reclamation plan

Notify NMOCD 24 hrs prior to beginning operations

SEE ATTACHED FOR CONDITIONS OF APPROVAL

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND **OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS** ON FEDERAL AND INDIAN LANDS

OIL CONS. DIV DIST. 3

AUG 0 5 2016

Daniel Manus	Regulatory Technician II				
Signature Mentiel Man	us Date July 25,	2016			
THIS	SPACE FOR FEDERAL OR STATE OFFICE US	E	12.5		
Abdulgadi Elmadan	Title PE	Date	8/02/16		
Conditions of approval of any are attached. Approval of this notice that the applicant holds legal or equitable title to those rights in the entitle the applicant to conduct operations thereon.					

(Instructions on page 2)

NOTE: THIS WELL HAS HIGH CONTENT H2S

PLUG AND ABANDONMENT PROCEDURE

July 19, 2016

Jicarilla 458 #3

East Blanco PC / Cabres	sto Canyon; Tertiary
1815' FNL, 230' FEL, Section 7, T30	N, R3W, Rio Arriba County, NM
API 30-039-24167 / Long:	/ Lat:

		API 30-039-24167 / Long: / Lat:
No	te:	All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.
	1.	This project will use an A-Plus steel tank to handle waste fluids circulated from well & cement wash up.
	2.	Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
	3.	Rods: Yes, NoX, Unknown Tubing: YesX, No, Unknown, Size2-3/8", Length3730' Packer: YesX, No, Unknown, TypeArrowset Packer at 3623' Packer: YesX, No, Unknown, TypeDouble Cup Packer @ 1722' If this well has rods or a packer, then modify the work sequence in step #2 as appropriate. PU on packer(s) and release. TOH and LD packer(s) and tubing. PU tubing workstring. Note: may need to pump extra water and scavenger due to H2S.

- 4. Plug #1 (Pictured Cliffs interval, Fruitland, Kirtland and Ojo Alamo tops, 3666'- 3085'): RU A-Plus WL. Round trip gauge ring to 3666'. RIH with 4.5" CIBP and set at 3666'. TIH with open ended tubing; tag CIBP. Mix and pump 60 sxs Class B cement (excess due to open perfs) and spot a plug from 3666' to isolate the PC interval and cover the Fruitland & Kirtland tops & Ojo Alamo perfs & top. PUH and WOC. TIH and tag cement, if necessary top off. PUH.
- Plug #2 (Nacimiento top, 1989' 1889'): Mix 15 sxs Class B cement (excess due to open perfs) and spot an underbalanced plug to cover the Nacimiento top. PUH and WOC. TIH and tag cement, if necessary top off. TOH.
- 6. Plug #3 (San Jose perforations, 1436' -1336'): TIH and set 4.5" CR at 1436'. Mix 12 sxs Class B cement and spot a plug inside the casing above the CR to isolate the San Jose interval. PUH.
- 7. Plug #4 (7-5/8" Surface casing shoe, 193' Surface): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 18 sxs cement and spot a balanced plug from 193' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing from 193' and the annulus from the squeeze holes to surface. Shut in well and WOC.
- 8. ND BOP and cut off wellhead below surface casing flange. Install P&A marker with cement to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. Cut off anchors and clean up location. Restore location per BLM stipulations.

Jicarilla 458 #3 Current

East Blanco PC/ Cabresto Canyon, Tertiary

1815' FNL & 230' FEL, Section 7-T-30-N, R-3-W , Rio Arriba County, NM

	Long:	/ Lat:	/API	30-039-24167
Today's Date: 7/19/16 Spud: 3/7/88 PC Comp: 4/13/88 OA Comp: 1/14/98 SJ Comp: 10/5/99 Elevation: 7089' GI 7107' KB	9-7/8" Hole			7-5/8" 26.4#, S-95 Casing set @ 143' Cement with 75 sxs, circulated to surface
Nacimiento @ 1939'				San Jose Perforations: 1486' – 1610' 2-3/8" 4.7# J-55 tubing at 3730' (54 jts, Double Cup Packer, 60 jts, T-2 On-Off tool, Seal nipple, Arrowset Packer, 3 jts, Profile nipple, pup jt)
				Double Cup Packer @ 1722'
Ojo Alamo @ 3135' Kirtland @ 3371' Fruitland @ 3400'				Ojo Alamo Perforations: 3163' – 3230'
Transaction & S-400		2.		Arrowset Packer @ 3623'
Pictured Cliffs @ 3713'				Pictured Cliffs Perforations: 3716' – 3790'
	6-3/4" Hole		7' TD	4.5" 10.5#/11.6#, Casing @ 3907' Cement with 425 sxs. Circulated cement to surface
		3857'	PBTD	

Jicarilla 458 #3 Proposed P&A

East Blanco PC/ Cabresto Canyon, Tertiary

1815' FNL & 230' FEL, Section 7-T-30-N, R-3-W , Rio Arriba County, NM

	Long:	/ Lat:	/ API	30-039-24167	
Today's Date: 7/19/16 Spud: 3/7/88 PC Comp: 4/13/88 OA Comp: 1/14/98	9-7/8" Hole			7-5/8" 26.4#, S-95 Ca Cement with 75 sxs,	asing set @ 143' circulated to surface
SJ Comp: 10/5/99 Elevation: 7089' GI 7107' KB					Plug #4: 193' – 0' Class B cement,18 sxs
7107 KB				Set CR @ 1436'	Plug #3: 1436' – 1336' Class B cement,12 sxs
				San Jose Perforations 1486' – 1610'	3:
Nacimiento @ 1939'					Plug #2: 1989' – 1889' Class B cement,15 sxs
Oie Alema @ 2415					Plug #1: 3666' - 3085' Class B cement, 60 sxs (excess due to open perfs
Ojo Alamo @ 3135'					
				Ojo Alamo Perforation 3163' – 3230'	s:
Kirtland @ 3371'					
Fruitland @ 3400'					
Pictured Cliffs @ 3713				Set CIBP @ 3666'	
, , , , , , , , , , , , , , , , , , , ,				Pictured Cliffs Perforat 3716' – 3790'	tions:
	6-3/4" Hole				
				4.5" 10.5#/11.6#, Cas Cement with 425 cement to s	sxs. Circulated
		4077' TD 3857' PBTD			
		0001 1010			

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: Jicarilla 458 #3

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Bring the top of plug #2 to 1849 ft. To cover the Nacimento Adjust cement volume accordingly.

Operator will run a CBL to verify cement top. Submit the electronic copy of the log for verification to the following addresses: aelmadani@blm.gov Brandon.Powell@state.nm.us

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.