Form 3160-5 (April 2004)

Subsequent Report

Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OM B No. 1004-0137 Expires March 31, 2007

4437	0	Pease Send No.	Marc
MAI	15	Lease-Serial No.	

NM4457 SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an Farmington Field Office abandoned well. Use Form 3160 - 3 (APD) for such proposals. Familing on Field Office abandoned well.

SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1. Type of Well			7. If Unit or	7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No. Schalk 57 #1E 9. API Well No.	
			8 Well Nan		
			Schalk		
3a Address		3b. Phone No. (include area code)	30-039-	22540	
P.O. Box 25825, Albuquerque, NM 87125				10 Field and Pool, or Exploratory Area Basin Dakota 11 County or Parish, State Rio Arriba County, NM	
 Location of Well (Footage, Sec., T., R., M., or Survey Description) 820' FNL & 820' FEL, Section 12, 30N, 5W 			-		
12. CHECK AT	PROPRIATE BOX(ES	TO INDICATE NATURE OF NO	ПСЕ, REPORT, OR	OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize Alter Casing Casing Repair		mation (Start/Resume)	Water Shut-Off Well Integrity Other	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filled once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Plug and Abandon

Plug Back

Schalk Development Company proposes to P&A the above well per the attached procedure.

Change Plans

Convert to Injection

OIL CONS. DIV DIST. 3

Notify NMOCD 24 hrs prior to beginning operations

AUG 18 2016

SEE ATTACHED FOR **CONDITIONS OF APPROVAL**

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

Temporarily Abandon

Water Disposal

		_
14. Thereby certify that the foregoing is true and correct Name (Printed/Typed) Jack Evans Title	Field Tech	
Signature Jack Evans Date	5-20-16	
THIS SPACE FOR FEDERAL OR	STATE OFFICE USE	
Approved by Approved by	Title PE Date 8/15/16	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office FFO	
	0.1 11 1.1	

Title I8 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)



Southwestern Region 3 Carson National Forest Jicarilla Ranger District 1110 Rio Vista Lane, Unit 2 Bloomfield, New Mexico 87413 Phone: (505) 632-2956

FAX: (505) 632-3173

Sundry Review Checklist

Plug & Abandon (P&A	Re-entry	/Sidetrack	Other:	
Schalk Develop API Number		mpany	I Name	57#1E
30-039- 22540 Footages 820 FNL,			5 w	Sec 12
Specialist Review	Review By	Review Date		Comments
Conditions of Approval (COAs)	(initial)	5/24/2016		
Archeology	RM	7/27/10	See attached	Stipulations, Pre-work
Wildlife	If m	5/24/2016	No issues -	Refer to Schalk 57 -30653) Project Record
Construction/Reclamation				
Other:				
Onsite/Field Visit Required	□No	Yes	Date Completed: _	
Original COAs apply New COAs attached				
Forest Service Concurrence	yne		15 A161	6

Lonn 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BURLAU OF LAND MANAGEMENT

RECEIVED

MAY & Personal Super March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an Farming abandoned well. Use Form 3160-3 (APD) for such proposals. Bureau of				NI-MAS7 6 Il Indust Allotte or Tribe Name gton Field Office f Land Management		
	IPLICATE- Other ins			7 If Unit of CA Agreement Name and/or No		
L. Ixpe of Well	GasWell Other			8 Well Name and No		
				Schulk 57 #11		
2 Name of Operator Schalk Deve	opment Company	1		9 API Well No		
P.O. Box 25825, Albuquerque	NM 87125	3b Phone No (meta-	de area code)	30-039-22540 10 Field and Pool on Explorators Area		
4. Location of Well. (Locatoge, Sec.)	I. R. M. or Survey Description)			Basin Dakota		
820' FN1. & 820' F11., Section	n 12, 30N, 5W			11 County or Parish State Rio Arriba County, NM		
12. CHECK A	PPROPRIATE BOX(ES) TO	O INDICATE NATU	RE OF NOTICE, I	REPORT, OR OTHER DATA		
TYPE OF SUBMISSION		TY	PE OF ACTION			
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abundon Plug Back	Production (S Reclamation Recomplete Temporarily A Water Disposal	Well Integrity Other		
determined that the vite is ready				nation. have been completed, and the operator has		
14 Thereby certify that the fore Name (Primed Typed) Jack Evans	going is true and correct	Title	Field	Tech		
Signature ac	2 Evans	Date	5-RC	Tech		
	THIS SPACE FOR	FEDERAL OR	STATE OFFICE	USE		
4	V six		Tiel	D		
Approved by Conditions of approval, if any, are certify that the applicant holds legal which would entitle the applicant to	or equitable title to those rights	does not warrant or	Title Office	Dote		
Title 18 U.S.C. Section 1001 and Title	43 USC Section 1212 make it	a crime for any person k	nowingly and willfully	to make to any department or agency of the United		

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

PLUG AND ABANDONMENT PROCEDURE

May 16, 2016

Schalk 57 #1E

Basin Dakota 820' FNL and 820' FEL, Section 12, T30N, R5W Rio Arriba County, New Mexico / API 30-039-22540 Lat: N ______/ Lat: W ______

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

- This well requires the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
- Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety
 regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on
 location. Record casing, tubing and bradenhead pressures. NU relief line and blow down
 well. Kill well with water as necessary and at least pump tubing capacity of water down the
 tubing. ND wellhead and NU BOP. Function test BOP.
- 3. Rods: Yes____, No__X__, Unknown___.
 Tubing: Yes _ X__, No___, Unknown____, Size __2-3/8 ___, Length __8145'
 Packer: Yes____, No____, Unknown_____, Type____.

 If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.
- NOTE: BLM requires a CBL log to be run on all wells where the cement did not
 circulate to surface or where a T.S. or CBL log was not previously run. This procedure
 is prepared with the understanding that it may be modified based on the TOC from the
 CBL.
- 5. Plug #1 (Dakota/Gallup perforations and top, 8073' 7895'): Round trip gauge ring or casing scraper to 8073', or as deep as possible. RIH and set 4.5" cement retainer at 8073'. Pressure test tubing to 1000 PSI. Load casing with water and circulate well clean. Pressure test casing to 1000#. If the casings do not test, then spot or tag subsequent plugs as appropriate. Circulate well clean. Mix 18 sxs Class B cement inside casing from 8073' to isolate the Dakota interval. PUH.
- Plug #2 (Gallup top, 6698' 6598'): Mix and pump 12 sxs Class B cement and spot a balanced plug inside casing to cover the Gallup top. PUH.
- 7. Plug #3 (Mancos and Mesaverde top, 5994' 5662'): Perforate squeeze holes 5994'. Attempt to establish rate if the casing pressure tested. TIH and set CR at 5944'. Mix and pump 158 sxs Class B cement, squeeze 129 sxs outside 4.5" casing and leave 29 sxs inside casing to cover through the Mesaverde top. TOH with tubing.

- 8 Plug #4 (Chacra top,4540' 4440'): Mix and pump 12 sxs Class B cement and spot a balanced plug inside casing to cover the Chacra top. PUH.
- 9. Plug #5 (Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops, 3543' 2941'): Mix and pump 50 sxs Class B cement and spot a balanced plug inside casing to cover the Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops. PUH.
- 10. Plug #6 (Nacimiento top, 1593' 1493'): Perforate squeeze holes 1593'. Attempt to establish rate if the casing pressure tested. TIH and set CR at 1543'. Mix and pump 51 sxs Class B cement, squeeze 39 sxs outside 4.5" casing and leave 12 sxs inside casing to cover the Nacimiento top. PUH.
- 11. Plug #7 (13-3/8" casing shoe, 356' 0'): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 30 sxs cement and spot a balanced plug from 356' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing from 356' and the annulus from the squeeze holes to surface. Shut in well and WOC.
- 12. ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations

Schalk 57 #1E

Proposed P&A Basin Dakota

820' FNL, 820' FEL, Section 12, T-30-N, R-5-W

Today's Date 5/11/16 Spud 11/17/80

Completed 5/11/81 Elevation 6676' GI

17.5" hole

(1989) Original Cement Squeeze 120 sxs with 2% CaCl2 from 1103' - 1118' (1999) Cement Squeeze #1 70 sxs cement from 1500' to 640' Cement Squeeze #2 34 sxs cement from 1056' to 600'. Cement Squeeze #3 with 220 sxs; circulate good cement out bradenhead from 520' to surface.

Nacimiento @ 1543'

Ojo Alamo @ 2791'

Kirtland @ 3011*

Fruitland @ 3375'

Pictured Cliffs @ 3493'

Chacra @ 4490'

Mesaverde @ 5662'

Mancos @ 5944'

Gallup @ 6648'

Dakota @ 7945'

Rio Arriba County, NM, API #30-039-22540

13-3/8" 72#, Casing set @ 306' Cement with 355 sxs, circulated

> Plug #7: 356'- 0' Class B cement, 30 sxs

CR @ 1543'

Plug #6: 1593' - 1493' Class B cement, 51 sxs 39 sxs out and 12 sxs in

Perforate @ 1593'

TOC unknown, did not circulate

Plug #5: 3543'- 2941' Class B cement, 50 sxs

Plug #4: 4540' - 4440' Class B cement, 12 sxs

DV Tool @ 5489' Stage #2: cement with 850 sxs

Set CR @ 5944'

Plug #3: 5994' - 5662'

Perforate @ 5994'

Class B cement, 158 sxs: 129 sxs out and 29 sxs in

TOC unknown, did not circulate

Plug #2: 6698' - 6598' Class B cement, 12 sxs

Set CR @ 8073'

Plug #1: 8073' - 7895'

Dakota Perforations: 8123' - 8225'

Class B cement, 18 sxs

4.5",10.5# casing set @ 8370' Stage #1: cement with 340 sxs

7.875" hole

TD 8370'

Schalk 57 #1E

Current Basin Dakota

820' FNL, 820' FEL, Section 12, T-30-N, R-5-W Rio Arriba County, NM, API #30-039-22540

Today's Date 5/11/16 Spud 11/17/80

Completed 5/11/81 Elevation 6676 GI

17 5" hole
(1989) Original Cement Squeeze 120 sxs
with 2% CaCl2 from 1103' – 1118'
(1999) Cement Squeeze #1 70 sxs
cement from 1500' to 640'
Cement Squeeze #2 34 sxs cement from
1056' to 600'
Cement Squeeze #3 with 220 sxs;
circulate good cement out bradenhead

from 520' to surface Nacimiento @ 1543'

Ojo Alamo @ 2791'

Kirtland @ 3011'

Fruitland @ 3375'

Pictured Cliffs @ 3493'

Chacra @ 4490'

Mesaverde @ 5662'

Mancos @ 5944'

Gallup @ 6648'

Dakota @ 7945'

13-3/8" 72#, Casing set @ 306' Cement with 355 sxs, circulated TOC unknown, did not circulate 2.375" J-55 tubing @ 8145' with SN @ 8102' DV Tool @ 5489' Stage #2: cement with 850 sxs TOC unknown, did not circulate Dakota Perforations: 8123' - 8225'

> 4.5',10.5# casing set @ 8370' Stage #1: cement with 340 sxs

TD 8370

7,875" hole

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: Schalk 57 #1E

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Set Plug #2 (7090-6990) ft. to cover the top of the Gallup top. BLM picks top of Gallup at 7040 ft.
 - Set Plug #3 (6490-6390) ft. inside/outside to cover the Mancos top. BLM picks top of Mancos at 6440 ft.
 - c) Bring the top of Plug #5 to 2761 ft. to cover the top of the Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops.
 - d) Bring the top of Plug #6 to 1464 ft. to cover the Nacimiento top. BLM picks top of Nacimiento at 1514 ft.

Top of the Chacra at 4486 ft. will be used for top of Mesaverde for plugging proposes (plug #4).

Operator will run a CBL to verify cement top. Outside plugs will be adjusted accordingly. Submit the electronic copy of the log for verification to the following addresses: jwsavage@blm.gov tsafe jwsavage@blm.gov tsafe jwsavage@blm.gov tsafe <a href="

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.