,	Submit 1 Copy To Appropriate District Office District I – (575) 393-6161 Et	193-6161Energy, Minerals and Natural Resourcesr., Hobbs, NM 88240OIL CONSERVATION DIVISION748-12831220 South St. Francis Dr.rtesia, NM 882101220 South St. Francis Dr.334-6178Santa Fe, NM 87410			Form C-103 Revised July 18, 2013
	District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 C			WELL API NO. 30-045-32683 5. Indicate Type of Lease	
	<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM			6. State Oil & Gas Lease No.	
	87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			Bar	or Unit Agreement Name nes Gas Com D
				8. Well Number	
	2. Name of Operator BP America Production Company	OIL CONS. DIV DIST. 3		9. OGRID Number 000778	
	3. Address of Operator 737 North Eldridge Pkwy, 12.181A	SEP 06 2016		10. Pool name or Wildcat	
	Houston, TX 77079 4. Well Location			Basin Fruitland Coal	
					West line
R	Section 24 Township 32N Range 11W NMPM County San Juan 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation 11. Elevation				
t					
6201'					
	12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ CEMPORARILY ABANDON □ CHANGE PLANS □ PULL OR ALTER CASING □ MULTIPLE COMPL □ COWNHOLE COMMINGLE □ CASING/CEMENT JOB □				EPORT OF: ALTERING CASING
	OTHER: OTHER:				
	 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. BP America Production Company respectfully requests to P&A the subject well. Please see the attached procedure. 				
	Spud Date: 04/01/2005 Rig Release Date:				
	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE OUP TITLE Regulatory Analyst DATE 08/31/2016 Type or print name Toya Colvin E-mail address: Toya.Colvin@bp.com PHONE: 281-892-5369 For State Use Only For State Use Only TITLE Deputy Oil & Gas Inspector, DATE DATE 9/20/16 APPROVED BY: By: Conditions of Approval (if any): TITLE Deputy Oil & Gas Inspector, DATE DATE 9/20/16				

August 31, 2016

NMOCD

BP would like to permanently abandon the Barnes B 21S well, as per the proposed procedure and wellbore sketches.

PLUG AND ABANDONMENT PROCEDURE Barnes GC D 001S Basin Fruitland Coal 785' FNL, 985' FWL, Section 24, T32N, R11W, San Juan County, NM API #30-045-32683

- Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.
- This project will use of a steel waste tank to contain waste fluids circulated from the well and cement wash up.
- Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
- Rods: Yes___, No_X_, Unknown___.
 Tubing: Yes X_, No___, Unknown___, Size <u>2-3/8</u>", Length <u>2862</u>'.
 Packer: Yes X_, No___, Unknown___, Type <u>Weatherford Arrow Prod Packer</u>.
 If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.
 Round trip 7" gauge ring or casing scraper to 2590' or as deep as possible.
- 4. Plug #1 (Fruitland Coal perforations and Fruitland top, 2590' 2461'): TIH and set 7" cement retainer at 2590'. Pressure test tubing to 1000#. Load casing with water and circulate well clean. Pressure test 7" casing to 800 PSI. *If casing does not test, then spot or tag subsequent plugs as appropriate*. Mix 35 sxs Class B cement and spot a plug above CR to isolate the Fruitland Coal perforations and cover the Fruitland top. PUH.
- Plug #2 (Kirtland and Ojo Alamo tops, 1437' 1212'): Mix 53 sxs cement and spot a balanced plug inside the casing to cover the Kirtland and Ojo Alamo tops. PUH.
- 6. Plug #3 (9-5/8" Surface casing, 180' Surface): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 40 sxs cement and spot a balanced plug from 180' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH

annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing and annulus from the squeeze holes to surface. Shut in well and WOC.

× #

 ND BOP and cut off wellhead below surface casing flange. Install P&A marker with cement to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. Cut off anchors and clean up location. Restore location per BLM stipulations.

Barnes GC D 001S Proposed P&A Basin Fruitland Coal

785' FNL, 985' FWL, Section 24, T-32-N, R-11-W, San Juan County, NM

.

Today's Date: 8/29/16

API #30-045-32683

