Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

RECEIVED

FORM APPROVED

OMB No. 1004-0137 Expires: July 31,2010

					1 4 6
MD	A 7	01-9	8-00	13.	Tra

abandoned well. U	se Form 3160-3 (APD) for such proposals.	Jicarilla Apache Tribe		
SUBMIT IN TRIPLICATE Type of Well	SUBMIT IN TRIPLICATE - Other Instructions on page 2			
Oil Well Gas Well Other	Nove a second to	8. Well Name and No.		
Name of Operator & Carlotte & Car	NUV 1 0 2016	Jicarilla 29-02-28 #13		
Black Hills Gas Resources, Inc. 3a. Address	3b. Phone No. (include area code)	9. API Well No. 30-039-29421		
3200 N 1st St, Bloomfield, NM 87413	(505) 634-5104	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey De		Burro Canyon Tert. / E. Blanco PC		
115' FNL & 2195' FEL NW/NE Sect	11. County or Parish, State			
8	*	Rio Arriba County, New Mexico		
12. CHECK APPROPRIATE BOX	(S) TO INDICATE NATURE OF NOTICE, REPORT, O	OR OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION				

Deepen Water Shut-off Notice of Intent Acidize Production ( Start/ Resume) Altering Casing Fracture Treat Reclamation Well Integrity Casing Repair √ Subsequent Report New Construction Recomplete Change Plans Plug and abandon Temporarily Abandon Convert to Injection Plug back Final Abandonment Notice Water Disposal 13. Describe Proposed or Completed Operation Clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.) TEMP AND MICHIGAN

Please find the attachment of the plug and abandonment report

(Instructions on page 2)

OIL CONS. DIV DIST. 3 NOV 1 0 2016

ACCEPTED FOR RECORD

w blo w

and the state of t

def - nat .

FARMINGTON FIELD OFFICE

14. I hereby certify that the foregoing	is true and correct. Name (Printed Types	d)			
Daniel Manus		Regulatory Techician I	Regulatory Techician II		
Signature Merriel	Vanus	Date November 1	2016		
	THIS SPACE	FOR FEDERAL OR STATE OFFIC			
Approved by		Title	Date		
	ched. Approval of this notice does not warn ble title to those rights in the subject lease ons thereon.				
	le 43 U.S.C. Section 1212, make it a crime		any department or agency of the United States any false,		

Black Hills Gas Resources, Inc. Jicarilla 29-02-28 #13

Section 28, T-29-N, R-2-W Rio Arriba County, NM Lease Number: MDA 701-98-0013 API #30-039-29421

Plug and Abandonment Report Notified Jicarilla BLM, BLM & NMOCD on 10/12/16

## Plug and Abandonment Summary:

- Plug #1 with 97 sxs (114.46 cf) Class B cement from 3663' to 2807' to cover the Pictured Cliffs interval, Fruitland, Kirtland and Ojo Alamo tops. Tag TOC at 2815'
- Plug #2 with 28 sxs (33.04 cf) Class B cement with 2% CaCl from 2025' to 1778' to cover the Nacimiento top. Tag TOC at 1788'.
- Plug #3 with CR at 1182' spot 24 sxs (28.32 cf) Class B cement from 1182' to 971' to cover the San Jose perfs.
- Plug #4 with 40 sxs (47.2 cf) Class B cement from 333' to surface to cover the 8-5/8" shoe and surface, circulate good cement out 5-1/2" casing valve.
- Plug #5 with 24 sxs Class B cement through poly pipe to top off casings and install P&A marker with coordinates N 36° 42′ 10″/ W 107° 2′ 48″.

## Plugging Work Details:

- 10/13/16 MIRU A-Plus #14. SITP 90 PSI, SICP 10 PSI and SIBHP 0 PSI. Blow well down. Pump 30 bbls of fresh water to kill well. Tubing on vacuum. ND wellhead. NU BOP and function test. TOH, tally 2-3/8" tubing. LD Model R packer. TIH w/ 2 3/8" tubing & plugging sub to 3663'. Pump 75 bbls total water ahead. Spot plug #1 with calculated TOC at 2807'. TOH. SI well. SDFD.
- 10/14/16 SICP 0 PSI and SIBHP 0 PSI. Function test BOP. TIH and tag TOC at 2815'. TOH to 2025'. Spot plug #2 with calculated TOC at 1778'. TOH. SI well and WOC. TIH, tag TOC at 1788'. TOH. TIH & set CR at 1182'. Sting out. Circulate well clean. Pressure test casing to 800 PSI, OK. Load bradenhead with 1/2 bbl and pressure test with 300 psi, OK. Spot plug #3 with calculated TOC at 971'. TOH. TIH open-ended to 333'. Spot plug #4 with TOC at surface. TOH. ND BOP. NU WH. SI well and SDFD.
- 10/17/16 SICP 0 PSI and SIBHP 0 PSI. Found cement down 23' in 5-1/2" casing. Cut off wellhead. Found cement down 29' in 8-5/8" casing. Spot plug #5 through poly pipe to top off casings and install P&A marker with coordinates N 36° 42' 10"/ W 107° 2' 48". RD and MOL.

Reuben Perea, Jicarilla BLM representative, was on location.