

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☒ Final Report

Name of Company: BP	Contact: Steve Moskal
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 505-326-9497
Facility Name: FLORANCE No. 035	Facility Type: Natural gas well

Surface Owner: Federal	Mineral Owner: Federal	API No. 3004509563
------------------------	------------------------	--------------------

**LOCATION OF RELEASE**

Unit Letter A	Section 18	Township 30N	Range 08W	Feet from the 1,090	North/South Line North	Feet from the 1,162	East/West Line East	County: San Juan
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	------------------

Latitude 36.81755° Longitude -107.71163°

**NATURE OF RELEASE**



Type of Release: natural gas	Volume of Release: 209 mcf	Volume Recovered: none
Source of Release: Regulator failure on separator	Date and Hour of Occurrence: 3/21/2017 @ 3:30 AM	Date and Hour of Discovery: 3/22/17 @ 9:30 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* Mechanical failure of gas regulator on separator. The separator regulator has an internal bolt that holds the diaphragm in place. That bolt backed out allowing the regulator to release the fuel supply, resulting in the release of the gas.

Describe Area Affected and Cleanup Action Taken.\* Regulator vented directly to atmosphere. No action necessary outside of repairing or replacing the regulator.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Steve Moskal	Approved by Environmental Specialist: 	
Title: Field Environmental Coordinator	Approval Date: <u>3/30/2017</u>	Expiration Date:
E-mail Address: steven.moskal@bp.com	Conditions of Approval: <u>N/F 1708951593</u>	Attached <input type="checkbox"/>
Date: March 29, 2017	Phone: 505-326-9497	

\* Attach Additional Sheets If Necessary

OIL CONS. DIV DIST. 3

MAR 30 2017