Form	31	6	0-	5
(June	20	1:	5)	

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 201

SUNDRY NOTICES AND REPORTS ON WELLS

5. Lease Serial No. NMSF080917

De satura de la forma forma de la tandella ante un anten en						
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			6. If In	6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Uı	nit or CA/Agreemen	nt, Name and/or No.	
Type of Well				8. Well Name and No. ATLANTIC B LS 4B		
2. Name of Operator Contact: TOYA COLVIN BP AMERICA PRODUCTION COMPANIMail: Toya.Colvin@bp.com				9. API Well No. 30-045-32841-00-S1		
3a. Address 501 WESTLAKE PARK BLVD. THREE ELDRIGE PLACE: 281-892-5369 HOUSTON, TX 77079			10. Fie BLA	<ol> <li>Field and Pool or Exploratory Area BLANCO MESAVERDE</li> </ol>		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. Co	11. County or Parish, State		
Sec 5 T30N R10W SESE 970FSL 690FEL 36.836011 N Lat, 107.899679 W Lon			SAN	SAN JUAN COUNTY, NM		
12. CHECK THE AI	PPROPRIATE BOX(ES) TO INDIC	CATE NATURE O	F NOTICE, REPOR	RT, OR OTHER	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Notice of Intent		☐ Production (Star	t/Resume)	Water Shut-Off	
_	☐ Alter Casing ☐ H	ydraulic Fracturing	■ Reclamation		Well Integrity	
☐ Subsequent Report		ew Construction	☐ Recomplete	_	☐ Other	
☐ Final Abandonment Notice		lug and Abandon	☐ Temporarily Ab	andon		
BY	☐ Convert to Injection ☐ P eration: Clearly state all pertinent details, inc	lug Back	☐ Water Disposal			
Attach the Bond under which the wor	ally or recomplete horizontally, give subsurfark will be performed or provide the Bond No operations. If the operation results in a mul pandonment Notices must be filed only after inal inspection.	on file with BLM/BIA	<ul> <li>Required subsequent i</li> </ul>	eports must be filed	d within 30 days	
BP requests to P&A the subject well.  MAR 2 0 2017  Please see the attached P&A procedure and required BLM reclamation plan documents.					017	
In accordance with NMOCD Pit Rule 19.15.17.9 NMAC, BP will use a closed-loop system during operations.  Notify NMOCD 24 hrs prior to beginning operations  Notify NMOCD 24 hrs prior to beginning operations						
SEE ATTACHED FOR  Operations  OPERATOR FROM OBTAINING ANY OPERATIONS AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS						
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #369007 veri For BP AMERICA PRODUCTION tted to AFMSS for processing by ABD	OMPANY, sent to	the Farmington			
Name (Printed/Typed) TOYA CO	LVIN	Title REGUL	ATORY ANALYST			
Signature (Electronic S	Submission)	Date 03/07/20	017			
	THIS SPACE FOR FEDEI	RAL OR STATE (	OFFICE USE			
Approved By ABDELGADIR ELMANDANI		TitlePETROLE	UM ENGINEER		Date 03/16/2017	
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conduction of th		ton				
	U.S.C. Section 1212, make it a crime for any statements or representations as to any matter		willfully to make to any	department or ager	ncy of the United	

DOMN MNOCD

### **BP America Production Company**

### Plug And Abandonment Procedure

### Atlantic B LS 004B

970 FSL & 690 FEL, Section 05, T30N, R10W San Juan County, NM / API 30-045-32841

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM safety and environmental regulations. Test rig anchors prior to moving in rig if not rigged to base beam.
- 2. Check casing, tubing, and bradenhead pressures.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure. Kill well as necessary. Ensure well is dead or on a vacuum.
- 4. ND wellhead and NU BOP. Function test BOP.
- 5. P/U 4-1/2" bit or casing scraper on 2-3/8" work string and round trip as deep as possible above top perforation at 4451'.
- 6. P/U 4-1/2" CR, TIH and set CR at +/- 4401'. Pressure test tubing to 1000 psi. Sting out of CR. Load hole, and pressure test casing to 800 psi. If casing does not test, then spot or tag subsequent plugs as appropriate. POOH w/ tubing.
- 7. Rig up to pump cement down tubing. Pump water to establish rate down tubing.

NOTE: All Plugs Include 100% excess outside casing and 50% Excess inside casing

## 8. Plug 1 (Mesa Verde Perforations and Formation Top 4401'-3852', 42 Sacks Class G Cement)

Mix 42 sx Class G cement and spot a balanced plug inside casing to cover Mesa Verde perforations and formation top.

### Plug 2 (Pictured Cliffs and Fruitland Formation Tops 2955'-2511', 34 Sacks Class G Cement)

Mix 34 sx Class G cement and spot a balanced plug inside casing to cover Pictured Cliffs and Fruitland formation tops.

### 10. Plug 3 (Kirtland Formation Top 2055'-1905', 12 Sacks Class G Cement)

Mix 12 sx Class G cement and spot a balanced plug inside casing to cover Kirtland formation top.

### 11. Plug 4 (Ojo Alamo Formation Top 1850'-1700', 12 Sacks Class G Cement)

Mix 12 sx Class G cement and spot a balanced plug inside casing to cover Ojo Alamo formation top.

## 12. Plug 5 (Nacimiento Formation Top 1250'-1100', 12 Sacks Class G Cement)

Mix 12 sx Class G cement and spot a balanced plug inside casing to cover Nacimiento formation top.

# 13. Plug 6 (Surface Shoe and Surface 250'-surface, 100 Sacks Class G Cement)

Attempt to pressure test the bradenhead annulus to 300 psi; note the volume to load. Perforate at 250' and attempt to circulate cement to surface filling the casing from 250' and the annulus from the squeeze holes to surface. Shut in well and WOC.

14. ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and restore location per BLM stipulations.

### **Wellbore Diagram**

Atlantic B LS 004B API #: 3004532841 San Jaun, New Mexico

Plug 6

250 ft - Surface

250 feet

100 sks of Class G

Plug 5

1250 ft - 1100 ft

150 feet

12 sks of Class G

Plug 4

1850 ft - 1700 ft

150 feet

12 sks of Class G

Plug 3

2055 ft - 1905 ft

150 feet

12 sks of Class G

Plug 2

2955 ft - 2511 ft

444 feet

34 sks of Class G

Plug 1

4401 ft - 3852 ft

549 feet

42 sks of Class G

Perforations

4451 ft - 4639 ft

4675 ft - 4722 ft

4784 ft - 4864 ft

4968 ft - 5117 ft

5140 ft - 5198 ft

5220 ft - 5264 ft

Surface

9-5/8" 32.3# @ 228 ft

Fruitland Coal - 2611 feet Pictured Cliffs - 2905 feet

Lewis - 3060 feet

Chacra - 3952 feet

Cliff House - 4406 feet

Menefee - 4726 feet

Point Lookout - 5137 feet

Mancos - 5496 feet

TOL- 2463 feet

Intermediate

7" 20# J-55 @ 2588 ft





### CORRPRO - PLUG AND ABANDON - DEEP ANODE GROUND BED

Permits: Corrpro will assist the Company in applications for permits required by any City, County and/or State agencies.


Anode Hole/Surface Casing: At the surface of the anode bed the surface casing shall be excavated or hydro-excavated at a depth of 3' below grade. All conduits and wires shall be terminated and removed. The surface casing and vent pipe will be cut down flush at 2' below grade. Anode leads, after terminated, will be left in the well bore. If the anode bore is open, a bentonite and water mixture will be poured in to backfill. A cement mixture of Portland cement shall be poured as backfill around the anode bed bore to approximately 6" above remaining surface casing. The excavation shall then be backfilled with native soil.

#### ANODE LEAD JUNCTION BOX


Removal: The anode lead junction box immediately adjacent to the deep anode will be removed along with all remaining conduits and wiring. The 4x4 post will be removed along with the concrete pad and backfilled to grade with native soil.

### **NEGATIVE/POSITIVE CABLES**

Termination of negative/positive leads will be left to the discretion of the owner.



Well name and no: Atlantic B LS 004 B API No. 30-045-32841



# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Atlantic B LS #4B

### CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
  - a) Set Plug #1 (4553'-3852') ft. to cover the Mesa Verde top. BLM picks top of Mesa Verde at 4503 ft.
  - b) Add Plug from (3684'-3584') ft. To cover the Chacra top. BLM picks to of the Chacra at 3634' ft.
  - c) Set Plug #2 (2955'-2446') ft. To cover the Fruitland top. BLM picks top of Fruitland top at 2496' ft.
  - d) Set Plug #3 (1675'-1575') ft. To cover the Kirtland Formation top. BLM picks top of Kirtland top at 1625' ft.
  - e) Set Plug #4 (1530'-1430') ft. To cover Ojo Alamo formation top. BLM picks top of the Ojo Alamo top at 1480' ft.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.