Form 3160-5 (March 2012)

RECEIVED **UNITED STATES**

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT 3 1 2017

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

5. Lease Serial No.

Contract No. 126 6. If Indian, Allottee, or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

aband	Jicarilla Apache Tribe				
SUBMIT IN	7. If Unit or CA/Agreement Name and/or No.				
Type of Well Oil Well	8. Well Name and No. Keetom Jicarilla No. 001				
2. Name of Operator		W	9. API Well No.	14 140. 001	
Enervest Operating, LLC			30-039-20203		
3a. Address 1 Fannin St., Suite 800 Houston		No. (include area code)	10. Field and Poo So. Blanco PC	l, or Exploratory Area	
4. Location of Well (Footage, Sec., Sec. 12, T24N, R04W 1850' FNL	11. County or Parish, State Rio Arriba, New Mexico				
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OF SUBMISSION		TYPE OF ACTION			
X Notice of Intent	Acidize Deepen	Production	(Start/Resume)	Water Shut-Off	
Subsequent Report	Alter Casing Fracture Tree Casing Repair New Constr	-		Well Integrity Other	
28	Change Plans X Plug and Al	bandon Temporaril	y Abandon		
Final Abandonment Notice	Convert to Injection Plug Back	Water Disp			
Attach the Bond under which the following completion of the invol	Operation: Clearly state all pertinent details, including or recomplete horizontally, give subsurface work will be performed or provide the Bond Notived operations. If the operation results in a multi-Abandonment Notice must be filed only after a	e locations and measured as b. on file with the BLM/BL tiple completion or recomp	nd true vertical de A. Required subse- letion in a new into	pths or pertinent markers and zones. quent reports must be filed within 31 erval, a Form 3160-4 must be filed c	
FnerVest Operating I.I.C resp	ectfully requests outhorization to plug and a	handon this well	OIL	CONS. DIV DIST. 3	

Please see attached Plug and Abandonment Procedure, Wellbore Diagrams and Site Reclamation Plan.

JUN 09 2017

Notify NMOCD 24 hrs prior to beginning operations

SEE ATTACHED FOR CONDITIONS OF APPROVAL BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIÉVE THE LESSEE AND **OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS** ON FEDERAL AND INDIAN LANDS

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Shelly Doescher			Age	ent			
Sitely Descrite	Title		Ag.				
Signature Shelly Worse her	Date	May 30, 2017					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by Abdelgadir [/niadani			PE	Date	6/7/17		
Conditions of approval if any are attached. Approval of this notice does not warrant or contact that the applicant holds legal or equitable title to those rights in the subject lease which w Office entitle the applicant to conduct operations thereon.							
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the Unit							

fictitious or fraudulent statements or representations as to any matter within its jurisdiction. NMOCD ~

PLUG AND ABANDONMENT PROCEDURE

May 17, 2017

Keetom Jicarilla #1

South Blanco Pictured Cliffs 1850' FNL and 790' FWL, Section 12, T24N, R4W Rio Arriba County, New Mexico / API 30-039-20203 Lat: N 36.3267/ Lat: W -107.21529 NAD 83

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

- This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
- Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety
 regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on
 location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well.
 Kill well with water as necessary and at least pump tubing capacity of water down the tubing.
 ND wellhead and NU BOP. Function test BOP.

3.	Rods:	Yes	, No_	_X, U	nknown				
	Tubing:	Yes _	X No	, Unl	(nown	, Size	1.75"	, Length _	3042'
	Packer:	Yes	, No_	_X, U	nknown	, Type _			
	If this we	ell has r	rods or a	oacker, th	en modify th	ne work s	equence in	step #2 as a	ppropriate.

- 4. NOTE: BLM requires a CBL log to be run on all wells where the cement did not circulate to surface or a CBL log was not previously run. This procedure is prepared with the understanding that it may be modified based on the TOC from the CBL.
- 5. Plug #1 (Pictured Cliffs Interval and Fruitland top, 3614' 2787'): Round trip gauge ring or casing scraper to tag existing retainer at 3614'. TIH with tubing and spot 113 sxs Class B cement (20% excess, open perfs) from existing CR to isolate the Pictured Cliffs Interval and through Fruitland interval. PUH and WOC. TI Hand tag cement 50' Fruitland top. If necessary top off Plug #1. TOH with tubing.
- 6. Plug #2 (Kirtland and Ojo Alamo tops, 2704' 2437'): Perforate HSC squeeze holes at 2704'. Establish injection rate. RIH and set CR at 2654'. TIH with tubing and sting into CR. Pressure test tubing to 1000#. Sting out of CR. Pressure test casing to 800#. If casing does not test then spot or tag subsequent plugs as appropriate. Sting into CR. Establish injection rate. Mix 115 sxs Class B cement, squeeze 79 sxs outside casing and leave 36 sxs inside casing. TOH.
- Plug #3 (Nacimiento top, 1200' 1100'): Perforate HSC squeeze holes at 1200'. Establish
 injection rate. RIH and set CR at 1150. TIH with tubing and sting into CR. Establish rate. Mix
 47 sxs Class B cement, squeeze 30 sxs outside casing and leave 17 sxs inside casing. TOH
 and LD tubing.

- Plug #4 (8.625" Surface casing shoe, 259' 0'): Perforate 3 squeeze holes at 259'. Establish circulation out bradenhead with water and circulate the BH annulus clean. Mix approximately 65 sxs Class B cement and pump down the 5.5" casing to circulate good cement to surface. Shut in well and WOC.
- ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A
 marker to comply with regulations. Record GPS coordinate for P&A marker on tower report.
 Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM
 stipulations

Keetom Jicarilla #1

Proposed P&A

South Blanco Pictured Cliffs

1850' FNL, 790' FWL, Section 12, T-24-N, R-4-W, Rio Arriba County, NM / API #30-039-20203 Lat N 36.3267 / Long W -107.21529 NAD 83

Today's Date: 5/17/17

Spud: 5/18/69

Completed: 7/12/69

Elevation: 6812' GL

12.75" hole

8.625" 24# Casing set @ 209' Cement with 150 sxs, circulated to surface

Perforate @ 259'

Plug #4: 259' - 0' Class B cement, 65 sxs:

Set CR @ 1150'

Plug #3: 1200' - 1100' Class B cement, 47 sxs: 17 inside and 30 outside

Perforate @ 1200'

Plug #2: 2704' - 2437' Class B cement, 115 sxs: 36 inside and 79 outside

Set CR @ 2654'

Perforate @ 2704'

TOC unknown, did not circulate

Plug #1: 3614' - 2787' Class B cement, 113 sxs (20% excess; open perfs)

Pictured Cliffs Perforations: 2985' - 3023'

Set Baker Model "K" retainer at 3614' (1969).

Chacra Perforations: 3859' - 3861'

5.5", 14#, Casing set @ 4107' Cement with 350 sxs

Plug #2: 4600' - 4700' 32 sxs (1969)

Plug #1: 5100' - 5200' 32 sxs (1969)

Nacimiento @ 1150'

Ojo Alamo @ 2487'

Kirtland @ 2654'

Fruitland @ 2837'

Pictured Cliffs @ 2984'

Chacra @ 3853'

7.875" hole

TD 5350 **PBTD 3614**'

Mesaverde 4627'


Mancos @ 5273'

Keetom Jicarilla #1

Current

South Blanco Pictured Cliffs

1850' FNL, 790' FWL, Section 12, T-24-N, R-4-W, Rio Arriba County, NM / API #30-039-20203 Lat N 36.3267 / Long W -107.21529 NAD 83



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Keetom Jicarilla #1

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
 - a) Set Plug #3 (1143'-1043') ft inside/outside. to cover the Nacimiento top. BLM picks top of Nacimiento at 1093' ft.

Operator will run a CBL to verify cement top. Submit the electronic copy of the log for verification to the following addresses: aelmadani@blm.gov Brandon.Powell@state.nm.us

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.