

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**OIL CONS. DIV DIST. 3** Form C-141  
Revised April 3, 2017  
AUG 14 2017  
Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company <b>Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company</b>	Contact Clara Cardoza	
Address 9a CR 5793	Telephone No. 505-326-9710	
Facility Name San Juan 27-5 Unit 3	Facility Type Well	
Surface Owner Federal Private	Mineral Owner Federal	API No. 30-039-07038

**LOCATION OF RELEASE**

Unit Letter M	Section 17	Township 27N	Range 05W	Feet from the 990	North/South Line South	Feet from the 990	East/West Line West	County Rio Arriba
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------------

Latitude 36.56909 Longitude -107.3873 NAD83

**NATURE OF RELEASE**

Type of Release Hydrocarbon/Produced Water	Volume of Release 38 bbl	Volume Recovered none
Source of Release Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 7/28/2017 @ 10:45
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith & Vanessa Fields	
By Whom? Lisa Hunter	Date and Hour 7/28/2017 @ 12:53 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*



Upon arriving at the site the field operator noticed condensate in the berm coming from the bottom of the tank which appears to be the result of corrosion. A truck was called to remove the oil from the tank in order to repair the tank.

Describe Area Affected and Cleanup Action Taken.\*

Hilcorp Energy will assess the soil within 30 days utilizing delineation by excavation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Clara Cardoza		
Title: Environmental Specialist	Approval Date: 8/17/2017	Expiration Date:
E-mail Address: ccardoza@hilcorp.com	Conditions of Approval: Sample Area MRO Include 8015/8021 Chlorides	Attached <input type="checkbox"/>
Date: 08/08/2017	Phone: 505-564-0733	

\* Attach Additional Sheets If Necessary

NVF1722936962