Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Se NMSF0	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMSF077966 6. If Indian, Allottee or Tribe Name		
						EASTERN NAVAJO 7. If Unit or CA/Agreement, Name and/or No.		
SUBMIT IN TRIPLICATE - Other instructions on page 2						892000844F 8. Well Name and No.		
1. Type of Well ☐ Oil Well Gas Well Other							ON UNIT 155	
2. Name of Operator Contact: TOYA COLVIN BP AMERICA PRODUCTION CO E-Mail: Toya.Colvin@bp.com						9. API Well No. 30-045-07269-00-S1		
 3a. Address 200 ENERGY COURT FARMINGTON, NM 87401 				3b. Phone No. (include area code) Ph: 281.366.7148		10. Field and Pool or Exploratory Area BASIN DAKOTA		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State			
Sec 23 T28N R13W SESW 0990FSL 1700FWL 36.643200 N Lat, 108.191150 W Lon					SAN JU	SAN JUAN COUNTY, NM		
12. C	HECK THE AF	PROPRIATE BOX(ES)	TO INDICA	ATE NATURE O	F NOTICE, REPORT,	OR OTHE	R DATA	
TYPE OF SUBMISSION TYPE OF ACTION					ACTION			
Notice of Inte	ent	□ Acidize	Dec Dec	epen	Production (Start/Re	esume)	□ Water Shut-Off	
Subsequent F		□ Alter Casing		draulic Fracturing	□ Reclamation		U Well Integrity	
		Casing Repair	_	w Construction	□ Recomplete		□ Other	
Final Abando			 Temporarily Abando Water Disposal 	on				
Attach the Bond u following comple testing has been c determined that th	inder which the wor tion of the involved ompleted. Final At the site is ready for final o P&A the subje	Illy or recomplete horizontally k will be performed or provide operations. If the operation re andonment Notices must be final inspection. ct well. Please see the at	e the Bond No. o esults in a multip led only after all	on file with BLM/BIA ble completion or reco l requirements, includ	. Required subsequent report mpletion in a new interval, a ing reclamation, have been c e required BLM	rts must be file a Form 3160-4	ed within 30 days must be filed once the operator has / DIST. 3	
In accordance	with NMOCD P	it Rule 19.15.17.9 NMAC), BP will use	a closed-loop sys	stem during operations	AUU	Lond	
SEE ATTACHED FOR CONDITIONS OF APPROVAL				BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS Notify NMOCD 24 hrs prior to beginning operations				
14. I hereby certify t		Electronic Submission # For BP AMERIC	A PRODUCTIO	N CO, sent to the	Farmington			
Committed to AFMSS for processing by ABDEL Name (Printed/Typed) TOYA COLVIN				GADIR ELMADAN	I on 08/16/2017 (17AE01 ATORY ANALYST	01SE)		
Signature (Electronic Submission)				Date 08/15/20	Date 08/15/2017			
		THIS SPACE F	OR FEDER	AL OR STATE	OFFICE USE			
Approved By_ABDELGADIR ELMADANI					JM ENGINEER		Date 08/16/20	
	Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.							
certify that the applicant	nt holds legal or equ e applicant to condu	ct operations thereon.	e subject lease	Office Farming	on			

-



BP America

Plug And Abandonment Procedure

GCU 155

990' FSL & 1700' FWL, Section 23, T28N, R13W

San Juan County, NM / API 30-045-07269

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM safety and environmental regulations. Test rig anchors prior to moving in rig if not rigged to base beam.
- 2. Check casing, tubing, and bradenhead pressures.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure. Kill well as necessary. Ensure well is dead or on a vacuum.
- 4. ND wellhead and NU BOP. Function test BOP.
- 5. P/U 4 ¹/₂" bit or casing scraper on 2-3/8" work string and round trip as deep as possible above top perforation at 6315'.
- 6. P/U 4 ½" CR, TIH and set CR at +/- 6265'. Pressure test tubing to 1000 psi. Sting out of CR. Load hole, and pressure test casing to 800 psi. If casing does not test, then spot or tag subsequent plugs as appropriate. POOH w/ tubing.
- 7. Rig up to pump cement down tubing. Pump water to establish rate down tubing.

NOTE: All Plugs Include 100% excess outside casing and 50% Excess inside casing

8. Plug 1 (Dakota Perforations and Dakota Formation Top 6265'-6215', 12 Sacks Class B Cement)

Mix 12 sx Class B cement and spot a balanced plug inside casing to cover Dakota perforations and formation top.

9. Plug 2 (Gallup Formation Top 5410'-5260', 12 Sacks Class B Cement)

Mix 12 sx Class B cement and spot a balanced plug inside casing to cover Gallup formation top.

10. Plug 3 (Mancos Formation Top 4540'-4390', 12 Sacks Class B Cement)

Mix 12 sx Class B cement and spot a balanced plug inside casing to cover Mancos formation top.

11. Plug 4 (Mesa Verde and Chacra Formation Tops 2680'-2300', 30 Sacks Class B Cement)

Mix 30 sx Class B cement and spot a balanced plug inside casing to cover Mesa Verde and Chacra formation tops.

12. Plug 5 (Pictured Cliffs Formation Top 1770'-1620', 12 Sacks Class B Cement)

Mix 12 sx Class B cement and spot a balanced plug inside casing to cover Pictured Cliffs formation top.

13. Plug 6 (Surface Shoe and Surface 364'-surface, 125 Sacks Class B Cement)

Attempt to pressure test the bradenhead annulus to 300 psi; note the volume to load. If BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 125 sx cement and spot a balanced plug from 364' to surface, circulate good cement out of casing valve. TOH and LD tubing. Shut well in and WOC. If BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the

casing from 364' and the annulus from the squeeze holes to surface. Shut in well and WOC.

14. ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and restore location per BLM stipulations.



Wellbore Diagram

GCU 155 API #: 3004507269 San Juan, New Mexico

Surface Casing

8-5/8" 24# @ 364 ft

<u>Plug 6</u> 364 ft - Surface 125 sks of Class B

<u>Plug 5</u> 1770 ft - 1620 ft 150 ft plug 12 sks of Class B

<u>Plug 4</u> 2680 ft - 2300 ft 380 ft plug 30 sks of Class B

<u>Plug 3</u> 4540 ft - 4390 ft 150 ft plug 12 sks of Class B


<u>Plug 2</u> 5410 ft - 5260 ft 150 ft plug 12 sks of Class B

<u>Plug 1</u> 6265 ft - 6215 ft 50 ft plug 12 sks of Class B Formation Lewis - 1910 feet MesaVerde - 2630 feet Mancos - 4490 feet Gallup - 5360 feet Lower Gallup - 5720 feet Greenhorn - 6190 feet Graneros Shale - 6250 feet Graneros Dakota - 6312 feet Dakota - 6377 feet

Retainer Set at 6265 ft

Production Casing

4.5" 10.5# @ 6475 ft



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE 6251 COLLEGE BLVD.

FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Gallegos Canyon Unit # 155

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

- a) Set Plug #4 (2680'-2182') ft to cover the Chacra top. BLM picks top of Chacra at 2232' ft.
- b) Add Fruitland Plug (1470'-1370') ft to cover the Fruitland top. BLM picks Fruitland tops at 1420ft.
- c) Add Kirtland Plug (529'-429') ft to cover Kirtland top. BLM picks Kirtland tops at 479ft.
- d) Set Plug #6 (409'-0') ft to cover Ojo Alamo top. BLM picks Ojo Alamo tops at 359ft.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.