Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMSF077764 6. If Indian, Allottee or Tribe Name			
	TRIPLICATE - Other ins				7. If Unit or CA/Agree		
1. Type of Well					8. Well Name and No.	2	
☐ Oil Well ⊠ Gas Well ☐ Oth 2. Name of Operator		HOLLY WO			9. API Well No.		
SOUTHLAND ROYALTY COM	MPANY LE-Mail: hwood@n	nspartners.com			30-045-09441-0	0-S1	
3a. Address 400 W 7TH STREET FORT WORTH, TX 76102	400 W 7TH STREET Ph: 817-33						ry Area
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description	n)			11. County or Parish, State		
Sec 17 T30N R10W SWSW 0 36.806671 N Lat, 107.912979			SAN JUAN COUNTY, NM			IM	
12. CHECK THE AF	PPROPRIATE BOX(ES)) TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DA	TA
TYPE OF SUBMISSION			TYPE OF	ACTION			
Notice of Intent	□ Acidize	Dee	pen	Product	tion (Start/Resume)	🗖 Wa	ter Shut-Off
Subsequent Report	□ Alter Casing		raulic Fracturing	Reclam		-	ll Integrity
	Casing Repair	_	Construction	Recomp		Oth Oth	ier
☐ Final Abandonment Notice	 Change Plans Convert to Injection 		g and Abandon				
SEE ATTACHED PLUG AND Notify NMOCD : prior to begins operations	24 hrs ning DFERATOR	OVAL OR ACC	EPTANCE OF TH WE THE LESSEN NING ANY OTH RED FOR OPER-	HIS AND R	OIL CONS. DI FEB- 1-3 2	V DIS	r. 3
14. I hereby certify that the foregoing is							
	Electronic Submission # For SOUTHLAND RO	OYALTY COMP	ANY LLC, sent to	the Farmin	gton		
Committed to AFMSS for processing by JA Name (Printed/Typed) ROBBIE A GRIGG			Title SUPVR REGULATORY REPORTING				
Signature (Electronic S	Submission)		Date 01/29/20	018			
	THIS SPACE F	OR FEDERA	L OR STATE	OFFICE U	SE		
Approved By JACK SAVAGE		TitlePETROLEUM ENGINEER Date 02/09/20			Date 02/09/2018		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a statements or representations as	a crime for any po s to any matter w	erson knowingly and		ake to any department or	agency of	the United
(Instructions on page 2) ** BLM REV	ISED ** BLM REVISE	D ** BLM RI		IREVISE) ** BLM REVISEI) **	

ß

U



Southland Royalty Company Plug & Abandon Procedure

September 12, 2017

Well:	Schumacher #12	API:	3004509441
Location:	800 FSL & 800 FWL	Field:	Dakota
Sec, T, R:	Sec. 17, T30N, R10W	Elevation:	GL: 6455
Cnty/State:	San Juan County, NM		
Lat/Long:	36.806483,-107.9135437	By:	Aztec Well Servicing

Objective:

Permanently plug & abandon the well from 7,247' to surface containing 6 separate cement plugs.

Prior to Rig:

- 1. Notify BLM & NMOCD
- 2. Note: verify all cement volumes based on actual slurry to be pumped.
- 3. See attached COA's from BLM & NMOCD.

Procedure:

- 1. MIRU unit and cementing equipment
- 2. ND WH, NU BOP stack, RU rig floor and 2 3/8" handling tools
- 3. LD production string, Tally & TIH work string / 4 $\frac{1}{2}$ " CSG scraper to 7260' TOOH
- 4. TIH w/4 $\frac{1}{2}$ " CICR and set @ 7247', test TBG, roll well & Test CSG. (WOC to be determined if test holds, note prior squeezes)
- 5. Plug #1, 7078' 7247' (Dakota perfs: 7297'-7400', DK Top: 7382', Graneros Top: 7238', Greenhorn Top: 7178'): Sting out of retainer, mix & pump 15 sxs (17.7 cf) of Class B cement (or equivalent), leaving 169' of cement on top of retainer to cover Dakota, Graneros and Greenhorn tops.
- 6. Pull above cement & reverse TBG clean. If required, run CBL.
- 7. WOC, TIH & tag TOC, re-spot if necessary
- 8. LD TBG to 5476'
- 9. Plug #2, 5326' 5476' (Mancos Top: 5426'): Pull up to 5476'. Mix and pump 15 sx (17.7 cf) of cement in a balanced cement plug from 5476' 5326'.
- 10. Pull above cement and reverse circulate to clean out tubing.
- 11. WOC, TIH & tag TOC, re-spot if necessary
- 12. LD TBG to 4590'
- 13. Plug #3, 4440' 4590' (Mesaverde Top: 4540'): Pull up to 4590'. Mix and pump 15 sx (17.7cf) of cement in a balanced cement plug from 4590' 4440'.
- 14. Pull above cement and reverse circulate to clean out tubing.
- 15. WOC, TIH & tag TOC, re-spot if necessary



Southland Royalty Company Plug & Abandon Procedure

September 12, 2017

Well:	Schumacher #12	API:	3004509441
Location:	800 FSL & 800 FWL	Field:	Dakota
Sec, T, R:	Sec. 17, T30N, R10W	Elevation :	GL: 6455
Cnty/State:	San Juan County, NM		
Lat/Long:	36.806483,-107.9135437	By:	Aztec Well Servicing

16. LD TBG to 3040'

- 17. Plug #4, 2890' 3040' (Pictured Cliffs Top: 2909'): Pull up to 3040'. Mix and pump 15 six (17.7cf) of cement in a balanced cement plug from 3040' 2890'.
- 18. Pull above cement and reverse circulate to clean out tubing.
- 19. WOC, TIH & tag TOC, re-spot if necessary
- 20.LD TBG to 1622'
- 21. Plug #5, 1472' 1622' (Ojo Alamo Top: 1572'): Pull up to 1622'. Mix and pump 15 sx (17.7 cf) of cement in a balanced cement plug from 1622' 1472'.
- 22. Pull above cement and reverse circulate to clean out tubing.
- 23. WOC, TIH & tag TOC, re-spot if necessary
- 24. LD all TBG
- 25. Plug #6, (9-5/8" Surface casing shoe, 350' to Surface): If required by BLM, Perforate at 350' and attempt to establish circulation to surface out the bradenhead valve (note: circulated cement to surface on primary surface casing cement job). Mix approximately 100 sxs (118 cf) of cement and pump down the 5-1/2" casing to circulate out the bradenhead casing valve. If unable to circulate, top off as necessary.
- 26. Mobilize unit and equipment to next well




Southland Royalty Company Plug & Abandon Procedure

September 12, 2017

Well:	Schumacher #12		API:	3004509441	
Location:	800 FSL & 800 FWL	F	Field:	Dakota	
Sec, T, R:	Sec. 17, T30N, R10W	E	Elevation:	GL: 6455	
Cnty/State:	San Juan County, NM				
Lat/Long:	36.806483,-107.9135437	7	Ву:	Aztec Well Serv	icing
	Date: 9/7/17 Elevation: 6370' GL		Plug #S: Su Class B cer	inf to 350' ment, 100 ax (118 cf)	
	KB: 6380' (10' KB) Hole Size: 13-3/4"		9-5/8", 36#.	J55 Casing set @ 301"	
				200 axa, circulated cmt to a	surf
	Hole Size	0			
	7-7/8" Ojo Alamo @ 1572"		Plug #5: 14	77 - 1077	
	Of Marine & 1012			ment, 15 ax (17.7 cf)	
	Fruitland @ 2580'		TOC - 1675		
			Plug #4: 28	90' - 3040'	Note: Previous Squeeze Jobs
	Pictured Cliffs @ 2909'			ment, 15 ax (17.7 cf)	3503'- 3800' 4/14/2011 3709'-3800'
	Lewis @ 2990'	-	DV tool - 30	75	370 sx under CICR
			Plug #3: 44	40' - 4590'	4/18/2011 3562'-3797'
				ment, 15 ax (17.7 cf)	15 sx Hesitate squeeze
	Cliff House @ 4540'		TOC - 4610		4/20/2011 3503-3797
	Menefee @ 4722'				20 sx Hesitate squeeze
	Point Lookout @ 5164		Plug #2: 53	20 - 5470	4/22/2011 3532-3797
	Mancos @ 5426"			ment, 15 ax (17.7 cf)	20 sx Hesitate Squeeze
	Gallup @ 6443"	State of Lot of Links	DV tool - 54	91	
	compt & arris				Whipstock: 4601' 6/17/1962'
					Lost DC's while drilling well
				1.1.1	
· •			TOC - 6960	r	
	Greenhorn @ 7178*		CICR set at		
	Graneros @ 7238'		Plug #1: 70 Class B cer	78' - 7247' nent, 15 sx (17.7 cf)	
				many is an first of	
	Dakota @ 7382' O	00	Dakota Perfs:	7297 - 7400'	
	¥				
				11.6#, casing set @ 7541'	
		PBTD: 7502'		ax (TOC - 6960')	
		TD: 7541"		0 ax (TOC - 4610') 5 ax (TOC - 1675')	
			and another office	and the start	

Page 3 of 3



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE 6251 COLLEGE BLVD.

FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Shumacher #12

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

3. The following modifications to your plugging program are to be made:

- a) Add a cement plug (6490 6390) ft. inside/outside to cover the Gallup top. BLM picks top of Gallup at 6440 ft. Adjust cement volume accordingly.
- b) Set Plug #2 (5710 5610) ft. inside/outside to cover the Mancos top. BLM picks top of Mancos at 5660 ft.
- c) Add Plug (3701 3601) ft. inside/outside to cover the Chacra top. BLM picks top of Chacra at 3651 ft. Adjust cement volume accordingly.
- d) Set Plug #4 (2946 2846) ft. inside/outside to cover the Pictured Cliffs top. BLM picks top of Pictured Cliffs at 2896 ft.
- e) Add a cement plug (2630 2530) ft. inside/outside to cover the Fruitland top. BLM picks top of Fruitland at 2580 ft. Adjust cement volume accordingly.
- f) Set Plug #5 (1710 1515) ft. inside/outside to cover the Ojo Alamo and Kirtland tops. BLM picks top of Kirtland at 1660 ft. BLM picks top of Ojo Alamo at 1565 ft.

Operator must run CBL to surface to identify TOC. Submit the electronic copy of the log for verification to the following addresses: jwsavage@blm.gov Brandon.Powell@state.nm.us

 H_2S has not been reported at this location, however, *High to Very High concentrations of* H_2S (180 – 500 ppm GSV and 800 ppm STV) have been reported in several wells within a 1 mile radius of this location. It is imperative that H_2S monitoring and safety equipment be on location during plugging operations at this location.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.