Form 3 160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135 Expires Jnovember 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or reenter an

Jicarilla Contract 77 6. If Indian, Allottee or Tribe Name

5. Lease Serial No.

abandoned wen. Use Form \$100-5 (AFD) for such proposals.				Jicarilla Apache Tribe	
SUBMIT IN TRIPLICATE – Other instructions on reverse side				7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Oil Well Gas Well Other				8. Well Name and No.	
2. Name of Operator			AXI Apache A-5		
DJR Operating, LLC				9. API Well No.	
3a. Address		3b. Phone No. (include area code) (303) 595-7433		30-039-05124	
1600 Broadway, Suite 1960 Denver, CO 80202				10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Ballard Pictured Cliffs		
Unit Letter A, Sec 9, T23N, R5W 800' FNL & 940' FEL			11. County or Parish, State		
				Rio Arriba, NM	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Reclamation Recomplete	te Other	

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days Following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection. determined that the site is ready for final inspection.)

DJR Operating, intends to permanently plug and abandon the AXI Apache A-5 as per the attached procedure.

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND **OPERATOR FROM OBTAINING ANY OTHER** AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

SEE ATTACHED FOR CONDITIONS OF APPROVAL

Notify NMOCD 24 hrs prior to beginning operations

14. Thereby certify that the foregoing is true and correct					
Name (Printed Typed) Ray Granillo	Agent for DJR Operating, LLC				
Signature	Date March 12, 2018				
THIS SPACE FOR FEDERAL OR STATE USE					
Approved by	Title Date 3/22/18				
Conditions of approval, if any, are attached. Approval of this notice does not warrecrify that the applicant holds legal or equitable title to those rights in the subject	ant or lease Office				

Title 18 U.S.C. Section 1001, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.













DJR Operating Plug & Abandon Procedure February 28, 2018

Well:

AXI Apachi A#5

800' FNL & 940' FEL

Location: Sec,T, R:

Sec. 28N, T23N, R5W

Cnty/State:

Rio Arriba, NM

Lat/Long:

36.24526,-107.36059

Elevation:

API:

Field:

30-039-05124

Picture Cliffs

GL:6,684' KB:

By:

Aztec Well Servicing

Objective:

Permanently plug & abandon the well from 2,257' to surface containing 4 cement plugs.

Prior to Rig:

1. Notify BLM & NMOCD

2. Note: verify all cement volumes based on actual slurry to be pumped.

3. See attached COA's from BLM & NMOCD.

Procedure:

- 1. MIRU well servicing rig and cement equipment.
- 2. ND WH, NU BOPE, RU rig floor and 1.66" handling tools.
- 3. LD production string.
- 4. Tally, PU & RIH with 2-3/8" work string and 5-1/2" casing scraper to 2,110'.
- 5. TOOH & lay down casing scraper. TIH w 5 1/2" CICR and set at 2,096'.
- 6. Test TBG to 1000 psi, sting out, roll well & test casing. (WOC to be determined if test holds).
- 7. Plug #1, 2046' 2096' (PC top: 2146', Perfs: 2146' 2162'): Mix & pump 6 sxs of Class B cement (or equivalent) to plug off Pictured Cliffs perfs. Sting out of CICR leaving 50' of cement on top of retainer. Circulate hole clean. If required by BLM, run CBL (note: circulated cement to surface on primary cement job).
- 8. Plug #2, 1425' 1575' (Kirtland Top: 1500'): Spot 18 sxs Class B cement in a balanced plug inside casing to cover Kirtland top. PUH. WOC. TIH to confirm top of plug. Re-spot if necessary.
- Plug #3, 825' 975' (Ojo Alamo Top: 900'): Spot 18 sxs Class B cement in a balanced plug inside casing to cover Ojo Alamo top. PUH. WOC. TIH to confirm top of plug. Re-spot if necessary.
- 10. **Plug #4, (146' to Surface):** Mix approximately 17 sxs of cement. Spot the surface plug to cover a minimum of 50' to surface and top off as necessary.
- 11. ND BOP and cut off wellhead below surface casing flange per regulation. Install P&A marker with cement to comply with regulations. RD, MOL and cut off anchors. Restore location per BLM stipulations.















DJR Operating Plug & Abandon Procedure February 28, 2018

Well:

AXI Apachi A#5

Location:

800' FNL & 940' FEL Sec. 28N, T23N, R5W

Sec,T, R: Cnty/State:

Rio Arriba, NM

Lat/Long:

36.24526,-107.36059

API:

30-039-05124

Field:

Picture Cliffs

Elevation:

GL:6,684' KB:

By:

Aztec Well Servicing

AXI APACHE A 5

Proposed P&A

Ballard Pictured Cliffs 800' FNL & 940' FEL, Section 28, T23N, R5W, Rio Arriba, NM API 30-039-05124 Spud: 9/23/1959 Procedure Date: 2/28/2018

All other water bearing zones

Surface Plug: 0-146' 17 sxs Class B

Surface Csg: 8-5/8" 24#

Prod Csg: 5-1/2" 14#

8-5/8" Set @ 96' Cmt w/ 70 sxs Circulated cmt to surf

Ojo Top: 900'

PLUG 3: 825- 975'

18 sxs Class B

Kirtland Top: 1500'

PLUG 2: 1425-1575' 18 sxs Class B

PC Top: 2146'

PLUG 1: 2046- 2096'

PC Perfs: 2146-2162'

Set CICR @ 2096' 6 sxs Class B

5-1/2" csg set @ 2257' Cemented w/ 100 sxs TOC ?

PBTD: 2257' TD: 2257'

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: AXI Apache A 5

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Set plug #1 (2096-1950) ft. to cover the PC perfs and Fruitland top. BLM picks top of Fruitland at 2000 ft.
 - b) Set plug #2 (1828-1597) ft. to cover the Kirltand and Ojo Alamo tops. BLM picks top of Kirltand at 1778 ft. BLM picks top of Ojo Alamo at 1647 ft.
 - c) Set plug #4 (220-0) ft. to cover the shoe and the Nacimiento top. BLM picks top of Nacimiento at 170 ft.

Operator must run CBL to surface to identify TOC. Submit the electronic copy of the log for verification to the following addresses: jwsavage@blm.gov Brandon.Powell@state.nm.us

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.