Form 3160-5 (June 2015)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5.	Lease Serial No.	
	NMNM03358	

6	If	Indian	Allottee	or	Tribe	Name
Ο.	11	mulan,	Allonee	OI	THE	rvaime

SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No.					
Type of Well     Oil Well	8. Well Name and No. NEBU 604 COM 2H					
Name of Operator     BP AMERICA PRODUCTION		9. API Well No. 30-045-35794-00-X1				
3a. Address PO BOX 3092 HOUSTON, TX 77253		No. (include area code) 892.5369				
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)	· ·		11. County or Parish,	State	
Sec 13 T31N R7W SWNW 18 36.901585 N Lat, 107.529243				SAN JUAN COL	UNTY, NM	
12. CHECK THE AF	PPROPRIATE BOX(ES) TO INDIC	CATE NATURE O	F NOTICE,	REPORT, OR OTH	HER DATA	
TYPE OF SUBMISSION	ACTION	-	3			
□ Notice of Intent		Deepen	_	on (Start/Resume)	☐ Water Shut-Off	
Subsequent Report     ■     Subsequent Report     Subsequent Report		Iydraulic Fracturing	☐ Reclama		☐ Well Integrity	
		New Construction	Recomp		☑ Other Drilling Operations	
☐ Final Abandonment Notice		lug and Abandon	-	arily Abandon	Diming operations	
19F	☐ Convert to Injection ☐ I	lug Back	☐ Water D	Pisposal		
Please see the attached remedial cement operations performed on the subject well March 2018.  NMOCD  APR 0 5 2018						
		DI	STRICT	111		
14. I hereby certify that the foregoing is  Con Name (Printed/Typed) TOYA CO	Electronic Submission #407580 ver For BP AMERICA PRODUC mmitted to AFMSS for processing by	TION CO, sent to the JACK SAVAGE on 0	Farmington	JWS0106SE)		
		1,200				
Signature (Electronic S	Submission)	Date 03/13/2	018			
	THIS SPACE FOR FEDE	RAL OR STATE	OFFICE US	SE		
Approved By ACCEPT	ED	JACK SAV TitlePETROLE		ER	Date 03/27/2018	
	d. Approval of this notice does not warrant uitable title to those rights in the subject leas act operations thereon.		ton			
	U.S.C. Section 1212, make it a crime for an statements or representations as to any matter		willfully to ma	ke to any department or	agency of the United	
(Instructions on page 2) ** BLM REV	ISED ** BLM REVISED ** BLM	REVISED ** BLN	N REVISED	** BLM REVISE	D **	

## NEBU 604 Com 2H REMEDIAL CEMENT OPS Report

## February-March 2018

02/28/18 - MIRU to location; test BOP; RU WL and set RBB at 6341' inside 5 1/2" liner

03/01/18 - Press test RBP @ 1000 psi - OK; dump 40' of sand on top of RBP

03/02/18 - RIH w/ work string; tag TOS @ 6303'; pull up to 6281'; spot 3 bbl of cement (15.8 ppg; 1.154 cft/sk); pull up to 6095' and reverse clean; POH; MU and round trip 8 %" string mill to 3558'; RU WL and perforate 4 shots at 3520' and 4 shots at 2462'; RD WL

03/03/18 - MU packer; RIH and set at 2503'; break circulation through lower perfs and up the upper perfs; release and POH w/ packer

03/04/18 – RU WL and RIH w/ CR; set CR at 3450'; RU cement crew; circulate down work string and up the upper perfs; pump 30 bbl chem wash; 10 bbl fresh water spacer; 78.7 bbl 12.4 ppg (1.947 cft/sk) lead slurry and 25 bbl 15.8 ppg (1.154 cft/sk) at 4 bpm; displace cement w/ 15 bbl fresh water; sting out of retainer and pull up 16'; start circulation – got cement returns at 240 bbl pumped – 10 bbl cement back; circ clean; Pull up to 2502' – spot 10 bbl cement plug (15.8 ppg; 1.154 cft/sk); POH w/ work string; start hesitation squeeze – displaced 2.5 bbl at 600 psj; WOC

03/05/18 - WOC

03/06/18 - MU drill out BHA; RIH to TOC at 2366'; break circulation and drill out cement to 2502'; fall through and circulate clean

03/07/18 - RIH and tag cement on top of retainer at 3431'; pressure test upper squeeze hole to 500 psi for 10 min – good test; POH drill string & BHA; RU WL and run CBL from 3430' to 2320' – log shows isolation between zones; submitted log and press test chart to NMOCD and BLM; received approval to continue with operations; RIH w/ drilling BHA and drill out cement, retainer and cement below it; fall through at 3521'; circulate clean; pressure test casing to 500 psi for 30 min – good test

03/08/18 – RU WL and run CBL from 3430' to 2320' – log shows isolation between zones; submitted log and press test chart to NMOCD and BLM; received approval to continue with operations; RIH w/ 8.75 bit and 8.5 string mill – tag at 5975'- clean out to 6037' (TOL); circulate clean; POH; Pick up sealbore polishing mill and RIH inside liner hanger – tag no go at 6037; circulate clean; started to POH butgot hang up 15' up from liner top; work tubing free and attempt to get back into liner – 6 ft short of original depth; POH w/ polishing assembly

03/09/18 – RIH w/ 4 ½" bit on 2 ½" tubing to 6073'; clean out to 6083'; circulate well clean; POH; RIH w/ sealbore polishing mill to no go; pull up above liner top and circulate; work polishing mill in and out of sealbore several times; POH and lay down polishing mill assembly; RU and RIH w/ tieback string – DV tool installed above seal assembly; sting into liner hanger; pressure test seal assembly to 2200' psi and monitor for 10 min – good test; pressure up to 2812 psi and open DV tool; pump 10 bbl fresh water; 170 bbl lead slurry (12.6 ppg; 465 sk, 1.84 cfl/sk) and 158 bbl tail slurry (13.5 ppg, 640 sk, 1.3 cfl/sk); drop closing plug and displace cement with 132 bbl water; bump plug at 3500 psi; monitor for 5 min; release pressure – DV tool closed; 21 bbl slurry return to surface; RD cement equipment; set casing in slips and energize slips; cut off pipe; NU WCE; WOC 8 hrs; RIH w/ 4.5 bit; drill out stage tool @ 6032'; RIH and wash down to top of RBP @ 6320'; circulate clean; POH drilling BHA;

03/10/18 – RIH w/ retrieving head; clean out sand on top of RBP; release RBP and POH; ND BOP; NU 13 %" x5" 10K tubing head; NU 5" 10K frac valve; RD service unit

