						RECEIVED			
Form 3160-5 (August 2007)						MAY 1 4 FORMAPPROVED OMB No. 1004-0137 Expires: July 31, 2010			
						5. Lease Serial No. Field Office Farmington Field Office			
	SUNDRY NOTICES AND REPORTS ON WELLS					Bureau of Land Manac 6.11 Indian, Allottee or Tribe	ioment Name		
	Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.								
<u></u>	SUBMIT IN TRIPLICATE - Other instructions on page 2.					7. If Unit of CA/Agreement,	Name and/or No.		
1. Type of Well	Type of Well								
	Oil Well X Gas Well Other					8. Well Name and No. South BI	South Blanco Federal 6 4		
2. Name of Ope	2. Name of Operator DJR Operating, LLC					9. API Well No. 30-6	039-22586		
3a. Address	3a. Address 3b. Phone No. (include				area code) 10. Field and Pool or Exploratory Area				
	lus WS, Farming			505-486-6	5958	Lybrook Gallup Ext.			
4. Location of		,R.,M., or Survey Description) ' FNL & 2310' FWL, UL - (C, Sec	c. 6, T23N, R7	N	11. Country or Parish, State Rio Arriba	, NEW MEXICO		
	12. CHECK	THE APPROPRIATE BOX(ES	S) TO	INDICATE NAT	URE OF N	OTICE, REPORT OR OT	HER DATA		
TYPE OF	TYPE OF SUBMISSION					TYPE OF ACTION			
X Notice	of Intent	Acidize		Deepen		Production (Start/Resume)	Water Shut-Off		
Subsequ	ent Report	Alter Casing Casing Repair		Fracture Treat New Construction		Reclamation Recomplete	Well Integrity Other		
	BK	Change Plans	=	Plug and Abandon		Temporarily Abandon			
	bandonment Notice	Convert to Injection		Plug Back		Water Disposal starting date of any proposed work and approximate duration thereof.			
DJR C	s been completed. Fin I that the site is ready 1 Operating, LLC r	Aved operations. If the operation real Abandonment Notices must be find for final inspection.) requests permission to plant the second	ed only	y after all requireme	nts, including	reclamation, have been comple	eted and the operator has		
		No	rior t	MOCD 24 hrs o beginning erations					
SEE ATTACHED FOR CONDITIONS OF APPROVAL					BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS				
		JUN		2018					
14. I hereby certify that the foregoing is true and correct. Name Sine article and some of the second secon					Engineer Tech				
		7. 1					<u> </u>		
Signature	unlenn-	Date	5/14/2018 Date						
		THIS SPACE FO	DR FE	DERAL OR S	TATE OF				
Approved by	Work Cu	INDA			Title	PE	Date 5/31/198		
Conditions of approval, if any, are attached Approval of this notice does not warrant of that the applicant kolds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon.					Office	•			
	or fraudulent statemen	43 U.S.C. Section 1212, make it a ts or representations as to any matter			ingly and wil	fully to make to any departmen	t or agency of the United States ar		

NMOCD	R
-------	---

PLUG AND ABANDONMENT PROCEDURE

April 30, 2018

South Bianco 6 #4


Lybrook Gallup Ext. 330' FNL, 2310' FWL, Section 6, T23N, R7W, Rio Arriba County, New Mexico API 30-039-22586 / Long _____ / _____

- Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class G, mixed at 15.8 ppg with a 1.15 cf/sx yield.
 - 1. This project will use an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
 - Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
 - 3. Rods:
 Yes_X
 No _____,
 Unknown_____.


 Tubing:
 Yes_X
 No _____,
 Unknown_____,
 Size ______.

 Packer:
 Yes_____,
 No X
 Unknown_____,
 Type ______.
 - 4. Plug #1 (Gallup perforations and top, 5309' 5209'): R/T 4.5" gauge ring or mill to 5309'. RIH and set 4.5" CR at 5309'. Pressure test tubing to 1000#. Circulate hole clean. <u>Attempt to pressure test casing to 800#. If casing does not test then spot or tag subsequent plugs as necessary.</u> Mix and pump 12 sxs Class G cement and spot a balanced plug inside casing to isolate the Gallup perforations and top. PUH.
 - 5. Plug #2 (Mancos top, 4514' 4414'): Mix and pump 12 sxs Class G cement and spot a balanced plug inside casing to cover the Mancos top. PUH.
 - 6. Plug #3 (Mesaverde top, 3564' 3464'): Mix and pump 12 sxs Class G cement and spot a balanced plug inside casing to cover the Mesaverde top. PUH.
 - 7. Plug #4 (Chacra top, 2477' 2377'): Mix and pump 12 sxs Class G cement and spot a balanced plug inside casing to cover the Chacra top. PUH.
 - 8. Plug #5 (Pictured Cliffs and Frutiland tops, 1991' 1759'): Mix and pump 22 sxs Class G cement and spot a balanced plug inside casing to cover through the Fruitland tops. TOH.
 - 9. Plug #6 (Kirtland and Ojo Alamo tops, 1438' 1190'): Mix and pump 24 sxs Class G cement and spot a balanced plug inside casing to cover through the Ojo Alamo top. PUH.

- 10. Plug #7 (8-5/8" Surface casing shoe and Surface, 313' Surface): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 49 sxs cement and spot a balanced plug from 313' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing and annulus from the squeeze holes to surface. Shut in well and WOC.
- 11. ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations



.



TD 5700' PBTD 5646'

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE 6251 COLLEGE BLVD.

FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: South Blanco 6 #4

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

3. The following modifications to your plugging program are to be made:

- a) Set plug #3 (2798 2698) ft. to cover the Mesaverde top. BLM picks top of Mesaverde at 2748 ft.
- b) Set plug #4 (2360 2260) ft. to cover the Chacra top. BLM picks top of Chacra at 2310 ft.
- c) Set plug #5 (1988 1740) ft. to cover the PC and Fruitland tops. BLM picks top of Pictured Cliffs at 1938 ft. BLM picks top of Fruitland at 1790 ft.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.