Form 3160-5 (November 1994)

Subsequent Report

Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

NMSF 079161

BUREAU OF LAND MANAGEMENT 5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS	SUNDRY	NOTICES A	AND REPO	RTS (ON WELLS
-------------------------------------	--------	-----------	----------	-------	----------

Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or N

Other

SUBMIT	IN	TRIPLICA	ATE -	Other	instructions	on	reverse	sid	e
--------	----	----------	-------	-------	--------------	----	---------	-----	---

Casing Repair

Change Plans

Convert to Injection

 Type of Well 				
Oil Well 🗶 Gas Well	Other			8. Well Name and No.
2. Name of Operator				Candado #7
DJR Operating, LLC				9. API Well No.
3a. Address		3b. Phone No. (includ	e area code)	30-039-06597
1600 Broadway, Suite 1960	10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., 2	T., R., M., or Survey Description	n)		Blanco PC South
Sec. 10-T26N-R7W				11. County or Parish, State
1550' FNL X 990' FWL	Rio Arriba, NM			
12. CHECK APPROPRIATE BOX	K(ES) TO INDICATE NAT	URE OF NOTICE, RE	PORT, OR OT	HER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production Reclamatio	(Start/Resume) Water Shut-Off Mell Integrity

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days Following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Plug Back

New Construction

Plug and Abandon

We believe this well has sustained a casing failure, and request permission to plug and abandon this well according to the attached procedure.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

Notify NMOCD 24 hrs prior to beginning operations BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

Recomplete

Water Disposal

Temporarily Abandon

* Approval of reclamation plan still reguired						
14. I hereby certify that the foregoing is true and correct						
Name (Printed/Typed)	Title					
Scott Lindsay	Reservoir Engineer					
Signature	Date					
Ast C	June 29, 2018					
THIS SPACE FOR	FEDERAL OR STATE USE					
Approved by way	Title Date 7/12 / 18					
Conditions of approval, it any, are attached Approval of this notice does not warr certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.						

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)





PLUG AND ABANDONMENT PROCEDURE

June 28, 2018

Candado #7

Blanco PC South
1550' FNL and 990' FWL, Section 10, T26N, R7W
Rio Arriba County, New Mexico / API 30-039-06597
Lat: N _____/ Lat: W _____

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class G, mixed at 15.8 ppg with a 1.15 cf/sx yield.

- Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
- Rods: Yes_____, No__X__, Unknown____.
 Tubing: Yes __X_, No____, Unknown_____, Size ____1.25"_, Length __2278'___.
 Packer: Yes____, No__X__, Unknown_____, Type____.
- NOTE: BLM requires a CBL log to be run on all wells where the cement did not circulate to surface or a CBL log was not previously run. This procedure is prepared with the understanding that it may be modified based on the TOC from the CBL.
- 4. Plug #1 (Pictured Cliffs perfs and Fruitland top, 1660' 1560'): Round trip 5.5" mill to 2187' or as deep as possible. RIH and set 5.5" CR at 2187'. Circulate well clean. Pressure test tubing to 1000#. Casing will not pressure test. Mix 33 sxs Class G cement inside casing from 2187' to isolate the Pictured Cliffs interval and Fruitland top. PUH and WOC. TIH and tag cement; top off if necessary. TOH.
- 5. Plug #2 (Kirtland and Ojo Alamo tops, 1707' 1492'): Perforate 3 squeeze holes at 1707'. Attempt to establish rate into squeeze holes if the casing pressure tested. Set 5.5" cement retainer at 1657'. Establish rate into squeeze holes. Mix and pump 105 sxs Class G cement squeeze 70 sxs outside the casing and leave 35 sxs inside casing to cover through the Kirtland and Ojo Alamo tops. TOH and WOC. TIH and tag cement; top off if necessary. TOH and LD tubing.
- 6. Plug #3 (Nacimiento top and 8-5/8" casing shoe, 262' 0'): Perforate 4 squeeze holes at 262'. Establish circulation out bradenhead with water and circulate the BH annulus clean. Mix and pump approximately 100 sxs cement and pump down the 5.5" casing to circulate good cement out bradenhead. Shut in well and WOC.
- ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A
 marker to comply with regulations. Record GPS coordinate for P&A marker on tower report.
 Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM
 stipulations



Pertinent Data Sheet

Well Name: Candado #7

Footage: 1550' FNL and 990' FWL

Location: Section 10, T26N, R7W

API#:

County: Rio Arriba County, NM

Lease:

30-039-06597 NMSF 079161

Field:

Blanco PC South

Elevation: 6097' GR

Cased TD: 2237' KB

OHTD: 2320' KB

Completed: 7/19/1955

Casing Record:

Hole Size	Casing Size	Wt.	Grade	Depth Set	Cement
12-1/4"	8-5/8"	24#	J-55	192'	100 sx (TOC N/A)
7-7/8"	5-1/2"	14#	J-55	2237'	100 sx (TOC N/A)
N/A	Open Hole			2320'	None

Tubing Record: 1-1/4" tubing set at 2278' GL.

Formation Tops: No logs

Nacimiento

Surface

Ojo Alamo

1542' (est.)

Kirtland

1657' (est.)

Fruitland

2004' (est.)

Pictured Cliffs 2229'

Perforation Record: Open hole completion.

Workover History: 12/16/73. Found hole in casing at 1152' Perfed 4 holes at 1162' Set packer at 956'

and squeezed with 120 sx.

Candado #7

Current

Blanco PC South

1550' FNL, 990' FWL, Section 10, T-26-N, R-7-W

Rio Arriba County, NM, API #30-039-06597

Today's Date: 6/28/18

Spud: 8/27/52 Completed: 7/19/55 Elevation: 6097' GI 12.25" hole 8-5/8" 24# Casing set @ 192' Cement with 100 sxs, circulated Nacimiento @ 212' 1.25" Tubing @ 2278' Casing failure @ 1152' (squeezed with 120 sxs) 1973 TOC unknown, did not circulate Ojo Alamo @ 1542' Kirtland @ 1657' Fruitland @ 2004' 7-7/8" hole 5.5",14#, J-55 Casing set to 2237' Cement with 100 sxs Pictured Cliffs @ 2229' Pictured Cliffs Open Hole: 2237' - 2320'

TD 2320'

Candado #7

Proposed P&A

Blanco PC South

1550' FNL, 990' FWL, Section 10, T-26-N, R-7-W Rio Arriba County, NM, API #30-039-06597

Today's Date: 6/28/18 Spud: 8/27/52 Completed: 7/19/55

Elevation: 6097' GI

Nacimiento @ 212'

12.25" hole

8-5/8" 24# Casing set @ 192' Cement with 100 sxs, circulated Plug #3: 262' - 0'

Class G cement, 100 sxs:

Plug #2: 1707' - 1492' Class G cement, 96 sxs: 31 inside and 65 outside

Plug #1: 2187' - 1954' Class G cement, 33 sxs

Perforate @ 262'

Casing failure @ 1152' (squeezed with 120 sxs) 1973

Ojo Alamo @ 1542'

Kirtland @ 1657'

Set CR @ 1657'

Perforate @ 1707'

TOC unknown, did not circulate

Fruitland @ 2004'


7-7/8" hole

Set CR @ 2187'

5.5",14#, J-55 Casing set to 2237' Cement with 100 sxs

Pictured Cliffs Open Hole: 2237' - 2320'

Pictured Cliffs @ 2229'



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: Candado #7

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Set Plug #1 (2187 1935) ft. to cover the PC and Fruitland tops. BLM picks top of Fruitland at 1985 ft.
 - b) Set Plug #2 (1666 1367) ft. inside/outside to cover the Kirtland and Ojo Alamo tops. BLM picks top of Kirtland at 1616 ft. BLM picks top of Ojo Alamo at 1417 ft.
 - c) Set Plug #3 (360 surface) ft. inside/outside to cover the Nacimiento top. BLM picks top of Nacimiento at 310 ft.

Operator will run a CBL to verify cement top. Submit the electronic copy of the log for verification to the following addresses: jwsavage@blm.gov Brandon.Powell@state.nm.us

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.