Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMSF078903 6. If Indian, Allottee or Tribe Name		
SUBMIT IN	TRIPLICATE - Other inst	ructions on J	page 2		7. If Unit or CA/Agree	ement, Name and/or	No.
1. Type of Well ☐ Oil Well 🛛 Gas Well 🔲 Oth	ner				8. Well Name and No. GALLEGOS CANYON UNIT 245E		
2. Name of Operator BP AMERICA PRODUCTION	Contact:	PATTI CAMP pell@bpx.com	BELL		9. API Well No. 30-045-26290-00-S1		
3a. Address3b. Phone No. (include area cod1199 MAIN AVE SUITE 101Ph: 970-712-5997DURANGO, CO 81301Ph: 970-712-5997				10. Field and Pool or Exploratory Area BASIN DAKOTA BASIN FRUITLAND COAL			
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description))			11. County or Parish,	State	
Sec 36 T28N R12W SWNE 1 36.621380 N Lat, 108.059220			SAN JUAN COUNTY, NM				
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICAT	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION			TYPE OF	ACTION	9		
□ Notice of Intent	Acidize	Deep Deep	ben	Product	tion (Start/Resume)	U Water Shut-	Off
	Alter Casing	🗖 Hydr	raulic Fracturing	Reclam	ation	Well Integri	ty
🛛 Subsequent Report	Casing Repair	_	Construction	Recomp		□ Other	
□ Final Abandonment Notice	Change Plans		and Abandon		rarily Abandon		
13. Describe Proposed or Completed Op	Convert to Injection	🗖 Plug		U Water I			
If the proposal is to deepen direction. Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f The subject well was plugged Well Diagram.	rk will be performed or provide l operations. If the operation res pandonment Notices must be file inal inspection.	the Bond No. on sults in a multiple ed only after all r	file with BLM/BIA e completion or reco requirements, includ	. Required su mpletion in a ing reclamatio	bsequent reports must be new interval, a Form 316 n, have been completed a	filed within 30 day 0-4 must be filed or	s nce
				College and Annual V	NMOCD	anerup and Sisk	
					NOV 1 5 2018		
				D	STRICT II		
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #4 For BP AMERICA Committed to AFMSS for pro-	PRODUCTIO	N CO, sent to the	Farmington	1		
Name (Printed/Typed) PATTI CA	MPBELL		Title REGUL	ATORY AN	ALYST		
Signature (Electronic	Submission)		Date 11/12/20	018			
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE		
Approved By ACCEPT	ED		JACK SAV _{Title} PETROLE	'AGE UM ENGIN	EER	Date 11/1	3/2018
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to condu	uitable title to those rights in the		Office Farming	ton			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to m	ake to any department or	agency of the Unite	d
(Instructions on page 2) ** BLM REV	ISED ** BLM REVISED) ** BLM RE	VISED ** BLN	REVISE	D ** BLM REVISE	D **	

.

L

Printed on 10/10/2018



Name: GCU 245E API:30-045-26290, 10/10/2018

Well Plugging Report

Production Company

Cement Summary

B P American

Eunice, NM 88231

P.O. Box 1089

•

BLM / NMOCD - Notified BLM and NMOCD on 9/26/18 at 8:00AM

PLUG #1 - Mix and Pump 60sxs (1.15 yield, 15.8 ppg, 69 cuft) Class G cement from 5,454' - 5,142' TOC.

Plug #2 - (Added Plug) Mix and Pump 58sxs (1.15 yield, 15.8 ppg, 66.7 cuft) Class G cement with 2% Calcium Chloride from 4,581' - 4,280' TOC.

Plug #3 – (Added Plug depth change) Mix and Pump 45sxs (1.15 yield, 15.8 ppg, 51.75 cuft) Class G cement from 3,409' - 3,175' TOC.

Plug #4 - Mix and Pump 35sxs (1.15 yield, 15.8 ppg, 40.25 cuft) Class G cement with 2% Calcium Chloride from 2,536' - 2,354' TOC.

Plug #5 – (NMOC added plug) Mix and Pump 60sxs (1.15 yield, 15.8 ppg, 69 cuft) Class G cement with 2% Calcium Chloride from 1,869' - 1,558' TOC.

Plug #6 - (BLM COA) Mix and Pump 53sxs (1.15 yield, 15.8 ppg, 60.95 cuft) Class G cement from 1,676' - 1,402' TOC.

Plug #7 – (COA depth change) Mixed and Pump 168sxs (1.15 yield, 15.8 ppg, 193.2 cuft) Class G cement from 701' - Surface.

Work Detail

PUX 09/27/2018	Activity
Ρ	JSA. S & S equipment.
Р	CHECK PSI: TBG-#0, CSG-30#, BH-0#. Open well to pit.
Ρ	X-over to rod equipment. LD '6, 8' pony rods, 66 3/4 guided rods. 4 7/8 guided rods. 1 rod pump. X-over to TBG equipment. ND WH, NU BOP. RU rig floor and TBG equipment. LD 58 JTS of 2-3/8 TBG & 1 Mudd anchor.
Ρ	RU 2.5 swivel and drilling equipment. Wait on TBG float. Strap and PU 6, 3-1/8 collars. PUP TIH tag CIBP @ 1900'. Attempt to establish circulation. Pump 150bbls of fresh water. No circulation. Wait on air foam unit for the AM. SIW, SDFD.
09/28/2018	
P	JSA. S & S equipment.
Р	CHECK PSI: TBG-VAC, CSG-VAC, BH-0#. Open well to pit.
Р	RU 2.5 swivel, Air Foam Unit and flow back tank.
Ρ	Begin cleaning out fill and drilling out 7" CIBP. Did not finish drilling out. RD swivel . PUH. SIW, SDFD.
10/01/2018	
Р	Conduct JSA. S & S Equipment.
Ρ	Check Well Pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH with 2-3/8" and tag top CIBP at 1,900' KB. PU Swivel and establish circulation with Air Foam Unit. D/O CIBP.
Р	Hang back Swivel. Tally, PU 2-3/8" TBG and chase to 5,455'.

Printed	on 10	/10	/2018
---------	-------	-----	-------

 Lay down 1. Joint, TOOH with 80 Stands 2-3/8" TBG, and 3 Stands of Drill Collars. P TIH with 173 JNTS 2-3/8" TBG 5,454' K8. P UPumpo dPug #1. Lay down TBG to 5,109', TOOH with 20 Stand for WOC. P Ecorduct JSA. Check Well Pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH with 2-3/8" TBG and tag TOC at 5,202". P Econduct JSA. Check Well Pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH with 2-3/8" TBG and tag TOC at 5,202". P Extra down TBG to 4,572', TOOH with 72 Stands and a Single. P RU A-Plus Wireline, Run CBL from 5,202" - 1760' (bottom of open FC Perforations). Showed good CMT behind 7" CSG. X TIH with 4' Plugging Sub, 145 JNTS 2-3/8" TBG to 4,583'. Pre-mix 2% Calcium Chloride in mix water. RU Pump onto TBG, pump and attempt to establish circulation with 70 BBLS. X Pumped Plug #2. X Lay down TBG to 4,523', TOOH with 20 Stands for WOC. X TIH with 2-3/8" TBG and tag TOC at 4,347'. Lay down TBG to 3,409', RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. P Pumped Plug #3. X Lay down TBG to 3,153', TOOH with 23 Stands for WOC. EOT above FC Perforations. P Secure Location and SDFD. 10/03/2018 P Conduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium Chloride in mix water. P Pumped Plug #4. Lay down TBG to 1,349' and TOOH with 10 Stands (above FC perforations.) for WOC. P TIH with 2-3/8" TBG and tag TOC at 1,86' and TOOH with 2% Calcium Chloride in mix water. P Pumped Plug #5. Lay down TBG to 1,549' and TOOH with 10 Stands (above FC perforations.) for WOC.<!--</th--><th></th><th>Printed on 10/10/2018</th>		Printed on 10/10/2018
 P RU Pump onto TBG. Pump and established circulation out CSG with 90 BBLS, circulate clean with additional 60 BBLS. P Pumped Plug #1. P Lay down TBG to 5,109', TOOH with 20 Stand for WOC. P Secure Location and SDFD. D/02/2018 P Conduct JSA. Check Well Pressures; 2-3/8" TBG on PSI, 7" CSG - 0 PSI, 9-5/8". Surface CSG - 0 PSI. TH with 2-3/8" TBG and tag TOC at 5,202'. P Lay down TBG to 4,572', TOOH with 72 Stands and a Single. P RU A-Plus Wireline, Run CBL from 5,202'- 1760' (bottom of open FC Perforations). Showed good CMT behind 7" CSG. X TIH with 4' Plugging Sub, 14S JNTS 2-3/8" TBG to 4,583'. Pre-mix 2% Calcium Chloride in mix water. RU Pump onto TBG, pump and attempt to establish circulation with 70 BBLS. X Pumped Plug #2. X Lay down TBG to 4,525', TOOH with 20 Stands for WOC. X TIH with 2-3/8" TBG and tag TOC at 4,347'. Lay down TBG to 3,409', Ru Pump onto TBG, and attempt to establish circulation with 60 BBLS. Y Pumped Plug #3. X Lay down TBG to 3,153', TOOH with 23 Stands for WOC. EOT above FC Perforations. P Sccure Location and SDFD. 10/03/2018 P Conduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water. P Pumped Plug #4. Lay down TBG to 1,549' and TOOH with 10 Stands (above FC perforations) for WOC. P TIH with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,869'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium Chloride in mix water. P Pumped Plug #5. Lay down TBG to 1,549' and TOOH with 10 Stands (above FC perforations) for WOC. P TOOH with 26 Stands and a Single wi	Р	
circulate clean with additional 60 BBLS.PPumped Plug #1.PLay down TBG to 5,109, TOOH with 20 Stand for WOC.PSecure Location and SDFD.10/02/2018PConduct ISA. Check Well Pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8"Surface CSG - 0 PSI. TIH with 2-3/8" TBG and tag TOC at 5,202'.PLay down TBG to 4,572, TOOH with 72 Stands and a Single.PRU A-Plus Wireline, Run CBL from 5,202'. 1760' (bottom of open FCPerforations). Showed good CMT behind 7" CSG.XTIH with 4" Plugging Sub, 145 JNTS 2-3/8" TBG to 4,583'. Pre-mix 2% CalciumChloride in mix water. RU Pump onto TBG, pump and attempt to establish circulation with 70 BBLS.XPumped Plug #2.XLay down TBG to 4,258', TOOH with 20 Stands for WOC.XTIH with 4-3/8" TBG and tag TOC at 4,347'. Lay down TBG to 3,409', Ru Pump onto TBG, and attempt to establish circulation with 60 BBLS.XPumped Plug #3.XLay down TBG to 3,153', TOOH with 23 Stands for WOC. EOT above FC Perforations.PSecure Location and SDFD.10/03/2018PPConduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water.PPumped Plug #4. Lay down TBG to 1,549' and TOOH with 10 Stands (above FC perforations) for WOC.PTIH with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,869'. RU Pump onto TBG, altermpt to establish circulation with 60	Р	
PLay down TBG to 5,109', TOOH with 20 Stand for WOC.PSecure Location and SDFD.10/02/2018PConduct JSA. Check Well Pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8"Surface CSG - 0 PSI. TIH with 2-3/8" TBG and tag TOC at 5,202'.PLay down TBG to 4,572', TOOH with 22 Stands and a Single.PRU A-Plus Wireline, Run CEL from 5,202' - 1760' (bottom of open FC Perforations). Showed good CMT behind 7" CSG.XTIH with 4" Plugging Sub, 145 JNTS 2-3/8" TBG to 4,583'. Pre-mix 2% Calcium Chloride in mix water. RU Pump onto TBG, pump and attempt to establish circulation with 70 BBLS.XPumped Plug #2.XLay down TBG to 4,258', TOOH with 20 Stands for WOC.XTIH with 4" Plugging Sub, 145 JNTS 2-3/8" TBG to 4,583'. Pre-mix 2% Calcium Chloride in mix water. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS.XPumped Plug #3.XLay down TBG to 3,153', TOOH with 23 Stands for WOC. EOT above FC Perforations.PSecure Location and SDFD.10/03/2018Conduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water.PPumped Plug #4. Lay down TBG to 1,237' and TOOH with 10 Stands (above FC perforations for WOC.PTIH with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,869'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium Chloride in mix water.PPumped Plug #5. Lay down TBG to 1,249' and	Ρ	
 P Secure Location and SDFD. 10/02/2018 P Conduct JSA. Check Well Pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH with 2-3/8" TBG and tag TOC at 5,202'. P Lay down TBG to 4,572', TOOH with 72 Stands and a Single. P RU A-Plus Wireline, Run CBL from 5,202' - 1760' (bottom of open FC Perforations). Showed good CMT behind 7" CSG. X TIH with 4'Plugging Sub, 145 JNTS 2-3/8" TBG to 4,583'. Pre-mix 2% Calcium Chloride in mix water. RU Pump onto TBG, pump and attempt to establish circulation with 70 BBLS. X Pumped Plug #2. X Lay down TBG to 4,258', TOOH with 20 Stands for WOC. X Hi with 2-3/8" TBG and tag TOC at 4,347'. Lay down TBG to 3,409', Ru Pump onto TBG, and attempt to establish circulation with 60 BBLS. X Pumped Plug #3. X Lay down TBG to 3,153', TOOH with 23 Stands for WOC. EOT above FC Perforations. P Secure Location and SDFD. 10/03/2018 P Conduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water. P Pumped Plug #4. Lay down TBG to 1,343' and TOOH with 10 Stands (above FC perforations) for WOC. P TIH with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,369'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium Chloride in mix water. Y Pumped Plug #5. Lay down TBG to 1,549' and TOOH for WOC. Y Hu with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,369'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium Chloride in mix water. Y Dumped Plug #5. Lay down TBG to 1,549' and TOOH for WOC. X TIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG	Р	
 10/02/2018 P Conduct JSA. Check Well Pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH with 2-3/8" TBG and tag TOC at 5,202'. P Lay down TBG to 4,572', TOOH with 72 Stands and a Single. P RU A-Plus Wireline, Run CBL from 5,202' - 1760' (bottom of open FC Perforations). Showed good CMT behind 7" CSG. X TIH with 4' Plugging Sub, 145 JNTS 2-3/8" TBG to 4,583'. Pre-mix 2% Calcium Chloride in mix water. RU Pump onto TBG, pump and attempt to establish circulation with 70 BBLS. X Pumped Plug #2. X Lay down TBG to 4,258', TOOH with 20 Stands for WOC. X TIH with 2-3/8" TBG and tag TOC at 4,347'. Lay down TBG to 3,409', Ru Pump onto TBG, and attempt to establish circulation with 60 BBLS. X Pumped Plug #3. X Lay down TBG to 3,153', TOOH with 23 Stands for WOC. EOT above FC Perforations. P Secure Location and SDFD. 10/03/2018 P Conduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump not TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water. P umped Plug #4. Lay down TBG to 2,337' and TOOH with 10 Stands (above FC perforations) for WOC. P TIH with 2-3/8" TBG and tag TOC at 1,676'. Surface. P Pumped Plug #5. Lay down TBG to 1,549' and TOOH for WOC. X TIH with 2-3/8" TBG and tag TOC at 1,676'. Surface. P WOOD, BLM requesting to Perf at 1,552'. X RU A-PIus Wireline, Run CBL from 1,676' - Surface. P WOOD, BLM requesting to Perf at 3,180' and TOOH for WOC. X TIH with 2-3/8" TBG and tag TOC at 1,676'. Surface. P WOOD, BLM requesting to Perf at 3,152'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" TBG and tag TOC at 1,676'. Surface. P WOOD,		
 Conduct JSA. Check Well Pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH with 2-3/8" TBG and tag TOC at 5,202'. Lay down TBG to 4,572, TOOH with 72 Stands and a Single. RU A-Plus Wireline, Run CBL from 5,202' - 1760' (bottom of open FC Perforations). Showed good CMT behind 7" CSG. TIH with 4 Plugging Sub, 145 JNTS 2-3/8" TBG to 4,583'. Pre-mix 2% Calcium Chloride in mix water. RU Pump onto TBG, pump and attempt to establish circulation with 70 BBLS. Pumped Plug #2. Lay down TBG to 4,258', TOOH with 20 Stands for WOC. TIH with 2-3/8" TBG and tag TOC at 4,347'. Lay down TBG to 3,409', Ru Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pumped Plug #3. Lay down TBG to 3,153', TOOH with 23 Stands for WOC. EOT above FC Perforations. Secure Location and SDFD. 10/03/2018 Conduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water. P Umped Plug #4. Lay down TBG to 2,337' and TOOH with 10 Stands (above FC perforations) for WOC. P TIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI. P TOOH with 26 Stands and a Single with 4' Plugging Sub. P RUA-Plug #5. Lay down TBG to 1,549' and TOOH for WOC. X RU A-Plus Wireline, Run CBL from 1,576'. Surface. WOO. BLM requesting to Perf at 1,552'. X RU A-Plus Wireline, Run CBL from 1,560' and TCOH 10 Stands for WOC. Secure location and SDFD. P TOOH with 26 Stands and a Single with 4' Plugging Sub. P RU A-Plug Wireline, RU A PUmp onto TBG establish at into holes. Pressured to 1000 PSI and held. X TIH with		Secure Location and SDFD.
Surface CSG - 0 PSI. TIH with 2-3/8" TBG and tag TOC at 5,202'.PLay down TBG to 4,572', TOOH with 22 Stands and a Single.PRU A-Plus Wireline, Run CBL from 5,202' - 1760' (bottom of open FC Perforations). Showed good CMT behind 7" CSG.XTIH with 4' Plugging Sub, 145 JNTS 2-3/8" TBG to 4,583'. Pre-mix 2% Calcium Chloride in mix water. RU Pump onto TBG, pump and attempt to establish circulation with 70 BBLS.XPumped Plug #2.XLay down TBG to 4,258', TOOH with 20 Stands for WOC.XTIH with 2-3/8" TBG and tag TOC at 4,347'. Lay down TBG to 3,409', Ru Pump onto TBG, and attempt to establish circulation with 60 BBLS.XPumped Plug #3.XLay down TBG to 3,153', TOOH with 23 Stands for WOC. EOT above FC Perforations.PSecure Location and SDFD.10/03/2018Conduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water.PPumped Plug #4. Lay down TBG to 1,549' and TOOH with 10 Stands (above FC perforations) for WOC.PTIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI.PPumped Plug #4. Lay down TBG to 1,549' and TOOH for WOC.XTIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI.PPumped Plug #5.PWOO. BLM requesting to Perf at 1,552'.XLoad Suffer Plug #6. RU APUmp onto TBG established circulation.PWOO. BLM requesting		
 P RU A-Plus Wireline, Run CBL from 5,202' - 1760' (bottom of open FC Perforations). Showed good CMT behind 7" CSG. X TIH with 4' Plugging Sub, 145 JNTS 2-3/8" TBG to 4,583'. Pre-mix 2% Calcium Chloride in mix water. RU Pump onto TBG, pump and attempt to establish circulation with 70 BBLS. X Pumped Plug #2. X Lay down TBG to 4,258', TOOH with 20 Stands for WOC. X TIH with 2-3/8" TBG and tag TOC at 4,347'. Lay down TBG to 3,409', Ru Pump onto TBG, and attempt to establish circulation with 60 BBLS. P Pumped Plug #3. X Lay down TBG to 3,153', TOOH with 23 Stands for WOC. EOT above FC Perforations. P Secure Location and SDFD. 10/03/2018 P Conduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water. P Pumped Plug #4. Lay down TBG to 2,337' and TOOH with 10 Stands (above FC perforations) for WOC. P TIH with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,869'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium Chloride in mix water. X Pumped Plug #5. Lay down TBG to 1,549' and TOOH for WOC. X TIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI. P TOOH with 26 Stands and a Single with 4' Plugging Sub. P RU A-Plus Wireline, Run CBL from 1,676' - Surface. P WOO. BLM requesting to Perf at 1,552'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" TBG and tag TOC at 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH -		Surface CSG - 0 PSI. TIH with 2-3/8" TBG and tag TOC at 5,202'.
 Perforations). Showed good CMT behind 7" CSG. X TIH with 4' Plugging Sub, 145 JNTS 2-3/8" TBG to 4,583". Pre-mix 2% Calcium Chloride in mix water. RU Pump onto TBG, pump and attempt to establish circulation with 70 BBLS. X Pumped Plug #2. X Lay down TBG to 4,258", TOOH with 20 Stands for WOC. X TIH with 2-3/8" TBG and tag TOC at 4,347". Lay down TBG to 3,409', Ru Pump onto TBG, and attempt to establish circulation with 60 BBLS. X Pumped Plug #3. X Lay down TBG to 3,153', TOOH with 23 Stands for WOC. EOT above FC Perforations. P Secure Location and SDFD. 10/03/2018 P Conduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water. P Pumped Plug #4. Lay down TBG to 2,337' and TOOH with 10 Stands (above FC perforations) for WOC. P TIH with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,869'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium Chloride in mix water. P Pumped Plug #4. Lay down TBG to 1,549' and TOOH with 10 Stands (above FC perforations) for WOC. P TIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI. P TOOH with 26 Stands and a Single with 4' Plugging Sub. P KU A-Plus Wireline, RIH and Perforate 3 3-1/8" holes at 1,552'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" TBG and tag TOC is 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. La		
 Chloride in mix water. RU Pump onto TBG, pump and attempt to establish circulation with 70 BBLS. X Pumped Plug #2. X Lay down TBG to 4,258", TOOH with 20 Stands for WOC. X TIH with 2-3/8" TBG and tag TOC at 4,347". Lay down TBG to 3,409', Ru Pump onto TBG, and attempt to establish circulation with 60 BBLS. X Pumped Plug #3. X Lay down TBG to 3,153", TOOH with 23 Stands for WOC. EOT above FC Perforations. Perforations. Pectro Location and SDFD. 10/03/2018 P Conduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH and tag TOC at 3,185". Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water. P Pumped Plug #4. Lay down TBG to 2,337' and TOOH with 10 Stands (above FC perforations) for WOC. P TIH with 2-3/8" TBG and tag TOC at 2,383". Lay down TBG to 1,869'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium Chloride in mix water. X Pumped Plug #5. Lay down TBG to 1,549' and TOOH for WOC. X TIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI. P TOOH with 26 Stands and a Single with 4' Plugging Sub. P RU A-Plus Wireline, RIH and Perforate 3 3-1/8" holes at 1,552'. X RU A-Plus Wireline, RIH and Perforate 3 3-1/8" holes at 1,552'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" TBG and tag TOC at 1,376' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. Y Humped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. P Conduct JSA.		Perforations). Showed good CMT behind 7" CSG.
 Lay down TBG to 4,258', TOOH with 20 Stands for WOC. TIH with 2-3/8" TBG and tag TOC at 4,347'. Lay down TBG to 3,409', Ru Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pumped Plug #3. Lay down TBG to 3,153', TOOH with 23 Stands for WOC. EOT above FC Perforations. Secure Location and SDFD. 10/03/2018 Conduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water. P Umped Plug #4. Lay down TBG to 2,337' and TOOH with 10 Stands (above FC perforations) for WOC. TIH with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,869'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water. Y Pumped Plug #5. Lay down TBG to 1,549' and TOOH with 10 Stands (above FC perforations) for WOC. TIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI. P TOOH with 26 Stands and a Single with 4' Plugging Sub. P RU A-Plus Wireline, Run CBL from 1,676' - Surface. W WOO. BLM requesting to Perf at 1,552'. X Ku A-Plus Wireline, RiH and Perforate 3 3-1/8" holes at 1,552'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" TbG and tag TOC at 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TbG and tag TOC at 1,37' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG at 2,38'" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH.<td>Х</td><td>Chloride in mix water. RU Pump onto TBG, pump and attempt to establish</td>	Х	Chloride in mix water. RU Pump onto TBG, pump and attempt to establish
 X TIH with 2-3/8" TBG and tag TOC at 4,347'. Lay down TBG to 3,409', Ru Pumpe onto TBG, and attempt to establish circulation with 60 BBLS. X Pumped Plug #3. X Lay down TBG to 3,153', TOOH with 23 Stands for WOC. EOT above FC Perforations. P Secure Location and SDFD. 10/03/2018 P Conduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water. P Pumped Plug #4. Lay down TBG to 2,337' and TOOH with 10 Stands (above FC perforations) for WOC. P TIH with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,869'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water. P Umped Plug #5. Lay down TBG to 1,549' and TOOH with 10 Stands (above FC perforations) for WOC. Y TIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI. P TOOH with 26 Stands and a Single with 4' Plugging Sub. P RU A-Plus Wireline, Run CBL from 1,676' - Surface. P WOO. BLM requesting to Perf at 1,552'. X RU A-Plus Wireline, RIH and Perforate 3 3-1/8" holes at 1,552'. X RU A-Plus Wireline, RIH and Perforate 3 3-1/8" holes at 1,552'. X RU A-Plus Wireline, RIH and Perforate 3 3-1/8" holes at 1,552'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" to 1,676'. RU Pump onto TBG established Circulation. P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TGG and tag TOC at 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. D/04/2018 P Conduct JSA. Check well pressures;	Х	
 onto TBG, and attempt to establish circulation with 60 BBLS. X Pumped Plug #3. X Lay down TBG to 3,153', TOOH with 23 Stands for WOC. EOT above FC Perforations. P Secure Location and SDFD. 10/03/2018 P Conduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water. P Pumped Plug #4. Lay down TBG to 2,337' and TOOH with 10 Stands (above FC perforations) for WOC. P TIH with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,869'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium Chloride in mix water. X Pumped Plug #5. Lay down TBG to 1,549' and TOOH for WOC. X TIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI. P TOOH with 26 Stands and a Single with 4' Plugging Sub. P RU A-Plus Wireline, Run CBL from 1,676' - Surface. P WOO. BLM requesting to Perf at 1,552'. X RU A-Plus Wireline, RH and Perforate 3 3-1/8" holes at 1,552'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" TBG and tag TOC at 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG arol'. Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). 		
 X Lay down TBG to 3,153', TOOH with 23 Stands for WOC. EOT above FC Perforations. P Secure Location and SDFD. 10/03/2018 P Conduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water. P Pumped Plug #4. Lay down TBG to 2,337' and TOOH with 10 Stands (above FC perforations) for WOC. P TIH with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,869'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium Chloride in mix water. X Pumped Plug #5. Lay down TBG to 1,549' and TOOH for WOC. X TIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI. P TOOH with 26 Stands and a Single with 4' Plugging Sub. P RU A-Plus Wireline, Run CBL from 1,676' - Surface. P WOO. BLM requesting to Perf at 1,552'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" to 1,676'. RU Pump onto TBG established Circulation. P Pumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG at 701'. P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 	Х	onto TBG, and attempt to establish circulation with 60 BBLS.
Perforations.PSecure Location and SDFD.10/03/2018PConduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water.PPumped Plug #4. Lay down TBG to 2,337' and TOOH with 10 Stands (above FC perforations) for WOC.PTIH with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,869'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium Chloride in mix water.XPumped Plug #5.Lay down TBG to 1,549' and TOOH for WOC.XTIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI.PTOOH with 26 Stands and a Single with 4' Plugging Sub.PRU A-Plus Wireline, Run CBL from 1,676' - Surface.PWOO. BLM requesting to Perf at 1,552'.XLoad 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held.XTIH with 2-3/8" to 1,676'. RU Pump onto TBG established Circulation.XPumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD.10/04/2018PPConduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI.XTIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH.XWOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'.PConduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI.XTIH with 2-3/8" TBG and tag TOC at 1,397'		
 10/03/2018 P Conduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water. P Pumped Plug #4. Lay down TBG to 2,337' and TOOH with 10 Stands (above FC perforations) for WOC. P TIH with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,869'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium Chloride in mix water. X Pumped Plug #5. Lay down TBG to 1,549' and TOOH for WOC. X TIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI. P TOOH with 26 Stands and a Single with 4' Plugging Sub. P RU A-Plus Wireline, Run CBL from 1,676' - Surface. P WOO. BLM requesting to Perf at 1,552'. X RU A-Plus Wireline, RIH and Perforate 3 3-1/8" holes at 1,552'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" to 1,676'. RU Pump onto TBG established Circulation. X Pumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'. P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 	Х	
 P Conduct JSA. Check well pressures; 2-3/8" TBG - 0 PSI, 7" CSG - 0 PSI, 9-5/8" Surface CSG - 0 PSI. TIH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water. P Pumped Plug #4. Lay down TBG to 2,337' and TOOH with 10 Stands (above FC perforations) for WOC. P TIH with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,869'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium Chloride in mix water. X Pumped Plug #5. Lay down TBG to 1,549' and TOOH for WOC. X TIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI. P TOOH with 26 Stands and a Single with 4' Plugging Sub. P RU A-Plus Wireline, Run CBL from 1,676' - Surface. P WOO. BLM requesting to Perf at 1,552'. X RU A-Plus Wireline, RIH and Perforate 3 3-1/8" holes at 1,552'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" to 1,676'. RU Pump onto TBG established Circulation. X Pumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'. P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 	Р	Secure Location and SDFD.
 Surface CSG - 0 PSI. TIH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60 BBLS. Pre-mix 2% Calcium Chloride in mix water. P Pumped Plug #4. Lay down TBG to 2,337' and TOOH with 10 Stands (above FC perforations) for WOC. P TIH with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,869'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium Chloride in mix water. X Pumped Plug #5. Lay down TBG to 1,549' and TOOH for WOC. X TIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI. P TOOH with 26 Stands and a Single with 4' Plugging Sub. P RU A-Plus Wireline, Run CBL from 1,676' - Surface. P WOO. BLM requesting to Perf at 1,552'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" to 1,676'. RU Pump onto TBG established Circulation. X Pumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'. P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 	10/03/2018	
perforations) for WOC.PTIH with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,869'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium Chloride in mix water.XPumped Plug #5. Lay down TBG to 1,549' and TOOH for WOC.XTIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI.PTOOH with 26 Stands and a Single with 4' Plugging Sub.PRU A-Plus Wireline, Run CBL from 1,676' - Surface.PWOO. BLM requesting to Perf at 1,552'.XRU A-Plus Wireline, RIH and Perforate 3 3-1/8" holes at 1,552'.XLoad 7" CSG with 4 BBLS, attempt and unable to established Circulation.XPumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD.10/04/2018PPConduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI.XTIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH.XWOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'.PPumped Plug #7. Good cement returns. (LD all tbg and topped off).PRig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A-	Ρ	Surface CSG - 0 PSI. TIH and tag TOC at 3,185'. Lay down TBG to 2,526' and Sub up to 2,536'. RU Pump onto TBG, and attempt to establish circulation with 60
PTIH with 2-3/8" TBG and tag TOC at 2,383'. Lay down TBG to 1,869'. RU Pump onto TBG, attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium Chloride in mix water.XPumped Plug #5. Lay down TBG to 1,549' and TOOH for WOC.XTIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI.PTOOH with 26 Stands and a Single with 4' Plugging Sub.PRU A-Plus Wireline, Run CBL from 1,676' - Surface.PWOO. BLM requesting to Perf at 1,552'.XRU A-Plus Wireline, RIH and Perforate 3 3-1/8" holes at 1,552'.XLoad 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held.XTIH with 2-3/8" to 1,676'. RU Pump onto TBG established Circulation.XPumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD.10/04/2018PPConduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI.XTIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH.XWOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'.PPumped Plug #7. Good cement returns. (LD all tbg and topped off).PRig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A-	Ρ	
 X TIH with 2-3/8" TBG and tag TOC at 1,676'. Load CSG and established good test at 800 - PSI. P TOOH with 26 Stands and a Single with 4' Plugging Sub. P RU A-Plus Wireline, Run CBL from 1,676' - Surface. P WOO. BLM requesting to Perf at 1,552'. X RU A-Plus Wireline, RIH and Perforate 3 3-1/8" holes at 1,552'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" to 1,676'. RU Pump onto TBG established Circulation. X Pumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'. P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 	Ρ	onto TBG, attempt to establish circulation with 60 BBLS. Pre-Mix 2% Calcium
 at 800 - PSI. P TOOH with 26 Stands and a Single with 4' Plugging Sub. P RU A-Plus Wireline, Run CBL from 1,676' - Surface. P WOO. BLM requesting to Perf at 1,552'. X RU A-Plus Wireline, RIH and Perforate 3 3-1/8" holes at 1,552'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" to 1,676'. RU Pump onto TBG established Circulation. X Pumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'. P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 	Х	Pumped Plug #5. Lay down TBG to 1,549' and TOOH for WOC.
 P TOOH with 26 Stands and a Single with 4' Plugging Sub. P RU A-Plus Wireline, Run CBL from 1,676' - Surface. P WOO. BLM requesting to Perf at 1,552'. X RU A-Plus Wireline, RIH and Perforate 3 3-1/8" holes at 1,552'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" to 1,676'. RU Pump onto TBG established Circulation. X Pumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'. P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 	Х	
 P RU A-Plus Wireline, Run CBL from 1,676' - Surface. P WOO. BLM requesting to Perf at 1,552'. X RU A-Plus Wireline, RIH and Perforate 3 3-1/8" holes at 1,552'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" to 1,676'. RU Pump onto TBG established Circulation. X Pumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'. P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 		
 P WOO. BLM requesting to Perf at 1,552'. X RU A-Plus Wireline, RIH and Perforate 3 3-1/8" holes at 1,552'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" to 1,676'. RU Pump onto TBG established Circulation. X Pumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'. P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 		
 X RU A-Plus Wireline, RIH and Perforate 3 3-1/8" holes at 1,552'. X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" to 1,676'. RU Pump onto TBG established Circulation. X Pumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'. P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 		
 X Load 7" CSG with 4 BBLS, attempt and unable to establish rate into holes. Pressured to 1000 PSI and held. X TIH with 2-3/8" to 1,676'. RU Pump onto TBG established Circulation. X Pumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'. P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 		
 Pressured to 1000 PSI and held. X TIH with 2-3/8" to 1,676'. RU Pump onto TBG established Circulation. X Pumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'. P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 		
 X TIH with 2-3/8" to 1,676'. RU Pump onto TBG established Circulation. X Pumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'. P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 	X	
 X Pumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure location and SDFD. 10/04/2018 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'. P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 	х	
10/04/2018PConduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI.XTIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH.XWOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'.PPumped Plug #7. Good cement returns. (LD all tbg and topped off).PRig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A-		Pumped Plug #6. Lay down TBG to 1,360' and TOOH 10 Stands for WOC. Secure
 P Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI. X TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. X WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'. P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 	10/04/2018	
 TIH with 2-3/8" TBG and tag TOC at 1,397' TOC. Lay down TBG to 701', TOOH. WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'. Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 		Conduct JSA. Check well pressures; TBG, CSG, & BH - 0 PSI.
 WOO from BLM, no additional perfs required. TIH with 2-3/8" TBG to 701'. Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 	х	
 P Pumped Plug #7. Good cement returns. (LD all tbg and topped off). P Rig down Work-floor and Nipple Down BOP. Dig out WH to cut off point. Use A- 	х	
	Р	
	Р	

Printed on 10/10/2018

TOC between 7" and 9-5/8" was 4' down. Weld on DHM, Mix and Pump 13sxs cement around DHM. (36 degrees 37' 17" N, 108 degrees 3' 35" W). RD Daylight Pulling Unit and Cement Equipment. Clean and move off Location.

* P - Procedure Planned; U - Unplanned A+ issue; X - COA, Well Conditions

On Site Reps:

Name KC Arnett

Ρ

Association BLM Notes On Location

GCU #245E

Plugged WBD Basin Dakota / Basin Fruitland Coal

1660' FNL, 1680' FEL, Section 36, T-28-N, R-12-W, San Juan County, NM

