	Submit ¹ I Copy To Appropriate District Office <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		Form C-103 Revised July 18, 2013 WELL API NO.
	<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210			30-045-25871 5. Indicate Type of Lease
	<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			$STATE \boxtimes FEE$
	District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No. E-6597-2
do	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Central Bisti Unit
	1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other			8. Well Number #096
	2. Name of Operator DJR Operating, LLC			9. OGRID Number 371838
	3. Address of Operator		10. Pool name or Wildcat	
	1 Road 3263 Aztec, NM 87410-9521			Bisti Lower Gallup
	4. Well Location			
	Unit Letter <u>H</u> - <u>1650'</u> feet from the <u>North</u> line and <u>330'</u> feet from the <u>East</u> line Section <u>16</u> Tourship <u>25N</u> Pages <u>12W</u> NMPM			
	Section 16 Township 25N Range 12W NMPM County San Juan 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11.			
	6221' GL			
	12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
	NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB CASING/CEMENT JOB			
	CLOSED-LOOP SYSTEM		OTHER: RTP	
	 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 			
DJR Operating, LLC request permission to plug and abandon the subject well per the attached proc and proposed wellbore diagram. Notify NMOCD 24 hrs prior to beginning operations				
				NMOCD
2	*Cof! Extend plug # 3! 1885'-714! mv top is 1835'			LEC 1 2 2018
	DISTRICT III			
	4 12 1004			-Anaronyoga
	Spud Date: 4-12-1984	Rig Release Dat	e:	
	I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
	SIGNATURE			
	Type or print name _Amy Archuleta E-mail address: _aarchuleta@djrllc.com PHONE: _505-632-3476 x201 For State Use Only Deputy Oil & Gas Inspector,			
	APPROVED BY: Known Conditions of Approval (if any):		District #	

5

PLUG AND ABANDONMENT PROCEDURE

December 7, 2018

Central Bisti Unit #96 Bisti Lower Gallup

1650' FNL, 330' FEL, Section 16, T25N, R12W, San Juan County, New Mexico API 30-045-25871 / Long _____ / ____

- Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class G, mixed at 15.8 ppg with a 1.15 cf/sx yield.
 - 1. This project will use an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
 - Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
 - 3. Rods:
 Yes____, No____, Unknown___X_.

 Tubing:
 Yes_X_, No____, Unknown___, Size___2-3/8", Length 4649'.

 Packer:
 Yes___, No_X_, Unknown___, Type____.
 - 4. Plug #1 (Gallup perforations and top, 4660' 4560'): R/T 5.5" gauge ring or mill to 4660'. RIH and set 5.5" CR at 4660'. Pressure test tubing to 1000#. Circulate hole clean. <u>Attempt to pressure test casing to 800#. If casing does not test then spot or tag subsequent plugs as necessary.</u> Mix and pump 18 sxs Class G cement and spot a balanced plug inside casing to isolate the Gallup perforations and top. PUH.
 - 5. Plug #2 (Mancos top, 3755' 3655'): Mix and pump 18 sxs Class G cement and spot a balanced plug inside casing to cover the Mancos top. PUH.

1885

- 6. Plug #3 (Mesaverde, Chacra and PC tops, 1492' 714'): Mix and pump 97 sxs Class G cement and spot a balanced plug inside casing to cover through the PC top. PUH.
- 7. Plug #4 (Fruitland and 8-5/8" Surface casing shoe and Surface, 269' Surface): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 32 sxs cement and spot a balanced plug from 269' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing and annulus from the squeeze holes to surface. Shut in well and WOC.
- 8. ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report.

Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations

, ¹



