Form 3160-5 (June 2015)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS not use this form for proposals to drill or to re-enter an

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 201.

5.	Lease Serial No.
	NMNM30015

2 4 4 4 4 4	- f f				
abandoned wel	s form for proposals to drill or to II. Use form 3160-3 (APD) for sucl	proposals.	6. I	f Indian, Allottee or Tr	ibe Name
SUBMIT IN 1	TRIPLICATE - Other instructions of	n page 2	7. I	f Unit or CA/Agreemen	nt, Name and/or No.
Type of Well	er: COAL BED METHANE			ell Name and No. CARRACAS 18B 3	
Name of Operator     SOUTHLAND ROYALTY COM	LAYLOCK RTNERS.COM		PI Well No. 0-039-30606-00-S	31	
3a. Address 400 W 7TH STREET FORT WORTH, TX 76102		No. (include area code) 334-7882		Field and Pool or Expl BASIN FRUITLAND	
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)		11.	County or Parish, State	2
Sec 18 T32N R4W SWSW 75 36.981541 N Lat, 107.301265			F	RIO ARRIBA COUI	NTY, NM
12. CHECK THE AF	PROPRIATE BOX(ES) TO INDIC	ATE NATURE O	F NOTICE, REP	ORT, OR OTHER	RDATA
TYPE OF SUBMISSION	,	TYPE OF	ACTION		
☐ Notice of Intent	_	eepen	☐ Production (S	_	☐ Water Shut-Off
Subsequent Report     ■     Subsequent Report     Subsequent Re		ydraulic Fracturing	☐ Reclamation		☐ Well Integrity
		ew Construction	Recomplete	Ī	☑ Other Operations
☐ Final Abandonment Notice		ug and Abandon	☐ Temporarily	Abandon	0 1
81	Convert to Injection P eration: Clearly state all pertinent details, inc	ug Back	☐ Water Dispos		
Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for final SRC drilling procedure 8/31/11. MIRU, Pull tubing and rods 2. PU Mill and TIH to verify cs 3. Set RBP, at 4400, above ori 4. Roll hole and pressure test 5. Release Pulling Unit 6. MIRU drilling rig 7. RU BOP and test 8. MIRU WL and run GR/CCL 9. Set RBP at 4184 below pro	8-10/5/18: g is clean ginal horizontal section casing  posed window area assembly and set whipstock above	on file with BLM/BIA iple completion or recoult requirements, include	<ul> <li>Required subseque impletion in a new in</li> </ul>	ent reports must be file terval, a Form 3160-4 e been completed and to	d within 30 days must be filed once
14. I hereby certify that the foregoing is	Electronic Submission #440746 veri For SOUTHLAND ROYALTY CO	MPANY LLC, sent to	the Farmington		
	mmitted to AFMSS for processing by a BLAYLOCK	The second secon	1/09/2018 (18JWS ATORY TECH	01/13E)	
21 / 00111112			.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Signature (Electronic S	Submission)	Date 10/22/20	018		
4,	THIS SPACE FOR FEDEI	RAL OR STATE	OFFICE USE		
Approved By ACCEPT	ED	JACK SAV <sub>Title</sub> PETROLE	'AGE UM ENGINEER		Date 11/09/2018
	<ul> <li>d. Approval of this notice does not warrant outable title to those rights in the subject least act operations thereon.</li> </ul>		ton		
	U.S.C. Section 1212, make it a crime for any statements or representations as to any matter		willfully to make to	any department or age	ncy of the United

(Instructions on page 2)
\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*



#### Additional data for EC transaction #440746 that would not fit on the form

#### 32. Additional remarks, continued

12. TOOH for curve BHA and drill sidetrack
13. Drill 6-1/8 from 4173 MD to 7882 MD / 4210 TVD
14. TOOH and run 4-1/2 pre-perforated liner from 4175 MD to 7874 MD (Perfs f/ 4511-7868 MD)

15. RD&R Drilling Rig
16. MIRU Pulling Unit
17. RIH to PBTD w/ open ended tbg cleaning up lateral with air unit
18. RIH and retrieve whipstock and upper RBP at 4184 w/ work string and jars

19. LD work string
20. Run production tbg to EOT at 4160 to produce lateral completion (2 3/8in, 4.7#, J-55)
21. Secure well, rig down and move off location

Attached are the WBD, Directional Survey, Gas Analysis, Daily Reports, and 3160-4.



Carracas 18B-3 Rio Arriba County, NM 32N-4W Section 18

TD - 7,590' MD; 4,185' TVD ST1: TD - 7,882' MD; 4,210' TVD

12 1/4" hole to 240' Csg: 5 jts - 9 5/8" 32.3# H-40 ST&C

Setting Depth: 229'

Cement 125 sx Class G (146 ft<sup>3</sup>) Circ. 7 bbls cmt to surface

8 3/4" hole to 4,611' Csg: 102 jts - 7" 23# J-55 LT&C

Setting Depth: 4,601'

Cement Lead: 635 sx Haliburton Light Tail: 150 sx Class G (1422 ft<sup>3</sup>) Circ. 75 bbls cmt to surface

6 1/4" hole to 7,590' Liner: 68 jts- 4 1/2" 11.6# J-55 LT&C Setting Depth: 7,590'

TOL: 4,556' No cement

Upper Lateral: 6-1/8" Hole to 7,882'

Liner: 87 Jts 4-1/2" 11.5# N-80

Setting Depth: 7,874'

TOL: 4175' No Cmt

> Upper ST Perforations: Pre-Perforated Liner 4511-7868' 40 Jts perf'd (every other)

Lwr Perforations: Pre-Perforated Liner 4602-7545' 23,540 holes @ 8 jspf

CBP @ 4,400'

First Delivered Sidetrack: 10/08/2018 2-3/8" 4.7# J-55 Prod Tbg Mule Shoe, 8' PJ, SN, Tbg EOT @ 4160', SN @ 4151' Sidetrack Window f/ 4165-73' TD - 7,882' MD 4.5" Liner Top 4,556' md

Prepared by: CArnold Date: 10/10/2018

Spud Date: 06/21/2009

TD - 7,590' MD

First Delivered: 09/10/2009

KB = 15 ft

GL = 7,426 ft API# 30-039-30606

## Job Summary for CARRACAS 18 B 3

### Drilling Sidetrack & Workover-08/31/2018

08/31/2018	Move in rig & equipment (for well maintenance, to prepare well for drilling ST). Rig up. Left well to sales. SDFN
09/04/2018	HJSM. Tubing 120 psi, casing 120 psi. Blow down well. N.U. BOP. Pull & tally tubing & BHA. (142 jts 2-3/8" J-55 tubing.) 3 slip stop in jt # 131. Ran tubing & string mill to 4484'.Pull tubing & string mill. Cap string on mill. Ran tubing & string mill. Turn w/ tongs. No drag. Pull Tubing & string mill. No cap string. Ran tubing & RBP. Set RBP @ 4400' KB. Roll hole w/ fresh water. Pressure test plug & casing to 2000#. Held. Pull tubing & setting sleeve laying tubing down on float. Shut blind rams. Secure well. SDFN
09/05/2018	N.D. BOP. Secure well. Tore down. Move out rig & equipment.
09/06/2018	R.U. Blue Jet. Ran GR & CCL. R.D. Blue Jet. Secure well.
09/07/2018	INACTIVE
09/08/2018	INACTIVE
09/09/2018	MI HOUSES F/HB RENTRAL AT CARRACAS FIELD OFFICE & RU. MI PUSHER, COMPANY MAN & CAMMAND CENTER ON LOCATION AND RU.
09/10/2018	MI AZTEC DRILLING #507 & SUPPORT EQUIPMENT. RU T/SIDE TRACK
09/11/2018	COMPLTE NU OF STACK, FLOW LINE, GAS BUSTER. PERFORM BOP TEST, W/BLM WITNESS. PUMU RBP, RIH ON DS.
09/12/2018	COMPLETE TOOH, BO LD RBP SETTING TOOLS. RIG REPAIRS FOR PIPE RAMS & RETEST. PUMU WHIP, RIH & SET. MILL WINDOW, TOOH
09/13/2018	PU MU SDI DIRECTIONAL BHA, RIH FILLING DP. DRLG, SLIDE & ROTATE F/4174' T/4857
	WOB=6K, STK'S=95 GPM=250, TD RPM=50, DH RPM=130-180, TDT=1100-2500, SPP=800
	TOOH FOR MOTOR
09/14/2018	TIH. DRLG F/4857'- T/6276' W/2 CLEAN UP CYCLES BEWTEEN
	WOB=7K, STK'S=95 GPM=250, TD RPM=70, DH RPM=130-180, TDT=2200-3500 SPP=850
	LOSSES 8-10 BPH
09/15/2018	TRIP FOR HWDP
	DRLG F/6276' T/7760' W/8 TO 12 BPH LOSSES
	WOB=5K, STK'S=95 GPM=250, TD RPM=0-65, DH RPM=130-180, TDT=2500-4200, SPP=1000
09/16/2018	DRLG F/7760' T/7882'
	WOB=5K, STK'S=95 GPM=250, TD RPM=0-65, DH RPM=130-180, TDT=2500-4200, SPP=1000
	SHORT TRIP F/7882 /4191. WASH/REAM F/6761' T/6683' CIRCULATE CLEAN. CONT

	SHORT TRIP. CIRC 3 SWEEPS AT 7882' - TOOH FOR LINER
09/17/2018	RIH 4.5" 11.6# N-80 BTC LINER AS FOLLOWS: BULL NOSE SHOE, LTC X BTC XO, 78 JTS 40 OF 78 PERFORATED W/.75" HOLES AT 4 SPF ON 90 DEG PHASING W/BLANK JT BETWEEN ALL PERF JT EXCEPT LAST 2 F/4501' T/4598', THEN 7 EA FULL JTS & 2 EA PJ'S FOLLOWED BY 78 JTS DP & 57 JTS HWDP. LANDED AT 7874.19' (11'KB).
	INSTALL HANGER W/BPV, ND BOP, NU WH. CLEANING PITS, RD, PREP T/MOVE IN AM.
09/21/2018	Move in rig & equipment. Rig up. Well dead. N.U.BOP. Tally & ran 2 3/8" L-80 tubing & muleshoe. Tag 6794.75' KB. Stand back 45 stands. Secure well. SDFWE
09/22/2018	NO ACTIVITY
09/23/2018	NO ACTIVITY
09/24/2018	HJSM. Tubing 0 psi, Casing 5 psi. Ran 1 stand . EOT 4183' KB. R.U. swab. Tag fluid 2900' from surface. Made 20 runs, recover 83 bbls, casing 160 psi. Made 17 more runs (total 37) @ 4 pm well kicked off w/ 405 psi on casing. Shut in @ 5 pm. Recover total 155 bbls. Casing @ 320 psi. Secure well. SDFN
09/25/2018	HJSM. Tubing 520 psi, casing 530 psi. Open tubing to flow back tank. Well flow 1.5 hrs. Recover 17 bbls. Fluid clean. Casing 315 psi. Pump 5 bbls down tubing. Ran 10 stands to 4839'. R.U. swab. Casing 350 psi. Fluid level 3100' from surface. Made 1 run. Well kicked off. Flow 1 hr. Recover 15 bbls. Casing 335 psi. Pump 5 bbls down tubing. Ran 5 stands to 5165'. Casing 360. Made run to 4400' didn't flow, second & third runs tag higher couldn't get down. Cut cup in half. Made 3 runs. Well kicked off. Flow 20 min. Died, casing 340 psi. Bringing up heavy black fluid w/ coal fines. Heavy coal fines. Made 1 run w/ half cup. Went down to 4400'. Made run w/ full cup. Well kicked off. Casing 400 psi. Bringing up coal fines & small chunks of coal. At 5 pm, kill well w/ 5 bbls, Pull & stand back 15 stands. EOT 4180'. Shut in. Recover total 61 bbls, casing 260 psi. Secure well. SDFN
09/26/2018	HJSM. Tubing 500 psi, Casing 510 psi. Kill tubing w/ 5 bbls. Ran 17 stands to 5295'. Well unload on its own. Shut in, wait on Ideal Completion Services. Ideal arrived. Check tubing @ 10:30. Tubing dead. Casing 550 psi. Pull 2 swabs. Well kicked off. Shut in. Ideal rigged up & took over well @ 2 pm. Tubing flowing w/ 40 psi. Casing 360 psi. Well flow 1 hr. Gas rate 200. Recover 12 bbls, casing 230 psi, tubing slightly blowing. Start swabbing. Well wouldn't flow longer than 15 mins when we would kick off. Fluid heavy w/ coal fines & coal. Had rough time getting swab to fall. Casing pressure stayed between 195 & 230 psi while swabbing. Made total 9 runs.(2 from 4400', 1 from 4500', 6 above 4000') Last 7 runs had to work down due to heavy coal fines. Recover total 30 bbls. Pump 5 bbls down tubing. Pull 17 stands. Shut in. Casing 250 psi. Secure well. SDFN
09/27/2018	HJSM. Tubing 490 psi, casing 500 psi. Ran tubing & tag @ 5550 80'. Pull up to 5484'. R.U. swab. Made 3 runs. Well unloaded @ 0900. Casing 535 pai. Flow 10 min, plugged valves w/ coal. Well flowing @ 0930. Turn to separator @ 0938. Tubing 50 psi, casing 490 psi, gas 241 through 2".Well bringing up heavy coal fines & coal. @ 1011, turn to 1" choke. Slugging heavy coal fines, casing 320 psi, tubing 90 psi. @ 1054 tubing 30 psi, casing 210 psi gas 114. Pump 2 bbls down tubing. Try to run 1 stand. Tag 5540'. 10' higher than this morning. Lay down tag jt. EOT 5516.60'. Had to pour new rope socket due to sandline birdcaging. @ 1246 made swab run. Well flowing casing 260 psi, tubing 45 psi. Well flowing bringing up coal. @ 1500 gas 31, tubing 20 psi, casing 185 psi. Made swab run. Fluid level 4150' from surface (little fluid) Blowing mist & coal. @1530 blowing mist, bringing up coal. Casing 160 psi, tubing 20 psi. @ 1600, blowing dry gas, bringing up coal, tubing 20 psi, casing 150 psi, gas 70. @ 1625 made swab run. Couldn't go any deeper than 3950'.Pull little fluid. casing 180 psi. Recover total 21 bbls water. R.D. swab. Tag @ 5555.80' Pull 21 stands out of side track. Secure well. SDFN
09/28/2018	HJSM. Tubing 100 psi, casing 520 psi. Open tubing, blew down quick. R.U. swab. Ran to

	2480'. Tubing plugged. Try to work through. Couldn't. Equalize tubing & casing. Blow down tubing. Didn't loosen plug. Slowly blow down casing to separator while flaring gas. Pull tubing to plug 1350' above seating nipple. (Fluid was 1062' above plug 2412' above seating nipple. Try to swab. Couldn't get swab to fall due to heavy fluid. Had to pull wet) Flush bottom 20 stands w/ 5 bbls. Ran tubing to top perf 4511'. Made swab run. Plugged hose & line w/ coal. Clean out. Made three runs, fluid level 3700' – 3800'. Well kicked off @ 1430. Run through separator & flare gas. Tubing 20 psi, casing 230 psi rate 127. @ 1630, Tubing 26, casing 140, rate 78, recover total 41 bbls. Pump 5 bbls. Pull 5 stands. Secure well. SDFWE.
09/29/2018	NO ACTIVITY
09/30/2018	NO ACTIVITY
10/01/2018	HJSM. Tubing 750 psi, casing 750 psi. Ran 6 stands. Tag @ 4571'. R.U. Airpackage. Start cleaning out w/ air. Returns, heavy coal fines & coal chunks. Clean out to 5712' KB. Dry up well. Shut down air. Pull & lay down 47 jts. Pull above sidetrack. Recover 21 bbls water. Put 10" coal & coal fines in flowback tank. Casing average pressure 95-110 psi. Secure well. SDFN
10/02/2018	HJSM. Tubing 0 (string float installed), casing 470 psi. Ran tubing. Tag @ 7874' PBTD. R.U. airpackage. Blow around until clean. Bringing up coal fines & coal. Dry up well. Pull 115 jts (57.5 stands). Shut in casing. @ 1230 flare gas, tubing 55, casing 150, rate 28. Bringing up coal fines. Let well flow for remainder of day. Tubing average 18 psi, Casing 150 psi, rate average 107. Well bringing up coal fines. Shut in. Secure well.SDFN
	HJSM. Tubing 550 psi, casing 550 psi. Kill tubing. Slowly blow down casing. (flare gas) Start in w/ tubing. Well unloaded @ 6780'. Kill well. Ran rest of tubing. Tag PBTD. Start out w/ tubing. 10 jts out, tubing unloaded. Kill well. Lay down total 127 jts. 128 jts in well. EOT 4180'. N.U. tubing to flow through separator. Tubing bringing up lite coal fines. Flaring gas. Recover 7 bbls. Tubing pressure 45-55 through 1" choke, 62 through ½ 'choke, 83 through ¼ choke. Casing 150-160. Rate from 104 to 74 at end of day. Secure well. SDFN
10/04/2018	HJSM. Tubing 575 psi, casing 575 psi. Kill tubing. Flare casing. Pull tubing. Ran Whipstock Hook, crossover sub, hydraulic jars, crossover & tubing. Tag, latch & pull tubing, crossover, hydraulic jars, crossover, whipstock hook & whipstock. Ran overshot, basket grapple & tubing. Latch RBP. Pull tubing, basket grapple, overshot & RBP, laying down tubing on float. Tally & ran ms/ 8' perf sub, seating nipple & 127 jts 2-3/8" J-55 tubing. (27 jts yellow band, 100 jts new). Land. EOT 4160.12' KB, S.N. 4151.02' KB. Secure well. SDFN
10/05/2018	HJSM. Tubing 590 psi, casing 590 psi. Kill tubing W/ 8 bbls. N.D.BOP. N.U. wellhead. Shut in & secure well. Tore down. Moved out rig & equipment.